

DAM SAFETY INSPECTION FORM

Inspector Scott Simons

Date 3-3-11

Time 11:40

Dam# 3738

Class II

Name of Dam Church of the Redeemer

Owner Church of Redeemer

Crest:

Charles Fenton rep. present.
maintenance

Erosion yes () no ☒ Description:

Visibility good ☒ fair () poor ()

Description of vegetation:

grass

Other:

Upstream slope:

Erosion yes () no ☒ Description:

Visibility good ☒ fair () poor ()

Description of vegetation:

grass, cut weeds

Other:

Downstream slope:

Erosion yes () no ☒ Description:

Visibility good ☒ fair () poor ()

Description of vegetation:

grass, weeds

Other:

Emergency Spillway:

Erosion yes () no ☒ Description:

Obstructions (logs, vegetation, etc.) yes () no ()

good shape

Other:

Principal Spillway & Outlet Channel/Basin (Deterioration, blockage, trash rack, etc.)

Upstream slope slumping on eastern end of spillway, need to evaluate and repair

Additional Comments:

need to evaluate steel gates, appears significant rusting

monitor crack in eastern inside wall for seepage