Document Receipt Information

☒ Hard Copy ☒ CD ☐ Email

Date Received 3-1-18

Permit Number 18693

Project Manager Bobbi Coleman

Name of Contractor CH2M

UST Certification Number _____

Docket Number 243 URP

Scanned _____

Jan 2018 ~~Quarterly~~ Monthly Status update

CH2M
3120 Highwoods Boulevard
Suite 214
Raleigh, NC 27604
O +1 919 875 4311
F +1 919 875 8491
www.ch2m.com

February 27, 2018

Delivered via FedEx Overnight Delivery

Ms. Bobbi Coleman
South Carolina Department of Health and Environmental Control (SCDHEC)
Assessment Section, UST Management Division
Bureau of Land and Waste Management
2600 Bull Street
Columbia, SC 29201

Subject: **Lewis Drive – January 2018 Monthly Status Update**
Plantation Pipe Line Company
Belton, South Carolina
Site ID #18693, "Kinder Morgan Belton Pipeline Release"

Dear Ms. Coleman,

On behalf of Plantation Pipe Line Company (Plantation), CH2M HILL Engineers, Inc. (CH2M) is submitting the attached Monthly Status Update covering activities conducted in January 2018 at the Lewis Drive site. If you have any questions or concerns, please call me at 919-760-1777, Mr. Scott Powell/CH2M at 678-530-4457, or Mr. Jerry Aycock/Plantation at 770-751-4165.

Regards,
CH2M HILL Engineers, Inc.

William M. Waldron, P.E.
Program Manager

Attachments:

- Monthly Status Update including:
  - Figure 1 – Groundwater and Surface Water Elevation Map
  - Figure 2 – Product Thickness Map
  - Table 1 – Field Observations
  - Table 2 – Stream Gauge Construction Information
  - Table 3 – Analytical Results for Surface Water
  - Table 4 – Well Construction Information
  - Table 5 – Groundwater Elevation and Product Thickness Data
  - Table 6 – Analytical Results for Groundwater
  - Surface Water Analytical Laboratory Reports

- Groundwater Analytical Laboratory Reports

c: Jerry Aycock, Plantation (Digital, Jerry_Aycock@kindermorgan.com)
Mary Clair Lyons, Esq., Plantation (Digital, Mary_Lyons@kindermorgan.com)
Richard Morton, Esq., Womble Carlyle Sandridge & Rice, PLLC (Digital, rmorton@wcsr.com)
File

Monthly Status Update
Plantation Pipe Line Company
Lewis Drive Remediation
Site ID #18693 "Kinder Morgan Belton Pipeline Release"
January 2018

Surface Water

- Routinely inspected Brown's Creek and the wetland area south of West Calhoun Road adjacent to Cupboard Creek for hydrocarbon sheen, odor, or distressed vegetation. No new signs of distressed vegetation, hydrocarbon sheen, or odor were noted at Brown's Creek or the wetland area south of West Calhoun Road adjacent to Cupboard Creek. The route of inspection is indicated on Figure 1. A summary of the field observations is provided in Table 1.
- Stream elevations from staff gauges are tabulated in Table 2 and are shown along with groundwater elevations on Figure 1.
- To date, 44 surface water sampling events have been performed and samples during each event were analyzed for benzene, toluene, ethylbenzene, xylenes, and naphthalene (see Table 3).
- During this reporting period, surface water samples were collected on January 9, 2018. Fourteen surface water samples were collected, at locations SW-01, SW-02, SW-04, SW-07, SW-08, SW-09, SW-10, SW-11, SW-12, SW-13, SW-14, FP-01, FP-02, and FP-03 (locations SW-03 in Brown's Creek could not be accessed for health and safety concerns and SW-05 and SW-06 in Cupboard Creek were dry).
    - The following constituent was detected above its surface water standard:
        - 25.0 µg/L benzene at SW-02
        - 12.3 µg/L benzene at SW-12
        - Apart from these locations, no dissolved hydrocarbons were detected above their respective surface water standards in the remaining surface water samples. Analytical lab reports are attached.

Product Recovery

- Gauged depth to product and depth to water in recovery sumps/trenches/wells, piezometers, monitoring wells, and stream gauges on a routine basis. Due to scheduling conflicts in January, the site-wide gauging event was performed on February 2 and 3, 2018. Two locations exhibited measurable product thicknesses of 0.5 foot or greater. The greatest product thickness measured from a recovery feature (recovery sumps, trenches, and wells) was 0.76 feet, at RW-05. The greatest product thickness measured from a non-recovery feature (piezometers, monitoring wells, and stream gauges) was 0.53 feet, at TW-42. All locations showing greater than 0.5 feet of product are away from surface water bodies at the site and have limited influence from the air sparging remediation system. Construction information for recovery features, piezometers, and monitoring wells is presented in Table 4. Groundwater elevation and product thickness data for January 2018 are presented in Table 5. Groundwater elevation and product thicknesses for January 2018 are presented on Figures 1 and 2, respectively.
- Less product was recovered in January 2018 than could be measured accurately by gauging the 1,500-gallon holding tanks. See Table 5 for the specific dates and times certain wells and sumps were used for product recovery.
- Through the end of January 2018, approximately 222,974 gallons (5,309 barrels) of product have been collected and disposed of offsite.

Groundwater

- Operated and recorded data from six continuous water level data loggers (In Situ Rugged Troll 100) in MW-02, MW-12, MW-15, MW-20, MW-25, and MW-40, and two barometric pressure loggers in MW-01 and MW-10 during the month.
- Collected monthly groundwater samples in accordance with the Corrective Action Plan and Addendum. The analytical lab reports are attached and results are summarized in Table 6.
    - During this reporting period, groundwater samples were collected (or attempted) on January 8 and 9, 2018, from 22 monitoring wells. There were seven monitoring wells that were not sampled because of insufficient water in the well or the presence of product. Samples were analyzed for benzene, ethylbenzene, toluene, total xylenes, 1,2-dichloroethane, methyl tert-butyl ether (MTBE), and naphthalene.
    - The following constituents were detected above their respective groundwater standards:

        - Benzene – in samples from seven monitoring wells ranging from 23.8 to 12,400 µg/L
        - Ethylbenzene – in one monitoring well at the concentration of 773 µg/L
        - Toluene – in one monitoring well at the concentration of 22,300 µg/L
        - Xylenes – in a sample from one monitoring well at the concentration of 10,200 µg/L
        - 1,2-dichloroethane – four monitoring wells have a laboratory reporting/quantitation limit greater than the screening level so it cannot be determined if the analyte was absent or present
        - MTBE – in samples from six monitoring wells ranging from 49.4 to 497 µg/L
        - Naphthalene – in samples from one monitoring well at the concentration of 63.7 µg/L and samples from another three monitoring wells have a laboratory reporting/quantitation limit greater than the screening level so it cannot be determined if the analyte was absent or present
    - Apart from these locations, no dissolved hydrocarbons were detected above their respective groundwater standards in the remaining groundwater samples.

Remedial System Operation

- Continued sparging via vertical well curtains in the Brown's Creek Protection Zone and Cupboard Creek Protection Zone, and sparging via horizontal wells in the Hayfield Zone.
- Flows in the vertical sparging wells were maintained at approximately 10 standard cubic feet per minute (scfm) each during this period.
- Flows in the 3 horizontal wells in the Hayfield Zone were incrementally increased to approximately 0.65 scfm per foot of screen during this period.
- Increased flows in the two stream aerators in Brown's Creek to a rate of 15 scfm each.

Regulatory Interaction

- Submitted *Monthly Status Update for December 2017* to South Carolina Department of Health and Environmental Control (SCDHEC) on January 19, 2018.
- Conducted internal stormwater pollution prevention plan (SWPPP) inspection on January 3, 2018.
- The Anderson County Stormwater Department performed a SWPPP inspection on January 25, 2018. No findings were noted.

Future Activities

- In accordance with the *Sparging Operating Limits* letter to SCDHEC dated July 26, 2017:
    - Increase flow in the stream aerators to up to a maximum of 15 scfm each.
    - Increase flow in the vertical sparging wells up to a maximum of 15 scfm each.
    - Increase flow in the horizontal sparging wells up to a maximum of 0.75 scfm per foot of screen.
- Implement the bedrock sparging pilot study.
- Conduct groundwater monitoring and reporting monthly.
- Gauge select recovery sumps, trenches, and wells once weekly located near Brown's Creek and Cupboard Creek for depth to groundwater and free product thickness.
- Evacuate product from select product recovery sumps, trenches, and wells once weekly located near Brown's Creek and Cupboard Creek. Collect liquids in two on-site 1,550-gallon poly tanks for eventual off-site disposal. Starting in February, product recovery by vacuum truck will be replaced with product-skimming canisters and petroleum-absorbent socks. This will allow more accurate tracking of free product recovered by well.
- Gauge monitoring wells and piezometers monthly for depth to groundwater and free product thickness.
- Continue routine visual inspections of Brown's Creek and Cupboard Creek.
- Conduct monthly surface water sampling at 17 established locations along Brown's Creek and Cupboard Creek in February 2018.
- Install additional monitoring wells to expand the monitoring network north of MW-30 and upgradient of MW-38.
- Abandon 1-inch diameter wells (piezometers) because the existing 2-inch monitoring well network is now sufficient for groundwater elevation and product thickness measurements. The piezometers are now redundant and cannot be used for product removal.
- Continue coordination with landowners and legal counsel on an as-needed basis.

Cumulative Product Shipped from the Site

Date	Destination	Total Product (gal)
12/9/2014	PPL Greensboro	4,289
12/9/2014	PPL Greensboro	3,100
12/12/2014	PPL Greensboro	1,189
12/30/2014	Crystal Clean (FCC)	5,057
12/31/2014	Crystal Clean (FCC)	5,333
1/4/2015	Crystal Clean (FCC)	5,000
1/4/2015	Crystal Clean (FCC)	2,872
1/5/2015	Crystal Clean (FCC)	5,013
1/6/2015	Crystal Clean (FCC)	4,800
1/7/2015	Allied Energies	6,532
1/7/2015	Allied Energies	6,425
1/7/2015	Allied Energies	8,200
1/9/2015	Allied Energies	6,482
1/9/2015	Allied Energies	7,825
1/12/2015	Allied Energies	6,540
1/12/2015	Allied Energies	6,467
1/13/2015	Allied Energies	6,732
1/13/2015	Allied Energies	6,595
1/15/2015	Allied Energies	6,500
1/22/2015	Allied Energies	5,791
1/23/2015	Allied Energies	5,450
1/27/2015	Allied Energies	5,791
1/27/2015	Allied Energies	5,557
1/27/2015	Allied Energies	6,043
1/28/2015	Allied Energies	4,411
2/5/2015	Allied Energies	5,513
2/11/2015	Allied Energies	5,732
2/11/2015	Allied Energies	5,606
2/25/2015	Allied Energies	5,583
3/4/2015	Allied Energies	4,000
3/16/2015	Allied Energies	5,200
6/3/2015	Allied Energies	6,500
6/3/2015	Allied Energies	4,214
8/10/2015	Allied Energies	6,000
11/2/2015	Allied Energies	5,800
11/13/2015	Crystal Clean (FCC)	2,900
12/1/2015	Allied Energies	6,690
12/1/2015	Allied Energies	6,700
12/7/2015	Crystal Clean (FCC)	500
9/28/2016	Shamrock	495
10/17/2016	Shamrock	110
10/24/2016	Shamrock	85
10/31/2016	Shamrock	70
11/10/2016	Shamrock	168
1/18/2017	A&D Archdale, NC	3,758
3/3/2017	A&D Archdale, NC	460
3/8/2017	A&D Archdale, NC	500
3/15/2017	A&D Archdale, NC	4,189
4/3/2017	A&D Archdale, NC	458
4/19/2017	A&D Archdale, NC	927
4/19/2017	A&D Archdale, NC	747
5/22/2017	A&D Archdale, NC	50
6/7/2017	A&D Archdale, NC	658
6/29/2017	A&D Archdale, NC	695
8/25/2017	A&D Archdale, NC	566
9/8/2017	A&D Archdale, NC	99
1/8/2018	A&D Archdale, NC	6
	Total (gallons)	**222,974**
	Total (barrels)	**5,309**

Notes:

1. Gasoline and water are field-segregated using two 1,550-gallon poly tanks prior to off-site disposal.



839.04 Corrected Groundwater Elevation as of 2/3/2018 in feet above mean sea level

NM Not measured

Base Map Sources:
*ESRI World Imagery Layer, 2017
*United States Geological Survey (USGS)
National Hydrography Dataset (NHD)

N

0 250 500

Scale in Feet

Figure 1. Groundwater and Surface Water Elevation Map
Lewis Drive Remediation Site
Belton, South Carolina
Site ID #18693 "Kinder Morgan Belton Pipeline Release"



LEGEND

- Release Point
- Monitoring Well
- Bedrock Monitoring Well
- Seep Location
- Recovery Sump
- Piezometer ("R" indicates Replacement)
- Recovery Well (4-inch diameter)
- Vertical Bedrock Sparging Well
- Vertical Saprolite Sparging Well
- Surface Water Sampling Location
- Septic Tank
- Recovery Trench Extraction Point
- Recovery Trench
- Surface Water Flow Direction
- Horizontal Sparging Well Riser
- Horizontal Sparging Well Screen
- Pipeline
- National Hydrography Dataset Stream
- Delineated Wetland
- Beaver Dam
- Detail Area

0.11 Product thickness in feet as of 2/3/2018

NP No product detected

NM Not measured

Base Map Sources:
*ESRI World Imagery Layer, 2017
*United States Geological Survey (USGS) National Hydrography Dataset (NHD)

N

0 175 350

Scale in Feet

Figure 2. Product Thickness Map
Lewis Drive Remediation Site
Belton, South Carolina
Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Table 1. Field Observation Log

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Date	**Inspect Wetlands South of Calhoun Road** (Any odor, sheen or distressed vegetation? Describe.)	**Inspect Brown's Creek Upstream and Downstream of the Culvert Under Lewis Drive** (Any odor, sheen or distressed vegetation? Describe.)
1/5/2018	No odors, sheens, or distressed vegetation observed in wetlands South of Calhoun Road.	No odors, sheens or distressed vegetation observed in wetlands either upstream or downstream of Culvert under Lewis Drive.
1/10/2018	No odors, sheens, or distressed vegetation observed in wetlands South of Calhoun Road.	No odors, sheens or distressed vegetation observed in wetlands either upstream or downstream of Culvert under Lewis Drive.
1/20/2018	No odors, sheens, or distressed vegetation observed in wetlands South of Calhoun Road.	No odors, sheens or distressed vegetation observed in wetlands either upstream or downstream of Culvert under Lewis Drive.
1/26/2018	No odors, sheens, or distressed vegetation observed in wetlands South of Calhoun Road.	No odors, sheens or distressed vegetation observed in wetlands either upstream or downstream of Culvert under Lewis Drive.
2/3/2018	No odors, sheens, or distressed vegetation observed in wetlands South of Calhoun Road.	No odors, sheens or distressed vegetation observed in wetlands either upstream or downstream of Culvert under Lewis Drive.

Notes:

ID = identification

Table 2. Stream Gauge Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Date Installed	Stream Bottom Elevation (ft amsl)	Elevation of Zero Mark (ft amsl)
SW-01	By hand	3/29/2016	812.39	812.82
SW-02	By hand	3/29/2016	808.36	808.65
SW-03	By hand	3/29/2016	815.05	815.09
SW-05	By hand	3/29/2016	838.69	838.75
SW-08	By hand	3/29/2016	802.14	802.04
SW-10	By hand	3/29/2016	776.62	778.09
SW-14	By hand	7/18/2017	837.13	NS

Notes:

amsl = above mean sea level relative to North American Vertical Datum of 1988 (NAVD88). Benchmark is 34.8289659 degrees north, 82.3710354 degrees west (NAD83, 2011), elevation 929.1 ft NAVD88.

ft = feet

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
		Screening Value (µg/L):		**2.2** [a]	**530** [a]	**1,000** [a]	**NA** [b]	**NA** [b]	**NA** [b]	**NA** [b]
SW-RELEASE	SW-RELEASE	1/20/2015	µg/L	**330**	**490**	**2,400**	**2,100**	**940**	**140**	**5.7 J**
	SW01-121114	12/11/2014	µg/L	0.5 U	1 U	1 U	2 U	1 U	1 U	1 U
	SW01-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-033115	3/31/2015	µg/L	5 U[c]	5 U	**17.6**	10 U	5 U	5 U	NA
	SW01-042215	4/22/2015	µg/L	5 U[c]	5 U	**14.9**	10 U	5 U	5 U	NA
	SW01-050715	5/7/2015	µg/L	5 U[c]	5 U	**7.0**	10 U	5 U	5 U	NA
	SW01-051915	5/19/2015	µg/L	5 U[c]	5 U	**8.8**	**10.6**	**6.4**	5 U	NA
	SW01-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW01-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW01-112415	11/24/2015	µg/L	**7.8**	**1.5**	**13.0**	**9.3**	**4.6**	1 U	NA
SW-01	SW01-122215	12/22/2015	µg/L	**4.6**	1 U	**8.8**	**5.5**	**3.1**	1 U	NA
	SW01-012516	1/25/2016	µg/L	**17.6**	**2.3**	**36.0**	**11.3**	**6.3**	1 U	NA
	SW01-021816	2/18/2016	µg/L	**23.4**	**3.0**	**55.6**	**15.0**	**9.1**	1 U	NA
	SW01-031616	3/16/2016	µg/L	**20.1**	**2.4**	**42.3**	**13.3**	**7.6**	1 U	NA
	SW01-042716	4/27/2016	µg/L	**20.8**	1 U	**30.6**	**2.9**	**2.0**	1 U	NA
	SW01-050916	5/9/2016	µg/L	**16.5**	**1.4**	**16.3**	**7.0**	**4.8**	1 U	NA
	SW01-062716	6/27/2016	µg/L	**9**	1 U	**3.3**	2 U	1 U	1 U	NA
	SW01-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW01-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW01-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW01-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW01-112816	11/28/2016	µg/L	**5.0**	1 U	**10.4**	**4.9**	**8.3**	1 U	NA
	SW01-122916	12/29/2016	µg/L	**12.6**	1 U	**22.1**	**11.2**	**13.5**	1 U	NA
	SW01-012017	1/20/2017	µg/L	**1.0**	1 U	**2.3**	2 U	**3.5**	1 U	NA
	SW01-022817	2/28/2017	µg/L	**18.5**	**1.93**	**37.0**	**13.8**	**10.2**	5 U	NA
	SW01-031517	3/15/2017	µg/L	**3.02**	1 U	**5.13**	**2.16**	**1.74**	5 U	NA
	SW01-032117	3/21/2017	µg/L	1 U	1 U	**1.57**	2 U	1 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-01	SW01-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW01-040517	4/5/2017	µg/L	1 U	1 U	**2.25**	2 U	1 U	5 U	NA
	SW01-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW01-061317	6/13/2017	µg/L	1 U	1 U	**1.90**	2 U	1 U	5 U	NA
	SW01-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW01-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW01-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW01-120517	12/5/2017	µg/L	**1.5**	1 U	**1.15**	2 U	**2.14**	5 U	NA
	SW01-121417	12/14/2017	µg/L	**4.52**	1 U	**4.52**	**3.48**	**3.2**	5 U	NA
	SW01-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	**1.15**	5 U	NA
SW-02	SW02-121114	12/11/2014	µg/L	0.5 U	1 U	1 U	2 U	1 U	1 U	1 U
	SW02-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-033115	3/31/2015	µg/L	5 U[c]	5 U	**6.0**	10 U	5 U	5 U	NA
	SW02-042215	4/22/2015	µg/L	5 U[c]	5 U	**13.0**	10 U	5 U	5 U	NA
	SW02-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW02-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-112415	11/24/2015	µg/L	**6**	**1.3**	**10.0**	**7.8**	**4.0**	1 U	NA
	SW02-122215	12/22/2015	µg/L	**4.1**	1 U	**7.6**	**5.1**	**3.1**	1 U	NA
	SW02-012516	1/25/2016	µg/L	**12**	**1.5**	**25.0**	**8.4**	**4.6**	1 U	NA
	SW02-021816	2/18/2016	µg/L	**15.5**	**1.8**	**35.3**	**10.1**	**5.9**	1 U	NA
	SW02-031616	3/16/2016	µg/L	**8**	**1.0**	**17.5**	**5.8**	**3.9**	1 U	NA
	SW02-042716	4/27/2016	µg/L	**5.6**	1 U	**7.1**	2 U	1 U	1 U	NA
	SW02-050916	5/9/2016	µg/L	**7.1**	1 U	**4.5**	**2.2**	**1.6**	1 U	NA
	SW02-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-02	SW02-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-112816	11/28/2016	µg/L	**5.4**	1 U	**1.6**	**2.6**	**4.8**	1 U	NA
	SW02-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	**1.4**	1 U	NA
	SW02-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW02-022817	2/28/2017	µg/L	**10.7**	1 U	**11.0**	**4.14**	**4.23**	5 U	NA
	SW02-031517	3/15/2017	µg/L	**11.4**	1 U	**8.6**	**4.45**	**3.6**	5 U	NA
	SW02-032117	3/21/2017	µg/L	**8.42**	1 U	**2.45**	**2.48**	**2.68**	5 U	NA
	SW02-033017	3/30/2017	µg/L	**2.18**	1 U	1 U	2 U	1 U	5 U	NA
	SW02-040517	4/5/2017	µg/L	**2.87**	1 U	**1.12**	2 U	**1.14**	5 U	NA
	SW02-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW02-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW02-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW02-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW02-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW02-120517	12/5/2017	µg/L	**26.6**	**1.8**	**8.39**	**10.2**	**7.17**	5 U	NA
	SW02-121417	12/14/2017	µg/L	**21.1**	**1.53**	**9.40**	**9.74**	**7.32**	5 U	NA
	SW02-010918	1/9/2018	µg/L	**25.0**	**1.56**	**12.4**	**11**	**8.24**	5 U	NA
SW-03	SW-UPGRADIENT	1/20/2015	µg/L	0.5 U	1 U	**0.23 J**	2 U	1 U	1 U	1 U
	SW03-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW03-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	--	9/24/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW03-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-03	SW03-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	--	8/19/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW03-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW03-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW03-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	--	1/9/2018	µg/L	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS
SW-04	SW-DOWNGRADIENT	1/20/2015	µg/L	**95**	**27**	**310**	**110**	**63**	**94** U	**2.7**
	SW04-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-04	SW04-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW04-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-112415	11/24/2015	µg/L	**1.7**	1 U	**2.7**	**2.9**	**1.6**	1 U	NA
	SW04-122215	12/22/2015	µg/L	**3.3**	1 U	**7.3**	**5.2**	**2.7**	1 U	NA
	SW04-012516	1/25/2016	µg/L	**6.9**	1 U	**14.0**	**4.9**	**2.8**	1 U	NA
	SW04-021816	2/18/2016	µg/L	**10.9**	**1.1**	**25.4**	**7.0**	**4.3**	1 U	NA
	SW04-031616	3/16/2016	µg/L	1 U	1 U	**2.0**	2 U	**1.8**	1 U	NA
	SW04-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-062716	6/27/2016	µg/L	1 U	1 U	**1.1**	2 U	1 U	1 U	NA
	SW04-072816	7/28/2016	µg/L	1 U	1 U	**23.5**	2 U	1 U	1 U	NA
	SW04-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW04-022817	2/28/2017	µg/L	1 U	1 U	**1.13**	2 U	1 U	5 U	NA
	SW04-031517	3/15/2017	µg/L	1 U	1 U	**2.90**	2 U	1 U	5 U	NA
	SW04-032117	3/21/2017	µg/L	1 U	1 U	**3.28**	2 U	1 U	5 U	NA
	SW04-033017	3/30/2017	µg/L	1 U	1 U	**6.15**	2 U	1 U	5 U	NA
	SW04-040517	4/5/2017	µg/L	1 U	1 U	**9.47**	2 U	1 U	5 U	NA
	SW04-050417	5/4/2017	µg/L	1 U	1 U	**13.8**	2 U	1 U	5 U	NA
	SW04-061317	6/13/2017	µg/L	1 U	1 U	**1.37**	2 U	1 U	5 U	NA
	SW04-071817	7/18/2017	µg/L	1 U	1 U	**1.92**	2 U	1 U	5 U	NA
	SW04-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW04-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW04-120517	12/5/2017	µg/L	1 U	1 U	**5.53**	2 U	1 U	5 U	NA
	SW04-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW04-010918	1/9/2018	µg/L	1 U	1 U	**4.09**	2 U	1 U	5 U	NA
SW-05	SW05-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
	SW05-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW05-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW05-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW05-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW05-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW05-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	--	5/19/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/3/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/18/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	7/15/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/13/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/24/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/22/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW05-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW05-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW05-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW05-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
SW-05	SW05-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	--	4/27/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	5/9/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/27/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	7/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/19/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/31/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	2/28/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/15/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/21/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/30/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	4/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	5/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-05	--	7/18/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/2/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/14/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/9/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
SW-06	SW06-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW06-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW06-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW06-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	--	3/31/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW06-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	--	5/7/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	5/19/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/3/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/18/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	7/15/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/13/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/24/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/22/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/24/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW06-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW06-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW06-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	--	3/16/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	4/27/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	5/9/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/27/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	7/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/19/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/31/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-06	--	2/28/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/15/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/21/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	3/30/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	4/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	5/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	6/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	7/18/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/2/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/14/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/9/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
SW-07	SW07-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW07-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	--	8/13/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/24/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW07-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW07-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	--	6/27/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-07	--	7/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	8/19/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/31/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/29/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	2/28/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW07-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	--	8/2/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	SW07-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW07-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
SW-08	SW08-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW08-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-08	SW08-122215	12/22/2015	µg/L	**1.6**	1 U	**3.8**	**2.5**	**1.6**	1 U	NA
	SW08-012516	1/25/2016	µg/L	**2.4**	1 U	**5.6**	**2**	**1.3**	1 U	NA
	SW08-021816	2/18/2016	µg/L	**2.9**	1 U	**7.6**	**2.3**	**1.5**	1 U	NA
	SW08-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW08-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW08-010918	1/9/2018	µg/L	**1.16**	1 U	1 U	2 U	**1.87**	5 U	NA
SW-09	SW09-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-09	SW09-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW09-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-122215	12/22/2015	µg/L	**2.1**	1 U	**4.8**	**3.3**	**2.1**	1 U	NA
	SW09-012516	1/25/2016	µg/L	**3.3**	1 U	**7.1**	**2.4**	**1.5**	1 U	NA
	SW09-021816	2/18/2016	µg/L	**2.2**	1 U	**5.9**	2 U	**1.2**	1 U	NA
	SW09-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW09-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW09-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
SW-10	SW10-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
	SW10-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW10-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
SW-10	SW10-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW10-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-10-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-10-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-10-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-10	SW10-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW10-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
SW-11	SW11-022515	2/25/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-030215	3/2/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-031115	3/11/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-031815	3/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-033115	3/31/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-042215	4/22/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-050715	5/7/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-051915	5/19/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-060315	6/3/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-061815	6/18/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-071515	7/15/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-081315	8/13/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-092415	9/24/2015	µg/L	5 U[c]	5 U	5 U	10 U	5 U	5 U	NA
	SW11-102215	10/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-112415	11/24/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-122215	12/22/2015	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-012516	1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-021816	2/18/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW11-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-11	SW11-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-11-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-11-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW-11-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW11-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
SW-12	SW12-081916	8/19/2016	µg/L	**6,430**	**764**	**15,400**	**3,360**	**1,730**	**128**	NA
	SW12-092916	9/29/2016	µg/L	**7,850**	**1,030**	**19,000**	**3,910**	**1,940**	**143**	NA
	SW12-103116	10/31/2016	µg/L	**165**	**17.7**	**302**	**103**	**58.2**	**4.7**	NA
	SW12-112816	11/28/2016	µg/L	**486**	**59.6**	**976**	**351**	**181**	**14.2**	NA
	SW12-122916	12/29/2016	µg/L	**707**	**97.3**	**1,790**	**408**	**213**	**16.8**	NA
	SW12-012017	1/20/2017	µg/L	**212**	**19.8**	**396**	**104**	**58**	**3.8**	NA
	SW12-022817	2/28/2017	µg/L	**26.1**	**4.04**	**62.3**	**18.0**	**9.73**	5 U	NA
	SW12-031517	3/15/2017	µg/L	**125**	**15.3**	**185**	**67.9**	**35.5**	5 U	NA
	SW12-032117	3/21/2017	µg/L	**134**	**12.1**	**45.0**	**60.8**	**33.6**	5 U	NA
	SW12-033017	3/30/2017	µg/L	**48.5**	**5.69**	**86.3**	**27.7**	**15.8**	5 U	NA
	SW12-040517	4/5/2017	µg/L	**67.1**	**9.24**	**127.0**	**43.6**	**23.7**	5 U	NA
	SW12-050417	5/4/2017	µg/L	**52.8**	**7.96**	**91.7**	**42**	**23.2**	5 U	NA
	SW12-061317	6/13/2017	µg/L	**102**	**16.6**	**166**	**85.1**	**46.2**	5 U	NA
	SW12-071817	7/18/2017	µg/L	**65**	**5.8**	**116**	**43.3**	**24.8**	5 U	NA
	SW12-080217	8/2/2017	µg/L	**125**	**14.7**	**204**	**102**	**67**	5 U	NA
	SW12-090517	9/5/2017	µg/L	**46.7**	**4.72**	**72**	**39**	**26.2**	5 U	NA
	SW12-090517-DUP	9/5/2017	µg/L	**57.4**	**5.5**	**86.5**	**46.2**	**32.1**	5 U	NA
	SW12-120517	12/5/2017	µg/L	**16.6**	**2.91**	**12.6**	**20.1**	**13.3**	5 U	NA
	SW12-121417	12/14/2017	µg/L	**9.19**	**2.66**	**8.26**	**18**	**12.1**	5 U	NA
	SW12-010918	1/9/2018	µg/L	**12.3**	**2.16**	**5.65**	**14.6**	**11.1**	5 U	NA
SW-13	SW13-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW13-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
SW-13	SW13-103116	10/31/2016	µg/L	1 U	1 U	**2.0**	2 U	1 U	1 U	NA
	SW13-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW13-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW13-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	SW13-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-040517	4/5/2017	µg/L	1 U	1 U	**1.21**	2 U	1 U	5 U	NA
	SW13-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW13-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
SW-14	SW14-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW14-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW14-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	SW14-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	--	12/14/2017	--	NS-DW	NS-DW	NS-DW	NS-DW	NS-DW	NS-DW	NS-DW
	SW14-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
FP-01	FP01-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP01-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
FP-01	FP01-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-01-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP01-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
FP-02	FP02-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-081916	8/19/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP02-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP02-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-040517	4/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-02-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA

Table 3. Analytical Results for Surface Water

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

				Analyte						
Location	**Sample ID**	**Date Collected**	**Units**	**Benzene**	**Ethylbenzene**	**Toluene**	**m&p-Xylene**	**o-Xylene**	**Naphthalene**	**MTBE**
FP-02	FP02-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
FP-03	FP03-031616	3/16/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-042716	4/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-050916	5/9/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-062716	6/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-072816	7/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	--	8/19/2016	--	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS
	FP03-092916	9/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-103116	10/31/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-112816	11/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-122916	12/29/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-012017	1/20/2017	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	NA
	FP03-022817	2/28/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP03-031517	3/15/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-032117	3/21/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-033017	3/30/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	--	4/5/2017	--	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS
	FP-03-050417	5/4/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-061317	6/13/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-071817	7/18/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-080217	8/2/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-090517	9/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-120517	12/5/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP-03-121417	12/14/2017	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA
	FP03-010918	1/9/2018	µg/L	1 U	1 U	1 U	2 U	1 U	5 U	NA

Notes:

[a] South Carolina Department of Health and Environmental Control (SC DHEC) R.61-68, Water Classifications and Standards, Human Health for consumption of water and organism, June 22, 2012.

[b] Screening levels for these compounds are not specified in SC DHEC R. 61-68.

[c] The analyte was analyzed for, but was not detected above the laboratory reporting/quantitation limit. However, the laboratory reporting/quantitation limit is above the screening criteria. The actual absence or presence of this analyte between the screening criteria and the laboratory reporting/quantitation limit can not be determined.

Samples analyzed by EPA Methods SW 8260B.

Bold indicates the analyte was detected above the method detection limit.

Gray shading indicates the analyte exceeded its screening value.

J = estimated

U = analyte was not detected above the reported sample quantitation limit

µg/L = microgram(s) per liter

MTBE = methyl tertiary butyl ether

NS-HS = sample not collected due to health and safety concerns

FP = free product

NA = not applicable

NS-IW = sample not collected due to insufficient volume of water in well

ID = identification

NS-DW = sample not collected due to locations being in a different watershed

SW = surface water

Table 4. Well Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Permit #	Date Installed	Date Abandoned	Purpose	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Measured Depth to Bottom (ft BTOC)	Bore Hole Diameter (in)	Well Dia (in)	Well Depth (ft bgs)	Bottom of Well (ft amsl)	Top of Screen or Open Borehole Interval (ft BTOC)	Bottom of Screen or Open Borehole Interval (ft BTOC)	Top of Screen or Open Borehole Interval (ft bgs)	Bottom of Screen or Open Borehole Interval (ft bgs)	Top of Screen or Open Borehole Interval (ft amsl)	Bottom of Screen or Open Borehole Interval (ft amsl)	Length of Screen or Open Borehole Interval (ft)
Monitoring Wells																			
MW-01	CME 550 HSA	MW-10136	6/26/2015	Still in use	Monitoring Well/Gauging	850.25	853.07	15.61	8	2	13.00	837.2	5.82	15.82	3.0	13.0	847.2	837.2	10.00
MW-01B	Schramm Air Rig	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	850.45	852.99	45.26	10	6	38.50	812.0	21.03	41.03	18.5	38.5	832.0	812.0	20.00
MW-02	CME 750 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	841.24	841.04	19.78	8	2	20.00	821.2	4.80	19.80	5.0	20.0	836.2	821.2	15.00
MW-02B	Schramm Air Rig/rehabbed (10/5/2017) with a Mobile Drill B57	MW-10136	6/24/2015	Still in use	Monitoring Well/Gauging	841.18	841.19	81.55	10	2	81.70	759.5	70.00	81.70	70.0	81.7	771.2	759.5	13.00
MW-03	CME 550 HSA	MW-10136	6/23/2015	Still in use	Monitoring Well/Gauging	838.38	838.36	22.19	8	2	20.00	818.4	4.98	19.98	5.0	20.0	833.4	818.4	15.00
MW-04	CME 550 HSA	MW-10136	6/23/2015	Still in use	Monitoring Well/Gauging	844.51	844.42	20.65	8	2	20.00	824.5	4.91	19.91	5.0	20.0	839.5	824.5	15.00
MW-05	CME 550 HSA	MW-10136	6/24/2015	Still in use	Monitoring Well/Gauging	851.15	851.11	19.89	8	2	20.00	831.1	4.96	19.96	5.0	20.0	846.1	831.1	15.00
MW-06	CME 550 HSA	MW-10136	6/24/2015	Still in use	Monitoring Well/Gauging	852.98	852.92	19.20	8	2	19.60	833.4	4.54	19.54	5.0	19.6	848.0	833.4	15.00
MW-06B	Mobile Drill B57	MW-11117	10/17/2017	Still in use	Monitoring Well/Gauging	852.42	852.57	85.65	13.75	4	85.20	767.2	65.50	85.50	65.5	85.5	786.9	766.9	20.00
MW-07	CME 550 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	853.02	853.02	13.60	8	2	13.50	839.5	3.50	13.50	3.5	13.5	849.5	839.5	10.00
MW-08	CME 550 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	844.75	844.72	19.80	8	2	19.70	825.1	4.67	19.67	4.7	19.7	840.1	825.1	15.00
MW-09	CME 550 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	843.72	843.63	20.21	8	2	19.50	824.2	4.41	19.41	4.5	19.5	839.2	824.2	15.00
MW-09B	Mobile Drill B57	MW-11117	10/17/2017	Still in use	Monitoring Well/Gauging	843.71	843.92	151.00	13.75	4	151.00	692.7	132.20	151.00	132.2	151.0	711.5	692.7	20.00
MW-10	CME 550 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	842.33	845.41	23.54	8	2	20.00	822.3	8.08	23.08	5.0	20.0	837.3	822.3	15.00
MW-11	CME 550 HSA	MW-10136	7/1/2015	Still in use	Monitoring Well/Gauging	852.36	855.63	32.50	8	2	25.20	827.2	13.27	28.27	14.2	25.0	838.2	827.4	15.00
MW-12	CME 550 HSA	MW-10136	6/25/2015	Still in use	Monitoring Well/Gauging	832.20	834.53	21.69	8	2	19.30	812.9	6.63	21.63	4.3	19.3	827.9	812.9	15.00
MW-12B	Geoprobe 3230 DT HSA	MW-10460	12/22/2015	Still in use	Monitoring Well/Gauging	832.26	834.98	45.81	10	6	43.00	789.3	35.72	45.72	33.0	43.0	799.3	789.3	10.00
MW-13	CME 550 HSA	MW-10136	6/26/2015	Still in use	Monitoring Well/Gauging	845.93	848.84	22.18	8	2	19.00	826.9	6.92	21.92	4.0	19.0	841.9	826.9	15.00
MW-13B	Geoprobe 3230 DT HSA	MW-10461	12/21/2015	Still in use	Monitoring Well/Gauging	847.19	849.82	55.36	10	6	58.00	789.2	50.64	60.64	48.0	58.0	799.2	789.2	10.00
MW-14	CME 550 HSA	MW-10136	6/26/2015	Still in use	Monitoring Well/Gauging	836.47	838.70	22.20	8	2	19.30	817.2	6.53	21.53	4.3	19.3	832.2	817.2	15.00
MW-14B	Mobile ST Schramm	MW-10578	5/3/2016	Still in use	Monitoring Well/Gauging	837.12	840.20	76.97	10	6	76.90	760.2	66.07	76.07	66.0	76.0	771.1	761.1	10.00
MW-15	CME 550 HSA	MW-10136	6/29/2015	Still in use	Monitoring Well/Gauging	828.68	831.03	21.22	8	2	19.00	809.7	6.35	21.35	4.0	19.0	824.7	809.7	15.00
MW-15B	CME 550 HSA	MW-10136	7/28/2015	Still in use	Monitoring Well/Gauging	828.66	831.29	74.41	10	6	77.85	750.8	70.48	80.48	67.9	77.9	760.8	750.8	10.00
MW-16	CME 750 HSA	MW-10136	6/26/2015	Still in use	Monitoring Well/Gauging	847.63	847.67	20.37	8	2	20.00	827.6	5.03	20.03	5.0	20.0	842.6	827.6	15.00
MW-17	CME 750 HSA	MW-10136	6/29/2015	Still in use	Monitoring Well/Gauging	855.32	855.35	15.30	8	2	11.00	844.3	6.03	11.03	6.0	11.0	849.3	844.3	5.00
MW-17B	Geoprobe 3230 DT HSA	MW-10462	1/7/2016	Still in use	Monitoring Well/Gauging	855.37	855.37	27.50	10	6	27.00	828.4	17.00	27.00	17.0	27.0	838.4	828.4	10.00
MW-18	CME 550 HSA	MW-10136	6/29/2015	Still in use	Monitoring Well/Gauging	846.82	846.89	19.75	8	2	20.00	826.8	5.06	20.06	5.0	20.0	841.8	826.8	15.00
MW-19	CME 750 HSA	MW-10136	6/29/2015	Still in use	Monitoring Well/Gauging	851.23	853.94	12.13	8	2	9.50	841.7	7.20	12.20	4.5	9.5	846.7	841.7	5.00
MW-20	CME 750 HSA	MW-10136	6/30/2015	Still in use	Monitoring Well/Gauging	853.07	852.89	19.45	8	2	19.00	834.1	3.81	18.81	4.0	19.0	849.1	834.1	15.00
MW-21	CME 750 HSA	MW-10136	6/30/2015	Still in use	Monitoring Well/Gauging	855.68	855.77	20.70	8	2	20.00	835.7	5.09	20.09	5.0	20.0	850.7	835.7	15.00
MW-22	CME 750 HSA	MW-10136	7/1/2015	Still in use	Monitoring Well/Gauging	854.62	854.60	10.30	8	2	11.00	843.6	5.98	10.98	6.0	11.0	848.6	843.6	5.00
MW-23	CME 750 HSA	MW-10136	7/1/2015	Still in use	Monitoring Well/Gauging	846.66	849.57	23.50	8	2	20.00	826.7	7.91	22.91	5.0	20.0	841.7	826.7	15.00
MW-23B	CME 550 HSA	MW-10136	7/22/2015	Still in use	Monitoring Well/Gauging	846.81	849.69	53.48	10	6	50.50	796.3	30.88	53.38	28.0	50.5	818.8	796.3	22.50
MW-24	CME 550 HSA	MW-10136	7/15/2015	Still in use	Monitoring Well/Gauging	815.72	817.92	15.30	8	2	13.00	802.7	10.20	15.20	8.0	13.0	807.7	802.7	5.00
MW-24B	CME 550 HSA	MW-10136	7/20/2015	Still in use	Monitoring Well/Gauging	815.83	818.72	45.10	10	6	39.50	776.3	22.39	42.39	19.5	39.5	796.3	776.3	20.00
MW-25	Geoprobe 3230 DT HSA	MW-10463	1/5/2016	Still in use	Monitoring Well/Gauging	823.46	826.18	18.07	8	2	15.00	808.5	8.04	18.04	5.0	15.0	818.5	808.5	10.00
MW-25B	Geoprobe 3230 DT HSA	MW-10464	1/5/2016	Still in use	Monitoring Well/Gauging	822.59	823.81	59.00	10	6	58.00	764.6	49.22	59.22	48.0	58.0	774.6	764.6	10.00
MW-26	Geoprobe 3230 DT HSA	MW-10465	1/4/2016	Still in use	Monitoring Well/Gauging	844.76	847.56	17.15	8	2	15.25	829.5	7.27	17.27	5.0	15.0	839.8	829.8	10.00
MW-26B	Geoprobe 3230 DT HSA	MW-10466	1/4/2016	Still in use	Monitoring Well/Gauging	844.81	847.81	43.84	10	6	38.00	806.8	29.00	41.00	26.0	38.0	818.8	806.8	12.00
MW-27	Geoprobe 3230 DT HSA	MW-10467	1/5/2016	Still in use	Monitoring Well/Gauging	854.22	854.11	29.51	8	2	30.25	824.0	15.11	30.11	15.0	30.0	839.2	824.2	15.00
MW-27B	CME 550 HSA / Schramm	MW-10578	4/26/2016	Still in use	Monitoring Well/Gauging	854.27	857.14	41.45	10	6	46.00	808.3	31.45	41.45	36.0	46.0	818.3	808.3	10.00
MW-28	Geoprobe 3230 DT HSA	MW-10468	1/5/2016	Still in use	Monitoring Well/Gauging	841.49	844.31	25.93	8	2	25.25	816.2	13.50	23.50	15.0	25.0	826.5	816.5	10.00
MW-29	Geoprobe 3230 DT HSA	MW-10469	1/4/2016	Still in use	Monitoring Well/Gauging	852.07	852.20	15.10	8	2	15.25	836.8	5.00	15.00	5.0	15.0	847.1	837.1	10.00
MW-30	Geoprobe 3230 DT HSA	MW-10470	1/6/2016	Still in use	Monitoring Well/Gauging	841.21	841.28	14.69	8	2	15.25	826.0	5.00	15.00	5.0	15.0	836.2	826.2	10.00
MW-31	CME 550 HSA	MW-10578	4/19/2016	Still in use	Monitoring Well/Gauging	842.26	845.04	28.20	8	2	25.00	817.3	13.20	28.20	10.0	25.0	832.3	817.3	15.00
MW-31B	CME 550 HSA / Schramm	MW-10578	4/22/2016	Still in use	Monitoring Well/Gauging	842.01	844.94	79.25	10	6	76.00	766.0	68.25	79.25	65.0	76.0	777.0	766.0	11.00

Table 4. Well Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Permit #	Date Installed	Date Abandoned	Purpose	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Measured Depth to Bottom (ft BTOC)	Bore Hole Diameter (in)	Well Dia (in)	Well Depth (ft bgs)	Bottom of Well (ft amsl)	Top of Screen or Open Borehole Interval (ft BTOC)	Bottom of Screen or Open Borehole Interval (ft BTOC)	Top of Screen or Open Borehole Interval (ft bgs)	Bottom of Screen or Open Borehole Interval (ft bgs)	Top of Screen or Open Borehole Interval (ft amsl)	Bottom of Screen or Open Borehole Interval (ft amsl)	Length of Screen or Open Borehole Interval (ft)
MW-32	CME 550 HSA	MW-10578	4/19/2016	Still in use	Monitoring Well/Gauging	839.81	842.93	29.09	8	2	26.00	813.8	13.09	28.09	10.0	25.0	829.8	814.8	15.00
MW-33	CME 550 HSA	MW-10578	4/15/2016	Still in use	Monitoring Well/Gauging	846.20	849.20	28.30	8	2	27.00	819.2	11.30	26.30	10.0	25.0	836.2	821.2	15.00
MW-33T	CME 550 HSA/Air Rotary	MW-10578	4/14/2016	Still in use	Monitoring Well/Gauging	846.15	849.11	100.35	8	2	96.50	749.7	87.85	97.85	84.0	94.0	762.2	752.2	10.00
MW-34	Hand Auger	MW-10994	3/16/2017	Still in use	Monitoring Well/Gauging	813.99	816.35	7.86	4	2	5.00	809.0	5.36	7.86	2.5	5.0	811.5	809.0	2.50
MW-35	CME 550 HSA	MW-10578	4/20/2016	Still in use	Monitoring Well/Gauging	826.22	829.40	28.42	8	2	26.00	800.2	12.42	27.42	10.0	25.0	816.2	801.2	15.00
MW-36	CME 550 HSA	MW-10578	4/22/2016	Still in use	Monitoring Well/Gauging	858.66	858.47	23.65	8	2	24.50	834.2	8.65	23.65	9.5	24.5	849.2	834.2	15.00
MW-36B	CME 550 HSA / Schramm	MW-10578	4/28/2016	Still in use	Monitoring Well/Gauging	858.49	858.15	47.54	10	6	54.90	803.6	36.64	46.64	44.0	54.0	814.5	804.5	10.00
MW-37	Geoprobe 8040 HSA	MW-10759	8/9/2016	Still in use	Monitoring Well/Gauging	810.93	813.92	18.11	6.25	2	16.00	794.9	7.11	17.11	5.0	15.0	805.9	795.9	10.00
MW-38	Geoprobe 8040 HSA	MW-10759	8/9/2016	Still in use	Monitoring Well/Gauging	810.49	813.28	11.61	6.25	2	9.10	801.4	6.41	11.41	3.9	8.9	806.6	801.6	5.00
MW-39	Geoprobe 8040 HSA	MW-10759	11/29/2016	Still in use	Monitoring Well/Gauging	816.92	819.90	13.01	6.25	2	11.00	805.9	7.01	12.01	5.0	10.0	811.9	806.9	5.00
MW-40	Geoprobe 8040 HSA	MW-10759	11/30/2016	Still in use	Monitoring Well/Gauging	814.75	817.79	13.18	6.25	2	11.00	803.8	7.18	12.18	5.0	10.0	809.8	804.8	5.00
MW-41	Geoprobe 8040 HSA	MW-10759	11/28/2016	Still in use	Monitoring Well/Gauging	816.67	819.68	13.20	6.25	2	11.00	805.7	7.20	12.20	5.0	10.0	811.7	806.7	5.00
MW-42	Geoprobe 8040 HSA	MW-10759	11/28/2016	Still in use	Monitoring Well/Gauging	817.31	820.33	13.40	6.25	2	11.00	806.3	7.40	12.40	5.0	10.0	812.3	807.3	5.00
MW-43	Mobile Drill B57	MW-10964	10/20/2017	Still in use	Monitoring Well/Gauging	815.92	818.12	10.30	8.5	2	7.50	808.42	5.30	10.30	2.5	7.5	813.42	808.42	5.00
MW-43B	Mobile Drill B57	MW-10964	10/20/2017	Still in use	Monitoring Well/Gauging	816.08	818.80	54.40	13.75	4	51.00	765.08	34.40	54.40	31.0	51.0	785.08	765.08	20.00
MW-44	Hollow Stem Auger	MW-10964	1/23/2017	Still in use	Monitoring Well/Gauging	853.82	853.67	9.82	6.25	2	10.00	843.8	4.82	9.82	5.0	10.0	848.8	843.8	5.00
MW-44B	Hollow Stem Auger/Wire Line/Air Rotary	MW-10964	1/23/2017	Still in use	Monitoring Well/Gauging	853.66	853.38	34.50	10.25	4	37.10	816.6	13.50	34.50	16.1	37.1	837.6	816.6	21.00
MW-45	Hollow Stem Auger	MW-10964	1/26/2017	Still in use	Monitoring Well/Gauging	852.39	852.47	14.42	6.25	2	14.00	838.4	4.42	14.42	4.0	14.0	848.4	838.4	10.00
MW-45B	Hollow Stem Auger/Wire Line/Air Rotary	MW-10964	1/25/2017	Still in use	Monitoring Well/Gauging	852.69	852.85	40.30	10.25	4	40.30	812.4	19.00	40.30	19.0	40.3	833.7	812.4	21.30
MW-46	Geoprobe 8040 DT	MW-11117	9/13/2017	Still in use	Monitoring Well/Gauging	842.43	845.47	17.05	8.5	2	14.00	828.4	12.05	17.05	9.0	14.0	833.4	828.4	5.00
MW-47	Geoprobe 8040 DT	MW-11117	9/14/2017	Still in use	Monitoring Well/Gauging	839.89	842.98	22.79	8.5	2	20.00	819.9	12.79	22.79	10.0	20.0	829.9	819.9	10.00
MW-48B	Mobile Drill B57	MW-11117	10/18/2017	Still in use	Monitoring Well/Gauging	829.53	832.34	94.50	13.75	4	91.00	738.5	74.50	94.50	71.0	91.0	758.5	738.5	20.00
MW-49	Geoprobe 8040 DT	MW-11117	9/14/2017	Still in use	Monitoring Well/Gauging	843.65	846.78	23.30	8.5	2	21.00	822.7	8.30	23.30	6.0	21.0	837.7	822.7	15.00
MW-50B	Mobile Drill B57	MW-11247	10/17/2017	Still in use	Monitoring Well/Gauging	847.11	850.34	109.60	13.75	4	106.00	741.1	89.60	109.60	96.0	106.0	751.1	741.1	20.00
Recovery Wells																			
RW-01	HSA	MW-09978	1/28/2015	Still in use	Gauging/LNAPL Recovery	849.49	851.92	20.80	6.25	4	17	832.5	4.44	19.44	2.0	17.0	847.5	832.5	15.00
RW-02	HSA	MW-09978	1/29/2015	Still in use	Gauging/LNAPL Recovery	850.22	852.69	25.72	6.25	4	23	827.2	15.47	25.47	13.0	23.0	837.2	827.2	10.00
RW-03	HSA	MW-09978	1/29/2015	Still in use	Gauging/LNAPL Recovery	850.03	852.34	33.39	6.25	4	31.2	818.8	18.51	33.51	16.2	31.2	833.8	818.8	15.00
RW-04	HSA	MW-09978	1/29/2015	Still in use	Gauging/LNAPL Recovery	852.15	853.93	35.04	6.25	4	33	819.2	14.78	34.78	13.0	33.0	839.2	819.2	20.00
RW-05	HSA	MW-09978	1/30/2015	Still in use	Gauging/LNAPL Recovery	850.99	853.53	38.25	6.25	4	34.5	816.5	22.04	37.04	19.5	34.5	831.5	816.5	15.00
RW-06	HSA	MW-09978	1/30/2015	Still in use	Gauging/LNAPL Recovery	844.21	846.21	38.50	6.25	4	38.5	805.7	20.49	40.49	18.5	38.5	825.7	805.7	20.00
RW-07	HSA	MW-09978	2/2/2015	Still in use	Gauging/LNAPL Recovery	841.01	843.19	38.00	6.25	4	38	803.0	15.18	40.18	13.0	38.0	828.0	803.0	25.00
RW-08	HSA	MW-09978	2/2/2015	Still in use	Gauging/LNAPL Recovery	833.46	835.48	33.50	6.25	4	33.5	800.0	10.52	35.52	8.5	33.5	825.0	800.0	25.00
RW-09	HSA	MW-09978	2/3/2015	Still in use	Gauging/LNAPL Recovery	831.13	835.12	42.13	6.25	4	41.5	789.6	15.49	45.49	11.5	41.5	819.6	789.6	30.00
RW-10	HSA	MW-10006	2/4/2015	Still in use	Gauging/LNAPL Recovery	846.76	848.53	66.51	6.25	4	68.5	778.3	5.27	70.27	3.5	68.5	843.3	778.3	65.00
RW-11	HSA	MW-10006	2/4/2015	Still in use	Gauging/LNAPL Recovery	851.03	852.97	21.40	6.25	4	19.5	831.5	6.44	21.44	4.5	19.5	846.5	831.5	15.00
RW-12	HSA	MW-10006	2/5/2015	Still in use	Gauging/LNAPL Recovery	851.64	854.49	16.90	6.25	4	14	837.6	6.90	16.90	4.0	14.0	847.6	837.6	10.00
RW-13	HSA	MW-10006	2/5/2015	Still in use	Gauging/LNAPL Recovery	847.57	847.97	45.53	6.25	4	50	797.6	0.53	45.53	5.0	50.0	842.6	797.6	45.00
RW-14	HSA	MW-10006	2/6/2015	Still in use	Gauging/LNAPL Recovery	826.25	827.54	55.00	6.25	4	55	771.2	5.00	55.00	5.0	55.0	821.2	771.2	50.00
RW-15	HSA	MW-10006	2/10/2015	Still in use	Gauging/LNAPL Recovery	849.48	851.64	36.50	6.25	4	36.5	813.0	1.50	36.50	1.5	36.5	848.0	813.0	35.00
Recovery Sumps																			
RS-01	Trackhoe	MW-09978	12/29/2014	Still in use	Gauging/LNAPL Recovery	847.95	849.13	23.60	NA	4	22.42	825.5	3.18	23.60	2.0	22.4	845.9	825.5	20.42
RS-02	Trackhoe	MW-09978	12/29/2014	Still in use	Gauging/LNAPL Recovery	848.54	849.52	20.00	NA	4	19.02	829.5	2.98	20.00	2.0	19.0	846.5	829.5	17.02
RS-04	Trackhoe	MW-09978	12/30/2014	Still in use	Gauging/LNAPL Recovery	850.36	851.47	10.75	NA	4	9.64	840.7	3.11	10.75	2.0	9.6	848.4	840.7	7.64
RS-05	Trackhoe	MW-09978	12/31/2014	Still in use	Gauging/LNAPL Recovery	847.14	848.31	25.20	NA	4	24.03	823.1	3.17	25.20	2.0	24.0	845.1	823.1	22.03
RS-06	Trackhoe	MW-09978	12/31/2014	Still in use	Gauging/LNAPL Recovery	848.25	849.47	25.18	NA	4	23.96	824.3	3.22	25.18	2.0	24.0	846.2	824.3	21.96
RS-07	Trackhoe	MW-09978	12/31/2014	Still in use	Gauging/LNAPL Recovery	854.06	855.08	16.65	NA	4	15.63	838.4	3.02	16.65	2.0	15.6	852.1	838.4	13.63

Table 4. Well Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Permit #	Date Installed	Date Abandoned	Purpose	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Measured Depth to Bottom (ft BTOC)	Bore Hole Diameter (in)	Well Dia (in)	Well Depth (ft bgs)	Bottom of Well (ft amsl)	Top of Screen or Open Borehole Interval (ft BTOC)	Bottom of Screen or Open Borehole Interval (ft BTOC)	Top of Screen or Open Borehole Interval (ft bgs)	Bottom of Screen or Open Borehole Interval (ft bgs)	Top of Screen or Open Borehole Interval (ft amsl)	Bottom of Screen or Open Borehole Interval (ft amsl)	Length of Screen or Open Borehole Interval (ft)
RS-08	Trackhoe	MW-09978	12/31/2014	Still in use	Gauging/LNAPL Recovery	852.59	854.00	20.22	NA	4	18.81	833.8	3.41	20.22	2.0	18.8	850.6	833.8	16.81
RS-09	Trackhoe	MW-09978	1/7/2015	Still in use	Gauging/LNAPL Recovery	846.75	847.60	18.85	NA	4	18.00	828.8	2.85	18.85	2.0	18.0	844.8	828.8	16.00
RS-10	Trackhoe	MW-09978	1/7/2015	Still in use	Gauging/LNAPL Recovery	846.28	847.42	20.06	NA	4	18.92	827.4	3.14	20.06	2.0	18.9	844.3	827.4	16.92
RS-11	Trackhoe	MW-09978	1/7/2015	Still in use	Gauging/LNAPL Recovery	846.35	847.44	22.06	NA	4	20.97	825.4	3.09	22.06	2.0	21.0	844.3	825.4	18.97
RS-12	Trackhoe	MW-09978	1/7/2015	Still in use	Gauging/LNAPL Recovery	846.58	847.74	21.29	NA	4	20.13	826.5	3.16	21.29	2.0	20.1	844.6	826.5	18.13
RS-13	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	845.39	845.98	19.92	NA	4	19.33	826.1	1.96	19.92	1.4	19.3	844.0	826.1	17.96
RS-14	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	844.66	845.97	19.93	NA	4	18.62	826.0	3.31	19.93	2.0	18.6	842.7	826.0	16.62
RS-15	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	845.36	846.41	19.93	NA	4	18.88	826.5	3.05	19.93	2.0	18.9	843.4	826.5	16.88
RS-16	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	844.56	845.44	19.98	NA	4	19.10	825.5	2.88	19.98	2.0	19.1	842.6	825.5	17.10
RS-17	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	843.29	844.22	19.91	NA	4	18.98	824.3	2.93	19.91	2.0	19.0	841.3	824.3	16.98
RS-18	Trackhoe	MW-09978	1/8/2015	Still in use	Gauging/LNAPL Recovery	846.82	847.89	19.98	NA	4	18.91	827.9	3.07	19.98	2.0	18.9	844.8	827.9	16.91
RS-20	Trackhoe	MW-09978	3/19/2015	Still in use	Gauging/LNAPL Recovery	841.73	842.69	11.84	NA	4	9.91	831.8	3.93	11.84	2.0	9.9	839.7	831.8	7.91
Recovery Trench Sumps																			
RT-1A	Trackhoe	MW-09978	1/6/2015	Still in use	Gauging/LNAPL Recovery	852.86	854.06	20.89	NA	4	20.00	832.9	3.20	21.20	2.0	20.0	850.9	832.9	18.00
RT-1B	Trackhoe	MW-09978	1/6/2015	Still in use	Gauging/LNAPL Recovery	853.29	854.15	21.10	NA	4	20.00	833.3	2.86	20.86	2.0	20.0	851.3	833.3	18.00
RT-1C	Trackhoe	MW-09978	1/6/2015	Still in use	Gauging/LNAPL Recovery	853.55	854.55	21.27	NA	4	20.00	833.5	3.00	21.00	2.0	20.0	851.5	833.5	18.00
RT-2A	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	815.66	817.48	10.81	NA	4	10.00	805.7	3.82	11.82	2.0	10.0	813.7	805.7	8.00
RT-2B	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	816.72	817.61	10.82	NA	4	10.00	806.7	2.89	10.89	2.0	10.0	814.7	806.7	8.00
RT-2C	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	816.86	818.06	10.23	NA	4	10.00	806.9	3.20	11.20	2.0	10.0	814.9	806.9	8.00
RT-2D	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	817.11	818.12	10.21	NA	4	10.00	807.1	3.01	11.01	2.0	10.0	815.1	807.1	8.00
RT-2E	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	817.32	818.25	10.24	NA	4	10.00	807.3	2.93	10.93	2.0	10.0	815.3	807.3	8.00
RT-2F	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	817.74	818.57	10.23	NA	4	10.00	807.7	2.83	10.83	2.0	10.0	815.7	807.7	8.00
RT-2G	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	819.27	820.07	10.24	NA	4	10.00	809.3	2.80	10.80	2.0	10.0	817.3	809.3	8.00
RT-2I	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	819.23	819.51	10.20	NA	4	10.00	809.2	2.28	10.28	2.0	10.0	817.2	809.2	8.00
RT-2J	Trackhoe	MW-09978	1/22/2015	Still in use	Gauging/LNAPL Recovery	817.47	817.63	10.22	NA	4	10.00	807.5	2.16	10.16	2.0	10.0	815.5	807.5	8.00
RT-2K	Trackhoe	MW-09978	3/20/2015	Still in use	Gauging/LNAPL Recovery	816.11	817.40	4.14	NA	4	2.50	813.6	2.64	4.14	1.0	2.5	815.1	813.6	1.50
RT-2L	Trackhoe	MW-09978	3/20/2015	Still in use	Gauging/LNAPL Recovery	817.95	819.54	6.60	NA	4	3.71	814.2	3.89	6.60	1.0	3.7	816.9	814.2	2.71
Piezometers																			
TW-04R	DPT	MW-10006	2/4/2015	Still in use	Gauging	852.68	852.64	5.46	2.2	1	5.5	847.2	2.46	5.46	2.5	5.5	850.2	847.2	3.00
TW-05R	DPT	MW-10006	2/4/2015	Still in use	Gauging	849.96	849.93	8.87	2.2	1	8.8	841.2	2.87	8.87	2.8	8.9	847.2	841.1	6.00
TW-14R	DPT	MW-10006	2/4/2015	Still in use	Gauging	853.47	853.37	6.20	2.2	1	6.5	847.0	2.20	6.20	2.5	6.3	851.0	847.2	4.00
TW-15R	DPT	MW-10006	2/4/2015	Still in use	Gauging	850.70	850.62	4.85	2.2	1	5	845.7	1.85	4.85	2.0	4.9	848.7	845.8	3.00
TW-21	DPT	MW-09978	1/22/2015	Still in use	Gauging	849.72	849.70	9.54	2.2	1	14	835.7	-0.46	9.54	4.0	9.6	845.7	840.2	10.00
TW-28	DPT	MW-09978	1/23/2015	Still in use	Gauging	851.57	851.42	31.84	2.2	1	30	821.6	11.84	31.84	10.0	32.0	841.6	819.6	20.00
TW-30	DPT	MW-09978	1/23/2015	Still in use	Gauging	851.86	851.81	23.15	2.2	1	24	827.9	8.15	23.15	9.0	23.2	842.9	828.7	15.00
TW-34	DPT	MW-09978	1/24/2015	Still in use	Gauging	854.92	854.79	25.04	2.2	1	23	831.9	10.04	25.04	8.0	25.2	846.9	829.7	15.00
TW-35	DPT	MW-09978	1/24/2015	Still in use	Gauging	854.22	854.10	25.12	2.2	1	23	831.2	10.12	25.12	8.0	25.2	846.2	829.0	15.00
TW-40	DPT	MW-09978	1/24/2015	Still in use	Gauging	853.45	853.35	34.05	2.2	1	33	820.5	14.05	34.05	13.0	34.2	840.5	819.3	20.00
TW-41	DPT	MW-09978	1/25/2015	Still in use	Gauging	849.38	849.38	32.15	2.2	1	34	815.4	7.15	32.15	9.0	32.1	840.4	817.2	25.00
TW-42	DPT	MW-09978	1/25/2015	Still in use	Gauging	847.02	846.84	27.50	2.2	1	29.5	817.5	7.50	27.50	9.5	27.7	837.5	819.3	20.00
TW-45	DPT	MW-09978	1/25/2015	Still in use	Gauging	848.26	848.31	36.86	2.2	1	37.5	810.8	11.86	36.86	12.5	36.8	835.8	811.4	25.00
TW-55	DPT	MW-10006	2/5/2015	Still in use	Gauging	846.00	845.93	41.50	2.7	1	43	803.0	11.50	41.50	13.0	41.6	833.0	804.4	30.00
TW-59	DPT	MW-09978	1/30/2015	Still in use	Gauging	834.84	834.78	21.15	2.7	1	22	812.8	6.15	21.15	7.0	21.2	827.8	813.6	15.00
TW-60	DPT	MW-09978	1/30/2015	Still in use	Gauging	828.00	828.03	37.20	2.7	1	41.5	786.5	2.20	37.20	6.5	37.2	821.5	790.8	35.00
TW-64	DPT	MW-09978	2/2/2015	Still in use	Gauging	845.89	845.88	52.85	2.2	1	55	790.9	2.85	52.85	5.0	52.9	840.9	793.0	50.00
TW-65	DPT	MW-09978	2/2/2015	Still in use	Gauging	845.66	845.62	44.81	2.2	1	44.5	801.2	9.81	44.81	9.5	44.8	836.2	800.8	35.00
TW-66	DPT	MW-09978	2/2/2015	Still in use	Gauging	820.18	820.31	23.81	2.7	1	24	796.2	3.81	23.81	4.0	23.7	816.2	796.5	20.00
TW-67	DPT	MW-09978	2/3/2015	Still in use	Gauging	852.88	852.71	26.47	2.7	1	27	825.9	6.47	26.47	7.0	26.6	845.9	826.2	20.00
TW-68	DPT	MW-09978	2/3/2015	Still in use	Gauging	846.59	846.45	29.96	2.2	1	27	819.6	9.96	29.96	7.0	30.1	839.6	816.5	20.00

Table 4. Well Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Permit #	Date Installed	Date Abandoned	Purpose	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Measured Depth to Bottom (ft BTOC)	Bore Hole Diameter (in)	Well Dia (in)	Well Depth (ft bgs)	Bottom of Well (ft amsl)	Top of Screen or Open Borehole Interval (ft BTOC)	Bottom of Screen or Open Borehole Interval (ft BTOC)	Top of Screen or Open Borehole Interval (ft bgs)	Bottom of Screen or Open Borehole Interval (ft bgs)	Top of Screen or Open Borehole Interval (ft amsl)	Bottom of Screen or Open Borehole Interval (ft amsl)	Length of Screen or Open Borehole Interval (ft)
TW-69	DPT	MW-09978	2/3/2015	Still in use	Gauging	840.38	840.27	51.91	2.2	1	50	790.4	11.91	51.91	10.0	52.0	830.4	788.4	40.00
TW-70	DPT	MW-09978	2/3/2015	Still in use	Gauging	842.07	841.95	45.05	2.2	1	43	799.1	10.05	45.05	8.0	45.2	834.1	796.9	35.00
TW-73	DPT	MW-09978	2/3/2015	Still in use	Gauging	850.60	850.53	16.00	2.7	1	16	834.6	6.00	16.00	6.0	16.1	844.6	834.5	10.00
TW-76	DPT	MW-10006	2/4/2015	Still in use	Gauging	852.53	852.44	43.62	2.7	1	43	809.5	8.62	43.62	8.0	43.7	844.5	808.8	35.00
TW-81	DPT	MW-10006	2/5/2015	Still in use	Gauging	849.48	849.43	7.00	2.2	1	7	842.5	2.00	7.00	2.0	7.0	847.5	842.4	5.00
TW-82	DPT	MW-10006	2/5/2015	Still in use	Gauging	849.83	849.64	10.00	2.2	1	10	839.8	2.00	10.00	2.0	10.2	847.8	839.6	8.00
TW-83	DPT	MW-10006	2/5/2015	Still in use	Gauging	850.54	850.44	17.00	2.2	1	17	833.5	2.00	17.00	2.0	17.1	848.5	833.4	15.00
TW-84	DPT	MW-10006	2/5/2015	Still in use	Gauging	851.38	851.22	13.50	2.2	1	13.5	837.9	3.50	13.50	3.5	13.7	847.9	837.7	10.00
TW-85	DPT	MW-10006	2/5/2015	Still in use	Gauging	843.64	843.49	39.00	2.7	1	39	804.6	9.00	39.00	9.0	39.2	834.6	804.5	30.00
TW-86	DPT	MW-10006	2/5/2015	Still in use	Gauging	853.28	853.10	6.00	2.2	1	6	847.3	2.00	6.00	2.0	6.2	851.3	847.1	4.00
TW-87	DPT	MW-10006	2/5/2015	Still in use	Gauging	852.33	852.25	7.00	2.2	1	7	845.3	2.00	7.00	2.0	7.1	850.3	845.3	5.00
TW-90	DPT	MW-10006	2/6/2015	Still in use	Gauging	845.48	845.43	46.50	2.7	1	46.5	799.0	6.50	46.50	6.5	46.6	839.0	798.9	40.00
TW-94	DPT	MW-10006	2/10/2015	Still in use	Gauging	840.75	840.58	40.00	2.7	1	40	800.8	5.00	40.00	5.0	40.2	835.8	800.6	35.00
TW-96	DPT	MW-10006	2/11/2015	Still in use	Gauging	840.52	840.40	28.76	2.7	1	30	810.5	3.76	28.76	5.0	28.9	835.5	811.6	25.00
Vertical Air Sparging Wells																			
VAS-01	Mobile B57 HSA	SCHE03020469	7/28/2016	Still in use	Cupboard Creek Protection	853.269	NS	NA	8.50	2.00	32.20	NA	NA	NA	28.70	31.20	NA	NA	2.50
VAS-02	Mobile B57 HSA	SCHE03020469	7/27/2016	Still in use	Cupboard Creek Protection	852.360	NS	NA	8.50	2.00	27.00	NA	NA	NA	23.50	26.00	NA	NA	2.50
VAS-03	Mobile B57 HSA	SCHE03020469	7/27/2016	Still in use	Cupboard Creek Protection	852.132	NS	NA	8.50	2.00	18.30	NA	NA	NA	14.80	17.30	NA	NA	2.50
VAS-04	Geoprobe 8040 HSA	SCHE03020469	8/4/2016	Still in use	Cupboard Creek Protection	852.056	NS	NA	8.50	2.00	16.70	NA	NA	NA	13.20	15.70	NA	NA	2.50
VAS-05	Mobile B57 HSA	SCHE03020469	7/27/2016	Still in use	Cupboard Creek Protection	851.559	NS	NA	8.50	2.00	13.00	NA	NA	NA	9.50	12.00	NA	NA	2.50
VAS-06	Mobile B57 HSA	SCHE03020469	7/26/2016	Still in use	Cupboard Creek Protection	851.612	NS	NA	8.50	2.00	14.40	NA	NA	NA	10.90	13.40	NA	NA	2.50
VAS-07	Mobile B57 HSA	SCHE03020469	7/26/2016	Still in use	Cupboard Creek Protection	851.603	NS	NA	8.50	2.00	19.40	NA	NA	NA	15.90	18.40	NA	NA	2.50
VAS-08	Mobile B57 HSA	SCHE03020469	7/25/2016	Still in use	Cupboard Creek Protection	851.583	NS	NA	8.50	2.00	22.00	NA	NA	NA	18.50	21.00	NA	NA	2.50
VAS-09	Mobile B57 HSA	SCHE03020469	7/25/2016	Still in use	Cupboard Creek Protection	851.607	NS	NA	8.50	2.00	14.00	NA	NA	NA	10.50	13.00	NA	NA	2.50
VAS-10	Mobile B57 HSA	SCHE03020469	7/25/2016	Still in use	Cupboard Creek Protection	851.411	NS	NA	8.50	2.00	16.10	NA	NA	NA	12.60	15.10	NA	NA	2.50
VAS-11	Mobile B57 HSA	SCHE03020469	7/28/2016	Still in use	Cupboard Creek Protection	852.476	NS	NA	8.50	2.00	25.30	NA	NA	NA	21.80	24.30	NA	NA	2.50
VAS-12	Geoprobe 8040 HSA	SCHE03020469	8/5/2016	Still in use	Cupboard Creek Protection	851.535	NS	NA	8.50	2.00	24.20	NA	NA	NA	20.70	23.20	NA	NA	2.50
VAS-13	Geoprobe 8040 HSA	SCHE03020469	8/5/2016	Still in use	Cupboard Creek Protection	851.701	NS	NA	8.50	2.00	19.60	NA	NA	NA	16.10	18.60	NA	NA	2.50
VAS-14	Geoprobe 8040 HSA	SCHE03020469	8/4/2016	Still in use	Cupboard Creek Protection	851.239	NS	NA	8.50	2.00	16.20	NA	NA	NA	12.70	15.20	NA	NA	2.50
VAS-15	Geoprobe 8040 HSA	SCHE03020469	8/4/2016	Still in use	Cupboard Creek Protection	850.732	NS	NA	8.50	2.00	15.50	NA	NA	NA	12.00	14.50	NA	NA	2.50
VAS-16	Geoprobe 8040 HSA	SCHE03020469	8/3/2016	Still in use	Cupboard Creek Protection	850.305	NS	NA	8.50	2.00	17.90	NA	NA	NA	14.40	16.90	NA	NA	2.50
VAS-17	Geoprobe 8040 HSA	SCHE03020469	8/3/2016	Still in use	Cupboard Creek Protection	849.842	NS	NA	8.50	2.00	19.30	NA	NA	NA	15.80	18.30	NA	NA	2.50
VAS-18	Geoprobe 8040 HSA	SCHE03020469	8/8/2016	Still in use	Cupboard Creek Protection	849.513	NS	NA	8.50	2.00	16.50	NA	NA	NA	13.00	15.50	NA	NA	2.50
VAS-19	Mobile B57 HSA	SCHE03020469	7/26/2016	Still in use	Cupboard Creek Protection	850.465	NS	NA	8.50	2.00	17.20	NA	NA	NA	13.60	16.10	NA	NA	2.50
VAS-20	Mobile B57 HSA	SCHE03020469	7/19/2016	Still in use	Brown's Creek Protection	827.789	NS	NA	8.50	2.00	47.60	NA	NA	NA	44.60	47.10	NA	NA	2.50
VAS-21	Mobile B57 HSA	SCHE03020469	7/19/2016	Still in use	Brown's Creek Protection	826.304	NS	NA	8.50	2.00	53.50	NA	NA	NA	50.00	52.50	NA	NA	2.50
VAS-22	Mobile B57 HSA	SCHE03020469	7/21/2016	Still in use	Brown's Creek Protection	827.394	NS	NA	8.50	2.00	57.00	NA	NA	NA	53.50	56.00	NA	NA	2.50
VAS-23	Mobile B57 HSA	SCHE03020469	7/22/2016	Still in use	Brown's Creek Protection	827.211	NS	NA	8.50	2.00	49.50	NA	NA	NA	46.00	48.50	NA	NA	2.50
VAS-24	Mobile B57 HSA	SCHE03020469	7/5/2016	Still in use	Brown's Creek Protection	826.803	NS	NA	8.50	2.00	58.50	NA	NA	NA	55.00	57.50	NA	NA	2.50
VAS-25	Mobile B57 HSA	SCHE03020469	7/11/2016	Still in use	Brown's Creek Protection	826.411	NS	NA	8.50	2.00	54.00	NA	NA	NA	50.50	53.00	NA	NA	2.50
VAS-26	Mobile B57 HSA	SCHE03020469	7/11/2016	Still in use	Brown's Creek Protection	825.180	NS	NA	8.50	2.00	55.00	NA	NA	NA	51.50	54.00	NA	NA	2.50
VAS-27	Mobile B57 HSA	SCHE03020469	7/8/2016	Still in use	Brown's Creek Protection	826.369	NS	NA	8.50	2.00	54.00	NA	NA	NA	50.50	53.00	NA	NA	2.50
VAS-28	Mobile B57 HSA	SCHE03020469	7/6/2016	Still in use	Brown's Creek Protection	828.930	NS	NA	8.50	2.00	23.10	NA	NA	NA	19.80	22.30	NA	NA	2.50
VAS-29	Mobile B57 HSA	SCHE03020469	7/6/2016	Still in use	Brown's Creek Protection	832.025	NS	NA	8.50	2.00	27.50	NA	NA	NA	24.00	26.50	NA	NA	2.50
VAS-30	Mobile B57 HSA	SCHE03020469	6/21/2016	Still in use	Brown's Creek Protection	831.485	NS	NA	8.50	2.00	52.90	NA	NA	NA	49.40	51.90	NA	NA	2.50

Table 4. Well Construction Information

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Installation Method	Permit #	Date Installed	Date Abandoned	Purpose	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Measured Depth to Bottom (ft BTOC)	Bore Hole Diameter (in)	Well Dia (in)	Well Depth (ft bgs)	Bottom of Well (ft amsl)	Top of Screen or Open Borehole Interval (ft BTOC)	Bottom of Screen or Open Borehole Interval (ft BTOC)	Top of Screen or Open Borehole Interval (ft bgs)	Bottom of Screen or Open Borehole Interval (ft bgs)	Top of Screen or Open Borehole Interval (ft amsl)	Bottom of Screen or Open Borehole Interval (ft amsl)	Length of Screen or Open Borehole Interval (ft)
VAS-31	Mobile B57 HSA	SCHE03020469	6/21/2016	Still in use	Brown's Creek Protection	828.337	NS	NA	8.50	2.00	42.00	NA	NA	NA	38.50	41.00	NA	NA	2.50
VAS-32	Mobile B57 HSA	SCHE03020469	6/30/2016	Still in use	Brown's Creek Protection	836.257	NS	NA	8.50	2.00	43.00	NA	NA	NA	39.50	42.00	NA	NA	2.50
VAS-33	Mobile B57 HSA	SCHE03020469	6/29/2016	Still in use	Brown's Creek Protection	840.900	NS	NA	8.50	2.00	52.60	NA	NA	NA	49.10	51.60	NA	NA	2.50
VAS-34	Mobile B57 HSA	SCHE03020469	7/13/2016	Still in use	Brown's Creek Protection	836.585	NS	NA	8.50	2.00	53.50	NA	NA	NA	50.00	52.50	NA	NA	2.50
VAS-35	Mobile B57 HSA	SCHE03020469	7/13/2016	Still in use	Brown's Creek Protection	831.212	NS	NA	8.50	2.00	40.00	NA	NA	NA	36.50	39.00	NA	NA	2.50
VAS-36	Mobile B57 HSA	SCHE03020469	7/7/2016	Still in use	Brown's Creek Protection	831.361	NS	NA	8.50	2.00	33.20	NA	NA	NA	29.70	32.20	NA	NA	2.50
VAS-37	Mobile B57 HSA	SCHE03020469	7/7/2016	Still in use	Brown's Creek Protection	832.454	NS	NA	8.50	2.00	16.50	NA	NA	NA	13.00	15.50	NA	NA	2.50
VAS-38	Mobile B57 HSA	SCHE03020469	7/6/2016	Still in use	Brown's Creek Protection	834.566	NS	NA	8.50	2.00	21.10	NA	NA	NA	16.60	19.10	NA	NA	2.50
VAS-39	Mobile B57 HSA	SCHE03020469	6/22/2016	Still in use	Brown's Creek Protection	835.956	NS	NA	8.50	2.00	42.40	NA	NA	NA	38.90	41.40	NA	NA	2.50
VAS-40	Mobile B57 HSA	SCHE03020469	6/23/2016	Still in use	Brown's Creek Protection	833.753	NS	NA	8.50	2.00	40.00	NA	NA	NA	36.50	39.00	NA	NA	2.50
VAS-41	Mobile B57 HSA	SCHE03020469	6/28/2016	Still in use	Brown's Creek Protection	845.071	NS	NA	8.50	2.00	27.80	NA	NA	NA	24.30	26.80	NA	NA	2.50
VAS-42A	Mobile B57 HSA	SCHE03020469	7/14/2016	Still in use	Brown's Creek Protection	845.304	NS	NA	8.50	2.00	39.30	NA	NA	NA	35.80	38.30	NA	NA	2.50
VAS-43A	Mobile B57 HSA	SCHE03020469	7/15/2016	Still in use	Brown's Creek Protection	843.078	NS	NA	8.50	2.00	66.50	NA	NA	NA	63.00	65.50	NA	NA	2.50
VAS-44A	Mobile B57 HSA	SCHE03020469	7/18/2016	Still in use	Brown's Creek Protection	838.353	NS	NA	8.50	2.00	72.50	NA	NA	NA	69.00	71.50	NA	NA	2.50
VAS-46	Mobile B57 HSA	SCHE03020469	6/24/2016	Still in use	Brown's Creek Protection	839.503	NS	NA	8.50	2.00	20.80	NA	NA	NA	18.00	20.50	NA	NA	2.50
Vertical Bedrock Sparging Wells																			
VBS-01	Hollow Stem Auger/Wire Line/Air Rotary	SCHE03020469M	1/28/2017	Still in use	Brown's Creek Protection	NS	NS	38.15	4.00	2.00	38.50	NA	NA	NA	34.50	38.50	NA	NA	2.00
VBS-02	Hollow Stem Auger/Wire Line/Air Rotary	SCHE03020469M	1/28/2017	Still in use	Brown's Creek Protection	NS	NS	31.05	4.00	2.00	31.00	NA	NA	NA	27.00	31.00	NA	NA	2.00
VBS-03	Hollow Stem Auger/Wire Line/Air Rotary	SCHE03020469M	1/27/2017	Still in use	Brown's Creek Protection	NS	NS	36.20	4.00	2.00	36.20	NA	NA	NA	32.20	36.20	NA	NA	2.00

Notes:

amsl = above mean sea level relative to North American Vertical Datum of 1988 (NAVD88). Benchmark is 34.8289659 degrees north, 82.3710354 degrees west (NAD83, 2011), elevation 929.1 ft NAVD88.

bgs = below ground surface

BTOC = below top of casing

DPT = direct push

ft = feet

HSA = hollow-stem auger

in = inches

NA = not applicable

NS = location not surveyed

RNE = Refusal not encountered

TOC = top of casing

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
MW-01					853.07			-	-	-
	2/3/2018	-	5.93	-		847.14	-	-	-	-
	1/8/2018	-	9.50	-		843.57	-	-	-	-
MW-01B					852.99			-	-	-
	2/3/2018	-	9.98	-		843.01	-	-	-	-
	1/8/2018	-	10.55	-		842.44	-	-	-	-
MW-02					841.04			-	-	-
	2/3/2018	-	-	-		841.04	-	-	-	-
	1/8/2018	-	14.26	-		826.78	-	-	-	-
MW-02B					841.19			-	-	-
	2/3/2018	-	0.10	-		841.09	-	-	-	-
	1/8/2018	-	23.70	-		817.49	-	-	-	-
MW-03					838.36			-	-	-
	2/3/2018	-	-	-		838.36	-	-	-	-
	1/8/2018	-	19.98	-		818.38	-	-	-	-
MW-04					844.42			-	-	-
	2/3/2018	-	8.70	-		835.72	-	-	-	-
	1/8/2018	-	14.97	-		829.45	-	-	-	-
MW-05					851.11			-	-	-
	2/3/2018	-	16.03	-		835.08	-	-	-	-
	1/8/2018	-	16.57	-		834.54	-	-	-	-
MW-06					852.92			-	-	-
	2/3/2018	-	14.95	-		837.97	-	-	-	-
MW-06B					852.57			-	-	-
	2/3/2018	-	14.57	-		838.00	-	-	-	-
MW-07					853.02			-	-	-
	2/3/2018	-	13.20	-		839.82	-	-	-	-
	1/8/2018	-	13.21	-		839.81	-	-	-	-
MW-08					844.72			-	-	-
	2/3/2018	-	5.50	-		839.22	-	-	-	-
	1/8/2018	-	19.43	-		825.29	-	-	-	-
MW-09					843.63			-	-	-
	2/3/2018	-	-	-		843.63	-	-	-	-
	1/8/2018	-	18.30	-		825.33	-	-	-	-
MW-09B					843.92			-	-	-
	2/3/2018	-	2.15	-		841.77	-	-	-	-
MW-10					845.41			-	-	-
	2/3/2018	-	8.20	-		837.21	-	-	-	-
	1/8/2018	-	15.08	-		830.33	-	-	-	-
MW-11					855.63			-	-	-
	2/3/2018	29.68	29.79	0.11		825.84	825.92	-	-	-
	1/8/2018	30.68	30.90	0.22		824.73	824.89	-	-	-
MW-12					834.53			-	-	-
	2/3/2018	-	14.07	-		820.46	-	-	-	-
	1/8/2018	-	15.11	-		819.42	-	-	-	-
MW-12B					834.98			-	-	-
	2/3/2018	-	14.60	-		820.38	-	-	-	-
	1/8/2018	-	15.50	-		819.48	-	-	-	-
MW-13					848.84			-	-	-
	2/3/2018	-	21.88	-		826.96	-	-	-	-
MW-13B					849.82			-	-	-
	2/3/2018	-	22.37	-		827.45	-	-	-	-
MW-14					838.70			-	-	-
	2/3/2018	-	17.29	-		821.41	-	-	-	-
MW-14B					840.20			-	-	-
	2/3/2018	-	19.01	-		821.19	-	-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
MW-15					831.03			-	-	-
	2/3/2018	-	13.42	-		817.61	-	-	-	-
	1/8/2018	-	12.84	-		818.19	-	-	-	-
MW-15B					831.29			-	-	-
	2/3/2018	-	15.65	-		815.64	-	-	-	-
	1/8/2018	-	16.23	-		815.06	-	-	-	-
MW-16					847.67			-	-	-
	2/3/2018	-	3.00	-		844.67	-	-	-	-
	1/8/2018	-	18.19	-		829.48	-	-	-	-
MW-17					855.35			-	-	-
	2/3/2018	-	10.85	-		844.50	-	-	-	-
MW-17B					855.37			-	-	-
	2/3/2018	-	16.55	-		838.82	-	-	-	-
MW-18					846.89			-	-	-
	2/3/2018	-	14.50	-		832.39	-	-	-	-
	1/8/2018	-	19.60	-		827.29	-	-	-	-
MW-19					853.94			-	-	-
	2/3/2018	-	11.20	-		842.74	-	-	-	-
	1/8/2018	-	11.78	-		842.16	-	-	-	-
MW-20					852.89			-	-	-
	2/3/2018	12.90	12.97	0.07		839.92	839.97	-	-	-
	1/8/2018	13.71	14.64	**0.93**		838.25	838.92	-	-	-
MW-21					855.77			-	-	-
	2/3/2018	-	16.73	-		839.04	-	-	-	-
MW-22					854.60			-	-	-
	2/3/2018	-	10.01	-		844.59	-	-	-	-
	1/8/2018	-	10.01	-		844.59	-	-	-	-
MW-23					849.57			-	-	-
	2/3/2018	-	10.25	-		839.32	-	-	-	-
	1/8/2018	-	11.02	-		838.55	-	-	-	-
MW-23B					849.69			-	-	-
	2/3/2018	-	11.35	-		838.34	-	-	-	-
MW-24					817.92			-	-	-
	2/3/2018	-	4.41	-		813.51	-	-	-	-
MW-24B					818.72			-	-	-
	2/3/2018	-	5.45	-		813.27	-	-	-	-
MW-25					826.18			-	-	-
	2/3/2018	-	8.39	-		817.79	-	-	-	-
	1/8/2018	-	8.80	-		817.38	-	-	-	-
MW-25B					823.81			-	-	-
	2/3/2018	-	4.80	-		819.01	-	-	-	-
	1/8/2018	-	5.53	-		818.28	-	-	-	-
MW-26					847.56			-	-	-
	2/3/2018	-	5.58	-		841.98	-	-	-	-
	1/8/2018	-	6.68	-		840.88	-	-	-	-
MW-26B					847.81			-	-	-
	2/3/2018	-	8.48	-		839.33	-	-	-	-
MW-27					854.11			-	-	-
	2/3/2018	-	27.18	-		826.93	-	-	-	-
MW-27B					857.14			-	-	-
	2/3/2018	-	30.70	-		826.44	-	-	-	-
MW-28					844.31			-	-	-
	2/3/2018	-	24.21	-		820.10	-	-	-	-
	1/8/2018	-	24.15	-		820.16	-	-	-	-
MW-29					852.20			-	-	-
	2/3/2018	-	9.18	-		843.02	-	-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
MW-29 (cont'd)	1/8/2018	-	10.36	-		841.84	-	-	-	-
MW-30					841.28			-	-	-
	2/3/2018	-	13.49	-		827.79	-	-	-	-
	1/8/2018	-	14.59	-		826.69	-	-	-	-
MW-31					845.04			-	-	-
	2/3/2018	-	19.23	-		825.81	-	-	-	-
	1/8/2018	-	22.55	-		822.49	-	-	-	-
MW-31B					844.94			-	-	-
	2/3/2018	-	20.25	-		824.69	-	-	-	-
MW-32					842.93			-	-	-
	2/3/2018	-	6.73	-		836.20	-	-	-	-
MW-33					849.20			-	-	-
	2/3/2018	-	25.17	-		824.03	-	-	-	-
MW-33T					849.11			-	-	-
	2/3/2018	-	26.44	-		822.67	-	-	-	-
MW-34					816.35			-	-	-
	2/3/2018	-	2.37	-		813.98	-	-	-	-
	1/8/2018	-	2.48	-		813.87	-	-	-	-
MW-35					829.40			-	-	-
	2/3/2018	-	8.18	-		821.22	-	-	-	-
	1/8/2018	-	10.57	-		818.83	-	-	-	-
MW-36					858.47			-	-	-
	2/3/2018	-	19.69	-		838.78	-	-	-	-
MW-36B					858.15			-	-	-
	2/3/2018	-	19.43	-		838.72	-	-	-	-
MW-37					813.92			-	-	-
	2/3/2018	-	3.39	-		810.53	-	-	-	-
MW-38					813.28			-	-	-
	2/3/2018	-	1.84	-		811.44	-	-	-	-
	1/8/2018	-	1.95	-		811.33	-	-	-	-
MW-39					819.90			-	-	-
	2/3/2018	-	5.22	-		814.68	-	-	-	-
	1/8/2018	-	4.86	-		815.04	-	-	-	-
MW-40					817.79			-	-	-
	2/3/2018	-	2.63	-		815.16	-	-	-	-
	1/8/2018	-	2.72	-		815.07	-	-	-	-
MW-41					819.68			-	-	-
	2/3/2018	-	4.38	-		815.30	-	-	-	-
	1/8/2018	-	4.40	-		815.28	-	-	-	-
MW-42					820.33			-	-	-
	2/3/2018	-	5.12	-		815.21	-	-	-	-
MW-43					818.12			-	-	-
	2/3/2018	-	4.15	-		813.97	-	-	-	-
	1/8/2018	-	4.35	-		813.77	-	-	-	-
MW-43B					818.80			-	-	-
	2/3/2018	-	2.10	-		816.70	-	-	-	-
MW-44					853.67			-	-	-
	2/3/2018	-	8.63	-		845.04	-	-	-	-
MW-44B					853.38			-	-	-
	2/3/2018	-	14.25	-		839.13	-	-	-	-
MW-45					852.47			-	-	-
	2/3/2018	-	14.23	-		838.24	-	-	-	-
	1/8/2018	-	14.25	-		838.22	-	-	-	-
MW-45B					852.85			-	-	-
	2/3/2018	-	15.63	-		837.22	-	-	-	-
MW-46					845.47			-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
MW-46 (cont'd)	2/3/2018	-	8.35	-		837.12	-	-	-	-
MW-47					842.98			-	-	-
	2/3/2018	-	16.38	-		826.60	-	-	-	-
MW-48B					832.34			-	-	-
	2/3/2018	-	17.90	-		814.44	-	-	-	-
MW-49					846.78			-	-	-
	2/3/2018	-	19.87	-		826.91	-	-	-	-
MW-50B					850.34			-	-	-
	2/3/2018	-	20.45	-		829.89	-	-	-	-
RS-01					849.13			-	-	-
	2/2/2018	-	NM	-		-	-	-	-	-
RS-02					849.52			-	-	-
	2/3/2018	9.94	9.96	0.02		839.56	839.57	-	-	-
RS-04					851.47			-	-	-
	2/3/2018	-	9.75	-		841.72	-	-	-	-
RS-05					848.31			-	-	-
	2/2/2018	-	NM	-		-	-	-	-	-
RS-06					849.47			-	-	-
	2/3/2018	-	10.87	-		838.60	-	-	-	-
RS-07					855.08			-	-	-
	2/3/2018	13.74	13.75	0.01		841.33	841.34	-	-	-
	1/26/2018	-	14.07	-		841.01	-	-	-	-
	1/20/2018	-	14.07	-		841.01	-	-	-	-
	1/10/2018	14.32	14.33	0.01		840.75	840.76	1/15/2018	9:45	9:50
	1/5/2018	14.15	14.16	0.01		840.92	840.93	-	-	-
RS-08					854.00			-	-	-
	2/3/2018	14.62	14.63	0.01		839.37	839.38	-	-	-
	1/26/2018	14.89	14.97	0.08		839.03	839.09	1/26/2018	9:05	9:10
	1/20/2018	14.72	14.78	0.06		839.22	839.26	-	-	-
	1/10/2018	14.68	14.75	0.07		839.25	839.30	1/15/2018	9:55	10:00
	1/5/2018	14.87	14.94	0.07		839.06	839.11	1/8/2018	11:51	11:56
RS-09					847.60			-	-	-
	2/3/2018	-	8.10	-		839.50	-	-	-	-
RS-10					847.42			-	-	-
	2/3/2018	6.91	6.92	0.01		840.50	840.51	-	-	-
RS-11					847.44			-	-	-
	2/3/2018	-	7.57	-		839.87	-	-	-	-
RS-12					847.74			-	-	-
	2/3/2018	-	7.92	-		839.82	-	-	-	-
RS-13					845.98			-	-	-
	2/3/2018	-	3.75	-		842.23	-	-	-	-
RS-14					845.97			-	-	-
	2/3/2018	-	4.82	-		841.15	-	-	-	-
RS-15					846.41			-	-	-
	2/3/2018	-	5.10	-		841.31	-	-	-	-
RS-16					845.44			-	-	-
	2/3/2018	-	3.83	-		841.61	-	-	-	-
RS-17					844.22			-	-	-
	2/3/2018	-	3.05	-		841.17	-	-	-	-
RS-18					847.89			-	-	-
	2/3/2018	-	8.27	-		839.62	-	-	-	-
RS-20					842.69			-	-	-
	2/3/2018	-	3.40	-		839.29	-	-	-	-
RT-1A					854.06			-	-	-
	2/2/2018	14.23	14.25	0.02		839.81	839.82	-	-	-
	1/26/2018	14.64	14.68	0.04		839.38	839.41	1/26/2018	9:10	9:15

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
RT-1A (cont'd)	1/20/2018	14.52	14.57	0.05		839.49	839.53	-	-	-
	1/10/2018	14.70	14.74	0.04		839.32	839.35	1/15/2018	9:30	9:35
	1/5/2018	14.66	14.73	0.07		839.33	839.38	1/8/2018	11:58	12:03
RT-1B					854.15			-	-	-
	2/2/2018	14.19	14.21	0.02		839.94	839.95	-	-	-
	1/26/2018	14.60	14.64	0.04		839.51	839.54	1/26/2018	9:15	9:20
	1/20/2018	14.48	14.53	0.05		839.62	839.66	-	-	-
	1/10/2018	14.66	14.71	0.05		839.44	839.48	1/15/2018	9:35	9:40
	1/5/2018	14.62	14.69	0.07		839.46	839.51	1/8/2018	12:03	12:08
RT-1C					854.55			-	-	-
	2/2/2018	15.81	15.83	0.02		838.72	838.73	-	-	-
	1/26/2018	15.19	15.23	0.04		839.32	839.35	1/26/2018	9:25	9:30
	1/20/2018	15.06	15.11	0.05		839.44	839.48	-	-	-
	1/10/2018	15.24	15.29	0.05		839.26	839.30	1/15/2018	9:40	9:45
	1/5/2018	15.23	15.29	0.06		839.26	839.30	1/8/2018	12:08	12:13
RT-2A					817.48			-	-	-
	2/2/2018	-	0.85	-		816.63	-	-	-	-
	1/26/2018	-	0.96	-		816.52	-	-	-	-
	1/20/2018	-	0.95	-		816.53	-	-	-	-
	1/10/2018	-	1.07	-		816.41	-	1/15/2018	11:00	11:05
	1/5/2018	-	1.25	-		816.23	-	1/8/2018	10:38	10:43
RT-2B					817.61			-	-	-
	2/2/2018	-	0.95	-		816.66	-	-	-	-
	1/26/2018	-	1.12	-		816.49	-	-	-	-
	1/20/2018	-	1.07	-		816.54	-	-	-	-
	1/10/2018	-	1.27	-		816.34	-	1/15/2018	11:05	11:10
	1/5/2018	-	1.42	-		816.19	-	1/8/2018	10:43	10:48
RT-2C					818.06			-	-	-
	2/2/2018	-	1.38	-		816.68	-	-	-	-
	1/26/2018	-	1.58	-		816.48	-	-	-	-
	1/20/2018	-	NM	-		-	-	-	-	-
	1/10/2018	-	1.72	-		816.34	-	1/15/2018	11:10	11:15
	1/5/2018	-	1.87	-		816.19	-	1/8/2018	10:48	10:53
RT-2D					818.12			-	-	-
	2/2/2018	-	1.46	-		816.66	-	-	-	-
	1/26/2018	-	1.67	-		816.45	-	-	-	-
	1/20/2018	-	1.62	-		816.50	-	-	-	-
	1/10/2018	-	1.80	-		816.32	-	1/15/2018	11:15	11:20
	1/5/2018	-	1.92	-		816.20	-	1/8/2018	10:53	10:58
RT-2E					818.25			-	-	-
	2/2/2018	1.57	1.58	0.01		816.67	816.68	-	-	-
	1/26/2018	-	1.78	-		816.47	-	-	-	-
	1/20/2018	-	NM	-		-	-	-	-	-
	1/10/2018	-	1.89	-		816.36	-	1/15/2018	11:20	11:25
	1/5/2018	-	NM	-		-	-	1/8/2018	10:58	11:03
RT-2F					818.57			-	-	-
	2/2/2018	1.87	1.88	0.01		816.69	816.70	-	-	-
	1/26/2018	-	2.11	-		816.46	-	-	-	-
	1/20/2018	-	NM	-		-	-	-	-	-
	1/10/2018	-	2.22	-		816.35	-	1/15/2018	11:25	11:30
	1/5/2018	-	NM	-		-	-	1/8/2018	11:03	11:08
RT-2G					820.07			-	-	-
	2/2/2018	-	0.95	-		819.12	-	-	-	-
	1/26/2018	-	0.92	-		819.15	-	-	-	-
	1/20/2018	-	NM	-		-	-	-	-	-
	1/10/2018	-	4.44	-		815.63	-	1/15/2018	11:30	11:35

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
RT-2G (cont'd)	1/5/2018	-	NM	-		-	-	1/8/2018	11:08	11:13
RT-2I					819.51			-	-	-
	2/2/2018	-	0.64	-		818.87	-	-	-	-
	1/26/2018	-	1.03	-		818.48	-	-	-	-
	1/20/2018	-	2.79	-		816.72	-	-	-	-
	1/10/2018	-	3.17	-		816.34	-	1/15/2018	11:35	11:40
	1/5/2018	-	NM	-		-	-	1/8/2018	11:13	11:18
RT-2J					817.63			-	-	-
	2/2/2018	-	NM	-		-	-	-	-	-
	1/26/2018	-	0.04	-		817.59	-	-	-	-
	1/20/2018	-	1.08	-		816.55	-	-	-	-
	1/10/2018	-	1.62	-		816.01	-	1/15/2018	11:40	11:45
	1/5/2018	-	1.89	-		815.74	-	1/8/2018	11:18	11:23
RT-2K					817.40			-	-	-
	2/2/2018	-	NM	-		-	-	-	-	-
	1/20/2018	1.35	1.36	0.01		816.04	816.05	1/26/2018	11:00	11:05
	1/10/2018	-	NM	-		-	-	1/15/2018	11:45	11:50
	1/5/2018	-	NM	-		-	-	1/8/2018	11:23	11:28
RT-2L					819.54			-	-	-
	2/2/2018	-	1.95	-		817.59	-	-	-	-
	1/26/2018	2.48	2.49	0.01		817.05	817.06	1/26/2018	10:50	10:55
	1/20/2018	2.30	2.31	0.01		817.23	817.24	-	-	-
	1/10/2018	2.52	2.54	0.02		817.00	817.01	1/15/2018	11:50	11:55
	1/5/2018	-	2.67	-		816.87	-	1/8/2018	11:28	11:33
RW-01					851.92			-	-	-
	2/3/2018	-	13.20	-		838.72	-	-	-	-
RW-02					852.69			-	-	-
	2/2/2018	22.68	22.85	0.17		829.84	829.96	-	-	-
RW-03					852.34			-	-	-
	2/3/2018	23.60	23.61	0.01		828.73	828.74	-	-	-
RW-04					853.93			-	-	-
	2/2/2018	29.54	29.74	0.20		824.19	824.34	-	-	-
	1/26/2018	29.99	30.04	0.05		823.89	823.93	1/26/2018	9:45	9:50
	1/20/2018	30.23	30.54	0.31		823.39	823.62	-	-	-
	1/10/2018	30.57	30.65	0.08		823.28	823.34	1/15/2018	10:10	10:15
	1/5/2018	30.11	30.26	0.15		823.67	823.78	1/8/2018	9:50	9:55
RW-05					853.53			-	-	-
	2/2/2018	32.92	33.68	**0.76**		819.85	820.41	-	-	-
	1/26/2018	33.39	33.73	0.34		819.80	820.05	1/26/2018	9:55	10:00
	1/20/2018	32.96	34.05	**1.09**		819.48	820.28	-	-	-
	1/10/2018	33.13	33.53	0.40		820.00	820.30	1/15/2018	10:15	10:20
	1/5/2018	33.35	33.99	**0.64**		819.54	820.01	1/8/2018	10:01	10:06
RW-06					846.21			-	-	-
	2/2/2018	26.82	26.83	0.01		819.38	819.39	-	-	-
	1/26/2018	27.16	27.18	0.02		819.03	819.04	-	-	-
	1/20/2018	-	26.47	-		819.74	-	-	-	-
	1/10/2018	-	26.55	-		819.66	-	1/15/2018	10:30	10:35
	1/5/2018	-	27.41	-		818.80	-	-	-	-
RW-07					843.19			-	-	-
	2/2/2018	22.94	22.95	0.01		820.24	820.25	-	-	-
	1/26/2018	23.38	23.40	0.02		819.79	819.81	1/26/2018	10:10	10:15
	1/20/2018	23.97	23.99	0.02		819.20	819.22	-	-	-
	1/10/2018	23.02	23.04	0.02		820.15	820.17	1/15/2018	10:40	10:45
	1/5/2018	-	24.03	-		819.16	-	1/8/2018	10:24	10:29
RW-08					835.48			-	-	-
	2/3/2018	-	15.75	-		819.73	-	-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
RW-08 (cont'd)	1/26/2018	16.22	16.23	0.01		819.25	819.26	1/26/2018	10:20	10:25
	1/20/2018	16.03	16.04	0.01		819.44	819.45	-	-	-
	1/10/2018	16.11	16.12	0.01		819.36	819.37	-	-	-
	1/5/2018	-	17.29	-		818.19	-	1/8/2018	10:17	10:27
RW-09					835.12			-	-	-
	2/2/2018	-	12.98	-		822.14	-	-	-	-
	1/26/2018	-	13.44	-		821.68	-	-	-	-
	1/20/2018	-	13.84	-		821.28	-	-	-	-
	1/10/2018	-	13.78	-		821.34	-	-	-	-
	1/5/2018	-	14.57	-		820.55	-	-	-	-
RW-10					848.53			-	-	-
	2/3/2018	-	7.00	-		841.53	-	-	-	-
RW-11					852.97			-	-	-
	2/2/2018	-	13.11	-		839.86	-	-	-	-
	1/26/2018	-	13.98	-		838.99	-	-	-	-
	1/20/2018	-	14.92	-		838.05	-	-	-	-
	1/10/2018	-	13.59	-		839.38	-	-	-	-
	1/5/2018	-	14.88	-		838.09	-	-	-	-
RW-12					854.49			-	-	-
	2/2/2018	-	15.93	-		838.56	-	-	-	-
	1/26/2018	-	15.95	-		838.54	-	-	-	-
	1/20/2018	-	15.79	-		838.70	-	-	-	-
	1/10/2018	-	15.29	-		839.20	-	-	-	-
	1/5/2018	-	15.94	-		838.55	-	-	-	-
RW-13					847.97			-	-	-
	2/3/2018	-	NM	-		-	-	-	-	-
RW-14					827.54			-	-	-
	2/3/2018	-	13.76	-		813.78	-	-	-	-
	1/26/2018	-	7.66	-		819.88	-	1/26/2018	10:30	10:35
	1/20/2018	14.83	14.84	0.01		812.70	812.71	-	-	-
	1/10/2018	-	14.04	-		813.50	-	-	-	-
	1/5/2018	-	NM	-		-	-	-	-	-
RW-15					851.64			-	-	-
	2/2/2018	-	13.88	-		837.76	-	-	-	-
SW-01					812.82			-	-	-
	2/3/2018	-	(0.88)	-		813.70	-	-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
SW-02					808.65			-	-	-
	2/3/2018	-	(1.55)	-		810.20	-	-	-	-
SW-03					815.09			-	-	-
	2/3/2018	-	(1.72)	-		816.81	-	-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
SW-05					838.75			-	-	-
	2/3/2018	-	NM	-		-	-	-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
SW-08					802.04			-	-	-
	2/3/2018	-	(1.06)	-		803.10	-	-	-	-
SW-10					778.09			-	-	-
	2/3/2018	-	(0.40)	-		778.49	-	-	-	-
SW-12					-			-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
SW-13					-			-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
TW-04R					852.64			-	-	-
	2/3/2018	-	4.25	-		848.39	-	-	-	-
TW-05R					849.93			-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
TW-05R (cont'd)	2/3/2018	-	4.32	-		845.61	-	-	-	-
TW-14R					853.37			-	-	-
	2/3/2018	-	4.98	-		848.39	-	-	-	-
TW-15R					850.62			-	-	-
	2/3/2018	-	2.93	-		847.69	-	-	-	-
TW-21					849.70			-	-	-
	2/3/2018	-	2.49	-		847.21	-	-	-	-
TW-28					851.42			-	-	-
	2/3/2018	22.68	22.80	0.12		828.62	828.71	-	-	-
TW-30					851.81			-	-	-
	2/3/2018	-	21.97	-		829.84	-	-	-	-
TW-34					854.79			-	-	-
	2/3/2018	-	22.23	-		832.56	-	-	-	-
TW-35					854.10			-	-	-
	2/3/2018	-	22.73	-		831.37	-	-	-	-
TW-40					853.35			-	-	-
	2/3/2018	-	28.92	-		824.43	-	-	-	-
TW-41					849.38			-	-	-
	2/3/2018	-	27.50	-		821.88	-	-	-	-
TW-42					846.84			-	-	-
	2/3/2018	25.87	26.40	**0.53**		820.44	820.83	-	-	-
TW-45					848.31			-	-	-
	2/3/2018	27.45	27.60	0.15		820.71	820.82	-	-	-
TW-55					845.93			-	-	-
	2/3/2018	-	15.80	-		830.13	-	-	-	-
	1/8/2018	-	21.73	-		824.20	-	-	-	-
TW-59					834.78			-	-	-
	2/3/2018	-	11.50	-		823.28	-	-	-	-
	1/8/2018	-	15.25	-		819.53	-	-	-	-
TW-60					828.03			-	-	-
	2/3/2018	-	9.78	-		818.25	-	-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
TW-64					845.88			-	-	-
	2/3/2018	-	16.70	-		829.18	-	-	-	-
	1/8/2018	-	21.10	-		824.78	-	-	-	-
TW-65					845.62			-	-	-
	2/3/2018	-	21.18	-		824.44	-	-	-	-
TW-66					820.31			-	-	-
	2/3/2018	-	2.45	-		817.86	-	-	-	-
	1/8/2018	-	2.37	-		817.94	-	-	-	-
TW-67					852.71			-	-	-
	2/3/2018	-	12.61	-		840.10	-	-	-	-
	1/8/2018	-	NM	-		-	-	-	-	-
TW-68					846.45			-	-	-
	2/3/2018	-	23.13	-		823.32	-	-	-	-
TW-69					840.27			-	-	-
	2/3/2018	-	13.38	-		826.89	-	-	-	-
TW-70					841.95			-	-	-
	2/3/2018	-	18.75	-		823.20	-	-	-	-
TW-73					850.53			-	-	-
	2/3/2018	-	6.00	-		844.53	-	-	-	-
	1/8/2018	-	9.83	-		840.70	-	-	-	-
TW-76					852.44			-	-	-
	2/3/2018	-	14.17	-		838.27	-	-	-	-
TW-81					849.43			-	-	-
	2/3/2018	-	2.40	-		847.03	-	-	-	-

Table 5. Groundwater Elevation and Product Thickness Data

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location ID	Date	Depth to Product (ft BTOC)	Depth to Water (ft BTOC)	Product Thickness (ft)	Top of Casing Elevation[1,2] (ft amsl)	Groundwater Elevation (ft amsl)	Corrected[3] Groundwater Elevation (ft amsl)	Date of Product Evacuation	Start Time	Finish Time
TW-82					849.64			-	-	-
	2/3/2018	-	2.45	-		847.19	-	-	-	-
TW-83					850.44			-	-	-
	2/3/2018	-	3.18	-		847.26	-	-	-	-
TW-84					851.22			-	-	-
	2/3/2018	-	4.15	-		847.07	-	-	-	-
TW-85					843.49			-	-	-
	2/3/2018	-	-	-		843.49	-	-	-	-
TW-86					853.10			-	-	-
	2/3/2018	-	5.48	-		847.62	-	-	-	-
TW-87					852.25			-	-	-
	2/3/2018	-	5.13	-		847.12	-	-	-	-
TW-94					840.58			-	-	-
	2/3/2018	-	-	-		840.58	-	-	-	-
TW-96					840.40			-	-	-
	2/3/2018	-	-	-		840.40	-	-	-	-

Notes:

[1.] Elevation of zero mark (ft amsl) for surface water staff gauges.

[2.] "RS-" and "RT-" features were trimmed to less than 12 inches above ground surface on 3/14/2017. Only the resurveyed top of casing elevation after trimming is displayed. Groundwater elevation calculations are based on the true top of casing elevation at the time of gauging.

[3.] Calculated based on an oil:water density ratio of 0.73.

Bold indicates the gauged product thickness was greater than 0.5 foot.

- = not applicable

amsl = above mean sea level

BTOC = below top of casing

DRY = well contained no measurable water or product

ft = feet

ID = identification

NM = not measured

The following features are no longer reliable for calculating groundwater elevation:

- RS-19 was damaged on or about January 20, 2017.
- RT-2H was covered over on or about January 17, 2017, due to construction efforts in the vicinity.
- TW-46 was damaged on or about December 8, 2016.

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-01	MW-01-072715			7/27/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-01-012716			1/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-01-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-01-090717			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-01-120517	12/4/2017	9.85	12/5/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-01B	MW-01B-080415			8/4/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-01B-012716			1/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-01B-120116			12/1/2016	µg/L	1 U	1 U	**1.4**	**5.6**	1 U	1 U	**1.3**	--
	MW-01B-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-01B-062817-FD			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-01B-090717			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-01B-120517	12/4/2017	10.24	12/5/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-02	MW-02-072715			7/27/2015	µg/L	**4,320**	625 U	**9,670**	**2,460**	5 U[b]	**171**	**74.7**	0.02 U
	MW-02-012616			1/26/2016	µg/L	**9,500**	**1,160**	**25,000**	**6,310**	50 U[b]	**285**	**139**	0.019 U
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-02-062917			6/29/2017	µg/L	**8,040**	**833**	**27,100**	**9,890**	250 U[b]	250 U[b]	1,250 U[b]	--
	MW-02-090817			9/8/2017	µg/L	**2,340**	**181**	**7,120**	**8,510**	50 U[b]	50 U[b]	**389**	--
	MW-02-100417	10/3/2017	16.03	10/4/2017	µg/L	**3,510**	**306**	**11,900**	**11,200**	50 U[b]	**53.9**	250 U[b]	--
	MW-02-110817	11/7/2017	4.20	11/8/2017	µg/L	**850**	100 U	**1,370**	**3,520**	100 U[b]	100 U[b]	500 U[b]	--
	MW-02-120717	12/4/2017	2.54	12/7/2017	µg/L	**153**	**15.1**	**313**	**441**	1 U	**70.9**	**12.8**	--
	MW-02-010918	1/8/2018	14.26	1/9/2018	µg/L	**307**	10 U	**878**	**1,300**	10 U[b]	**61.8**	**63.7**	--
MW-02B	MW-02B-080415			8/4/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-02B-D-080415			8/4/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-02B-030116			3/1/2016	µg/L	1 U	1 U	**4.8**	**4.6**	1 U	1 U	1 U	0.019 U
	MW-02B-D-030116			3/1/2016	µg/L	1 U	1 U	**4.8**	**5.3**	1 U	1 U	1 U	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-02B-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-02B-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-02B-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-02B-120717	12/4/2017	24.56	12/7/2017	µg/L	1 U	1 U	**1.11**	3 U	1 U	1 U	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-03	MW-03-072715			7/27/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-03-012516			1/25/2016	µg/L	**108**	**20.1**	**958**	**598**	1 U	1 U	**11.1**	0.02 U
	MW-03-120616			12/6/2016	µg/L	**61.1**	**25.1**	**229**	**330**	2 U	2 U	**3.6**	--
	MW-03-062917			6/29/2017	µg/L	**10.9**	1 U	**24.6**	**6.98**	1 U	**2.34**	5 U	--
	--			9/5/2017	--	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS	NS-HS
	--	10/3/2017	19.87	10/3/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-03-110817	11/7/2017	--*	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-03-120517	12/4/2017	18.00	12/5/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	--	1/8/2018	19.98	1/8/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-04	MW-04-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	MW-04-012516			1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-04-120616			12/6/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-04-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-04-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-04-090817-DUP			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-04-120717	12/4/2017	10.07	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-05	MW-05-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	MW-05-012516			1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-05-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-100417	10/3/2017	17.03	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-110817	11/7/2017	17.18	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-120717	12/4/2017	16.55	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-05-010918	1/8/2018	16.57	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-06	MW-06-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-06-012116			1/21/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-06-120216			12/2/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-06-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-06-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-06	MW-06-120717	12/4/2017	15.45	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-06B	MW-06B-120717	12/4/2017	16.14	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-06B-D-120717	12/4/2017	16.14	12/7/2017	µg/L	1 U	1 U	**1.82**	3 U	1 U	1 U	5 U	--
MW-07	--			7/27/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-07-012116			1/21/2016	µg/L	**1,060**	**389**	**5,210**	**2,620**	40 U[b]	40 U[b]	40 U[b]	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-07-062917			6/29/2017	µg/L	**4,290**	**629**	**17,700**	**4,990**	250 U[b]	250 U[b]	1,250 U[b]	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/3/2017	13.20	10/3/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/7/2017	13.20	11/7/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	13.21	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/8/2018	13.21	1/8/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-08	MW-08-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-08-012616			1/26/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-08-120616			12/6/2016	µg/L	1 U	1 U	**14.4**	**7.1**	1 U	1 U	1 U	--
	MW-08-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-08-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-08-120717	12/4/2017	10.47	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-09	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-09-062917			6/29/2017	µg/L	**3,860**	**517**	**13,000**	**8,680**	200 U[b]	200 U[b]	1,000 U[b]	--
	--			9/5/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-09-120717	12/4/2017	3.05	12/7/2017	µg/L	**54.3**	**3.44**	**19.6**	**64.8**	1 U	**27.5**	5 U	--
MW-09B	MW-09B-120717	12/4/2017	9.15	12/7/2017	µg/L	**21.8**	**24.7**	**82.1**	**179**	1 U	**4.72**	**11.9**	--
MW-10	MW-10-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	MW-10-012616			1/26/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-10-120616			12/6/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-10-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-050317-FD			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-10	MW-10-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-100417	10/3/2017	17.33	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-110817	11/7/2017	12.64	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-120717	12/4/2017	10.85	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-10-010918	1/8/2018	15.08	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-11	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-11-012616			1/26/2016	µg/L	**10,600**	**948**	**24,400**	**4,700**	10 U[b]	**432**	**123**	0.019 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-11-062817			6/28/2017	µg/L	**10,900**	**2,140**	**29,600**	**11,700**	100 U[b]	**147**	500 U[b]	--
	--			9/5/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	12/4/2017	29.86	12/4/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
MW-12	MW-12-072815			7/28/2015	µg/L	**51.3**	5 U	**22.9**	**39.2**	5 U[b]	5 U	5 U	0.02 U
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/13/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/20/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/31/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			4/6/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-12-062817			6/28/2017	µg/L	**1,190**	**467**	**7,910**	**5,100**	50 U[b]	50 U[b]	250 U[b]	--
	MW-12-090817			9/8/2017	µg/L	**648**	**436**	**3,470**	**4,440**	100 U[b]	100 U[b]	500 U[b]	--
	MW-12-120617	12/4/2017	15.55	12/6/2017	µg/L	**367**	**137**	**1,540**	**4,660**	10 U[b]	10 U	**54.4**	--
MW-12B	MW-12B-012616			1/26/2016	µg/L	**228**	**31.4**	**193**	**532**	1 U	**5.4**	**14.6**	0.019 U
	MW-12B-113016			11/30/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-12B-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-12B-031417-FD			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-12B-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-12B-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-12B-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-12B-062817			6/28/2017	µg/L	**30.1**	1 U	**7.28**	**14.3**	1 U	**11.8**	5 U	--
	MW-12B-090817			9/8/2017	µg/L	**126**	**3.81**	**16.8**	**256**	1 U	1 U	**12**	--
	MW-12B-120617	12/4/2017	16.12	12/6/2017	µg/L	**1.01**	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-13	--			7/27/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-13-012816			1/28/2016	µg/L	**2**	1 U	**12.5**	**6.9**	1 U	1 U	1 U	0.02 U

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-13	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-13-062917			6/29/2017	µg/L	**1.18**	1 U	**3.39**	3 U	1 U	1 U	5 U	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	21.87	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-13B	MW-13B-012816			1/28/2016	µg/L	**367**	1 U	**5.6**	**59.5**	1 U	**119**	1 U	0.02 U
	MW-13B-D-012816			1/28/2016	µg/L	**405**	1 U	**6.1**	**59.1**	1 U	**108**	1 U	0.02 U
	MW-13B-113016			11/30/2016	µg/L	**550**	**5.1**	**21.2**	**140**	5 U[b]	**158**	**7.9**	--
	MW-13B-062817			6/28/2017	µg/L	**308**	**3.09**	**10.3**	**103**	1 U	**121**	**5.13**	--
	MW-13B-090817			9/8/2017	--	NS-SL	NS-SL	NS-SL	NS-SL	NS-SL	NS-SL	NS-SL	NS-SL
	MW-13B-110817	11/7/2017	23.08	11/8/2017	µg/L	**325**	**3.42**	**19**	**91.6**	1 U	**173**	**5.55**	--
	MW-13B-D-110817	11/7/2017	23.08	11/8/2017	µg/L	**356**	**3.85**	**20.8**	**100**	1 U	**168**	**6.61**	--
	MW-13B-120617	12/4/2017	22.66	12/6/2017	µg/L	**269**	**3.97**	**24.4**	**100**	1 U	**140**	**8.83**	--
MW-14	MW-14-072815			7/28/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-14-012816			1/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-14-113016			11/30/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-14-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-14-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-14-120617	12/4/2017	17.62	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-14B	MW-14B-052516			5/25/2016	µg/L	**5**	1 U	1 U	**4.4**	1 U	**17.2**	1 U	0.02 U
	MW-14B-052516-FD			5/25/2016	µg/L	**4.6**	1 U	1 U	**4.1**	1 U	**23.6**	1 U	0.02 U
	MW-14B-113016			11/30/2016	µg/L	**10.5**	1 U	**1.1**	**5.5**	1 U	**19.7**	1 U	--
	MW-14B-062817			6/28/2017	µg/L	**38.1**	**1.34**	**2.56**	**19.1**	1 U	**36.2**	5 U	--
	MW-14B-090817			9/8/2017	µg/L	**6.81**	1 U	1 U	**6.67**	1 U	**18.7**	5 U	--
	MW-14B-120617	12/4/2017	19.22	12/6/2017	µg/L	**8.82**	1 U	1 U	**6.91**	1 U	**24.4**	5 U	--
MW-15	MW-15-080415			8/4/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	MW-15-012816			1/28/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-15-120716			12/7/2016	µg/L	**3,680**	**139**	**422**	**2,280**	25 U[b]	**188**	**43.8**	--
	MW-15-031417			3/14/2017	µg/L	**1,960**	**72**	**324**	**1,320**	25 U[b]	**161**	125 U[b]	--
	MW-15-031417-FD			3/14/2017	µg/L	**1,820**	**61**	**286**	**1,120**	25 U[b]	**153**	125 U[b]	--
	MW-15-032017			3/20/2017	µg/L	**3,390**	**103**	**505**	**2,460**	50 U[b]	**194**	250 U[b]	--
	MW-15-033117			3/31/2017	µg/L	**2,850**	**65.4**	**444**	**1,860**	20 U[b]	**221**	100 U[b]	--
	MW-15-040617			4/6/2017	µg/L	**1,790**	**60.6**	**465**	**886**	25 U[b]	**181**	125 U[b]	--
	MW-15-062817			6/28/2017	µg/L	**73**	25 U	**29**	**110**	25 U[b]	**91.8**	125 U[b]	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-15	MW-15-090817			9/8/2017	µg/L	**454**	**24**	**567**	**338**	5 U[b]	**193**	25 U[b]	--
	MW-15-120617	12/4/2017	13.66	12/6/2017	µg/L	1 U	1 U	**2**	**5**	1 U	**140**	5 U	--
MW-15B	MW-15B-080415			8/4/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.019 U
	MW-15B-012816			1/28/2016	µg/L	**4.8**	1 U	**2**	**3.9**	1 U	1 U	1 U	0.02 U
	MW-15B-113016			11/30/2016	µg/L	**337**	**34**	**565**	**194**	5 U[b]	**26.7**	**5**	--
	MW-15B-031417			3/14/2017	µg/L	**2,160**	**248**	**4,580**	**1,500**	100 U[b]	**118**	500 U[b]	--
	MW-15B-032017			3/20/2017	µg/L	**615**	**88.6**	**1,270**	**555**	25 U[b]	**67.5**	125 U[b]	--
	MW-15B-033117			3/31/2017	µg/L	**1,630**	**205**	**3,240**	**1,180**	50 U[b]	**115**	250 U[b]	--
	MW-15B-040617			4/6/2017	µg/L	**1,020**	**132**	**2,020**	**789**	25 U[b]	**84.7**	125 U[b]	--
	MW-15B-040617-FD			4/6/2017	µg/L	**973**	**124**	**1,910**	**742**	25 U[b]	**82.9**	125 U[b]	--
	MW-15B-062817			6/28/2017	µg/L	**1,510**	**145**	**3,520**	**1,280**	100 U[b]	100 U[b]	500 U[b]	--
	MW-15B-090817			9/8/2017	µg/L	**1,820**	**164**	**3,560**	**1,210**	50 U[b]	**133**	250 U[b]	--
	MW-15B-120617	12/4/2017	16.25	12/6/2017	µg/L	**1,760**	**239**	**3,630**	**1,380**	1 U	**135**	**37.6**	--
	MW-15B-D-120617	12/4/2017	16.25	12/6/2017	µg/L	**491**	**56**	**1,050**	**408**	1 U	**117**	**35.4**	--
MW-16	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-16-062917			6/29/2017	µg/L	**12,900**	**1,770**	**36,400**	**12,500**	500 U[b]	**1,740**	2,500 U[b]	--
	--			9/5/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	12/4/2017	7.00	12/7/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
MW-17	--			7/27/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/31/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			4/6/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			6/26/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	10.85	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-17B	MW-17B-030116			3/1/2016	µg/L	**6,480**	**488**	**11,900**	**2,870**	**5**	**742**	**104**	0.019 U
	MW-17B-120116			12/1/2016	µg/L	**9,370**	**761**	**16,900**	**4,500**	100 U[b]	**954**	**112**	--
	MW-17B-031317			3/13/2017	µg/L	**7,350**	**770**	**14,100**	**4,510**	200 U[b]	**944**	1,000 U[b]	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-17B	MW-17B-032017			3/20/2017	µg/L	**10,700**	**1,360**	**21,400**	**7,910**	**323**	**1,210**	1,000 U[b]	--
	MW-17B-033117			3/31/2017	µg/L	**9,190**	**900**	**17,500**	**5,910**	100 U[b]	**1,200**	500 U[b]	
	MW-17B-033117FD			3/31/2017	µg/L	**9,190**	**956**	**18,200**	**6,330**	100 U[b]	**1,210**	500 U[b]	--
	MW-17B-040617			4/6/2017	µg/L	**7,780**	**833**	**14,900**	**5,330**	200 U[b]	**991**	1,000 U[b]	--
	MW-17B-062817			6/28/2017	µg/L	**11,200**	**704**	**21,600**	**5,650**	200 U[b]	**1,150**	1,000 U[b]	--
	MW-17-090817			9/8/2017	µg/L	**11,400**	**1,240**	**23,900**	**8,460**	20 U[b]	**1,330**	**201**	--
	MW-17B-120717	12/4/2017	17.05	12/7/2017	µg/L	**10,600**	**1,060**	**14,900**	**9,210**	10 U[b]	**1,140**	**178**	--
MW-18	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			6/26/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			9/5/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	12/4/2017	11.64	12/4/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
MW-19	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	MW-19-012116			1/21/2016	µg/L	**22.8**	**18.5**	**256**	**437**	1 U	1 U	**10.7**	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
				3/31/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-19-040617			4/6/2017	µg/L	**9,810**	**1,030**	**25,000**	**10,300**	250 U[b]	250 U[b]	1,250 U[b]	--
	MW-19-062917			6/29/2017	µg/L	**9,410**	**683**	**27,200**	**9,580**	200 U[b]	**320**	1,000 U[b]	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	11.77	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-20	--			7/27/2015	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			1/19/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			11/28/2016	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/13/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/20/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			3/31/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			4/6/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			5/4/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			6/26/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			7/17/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-20	--			8/1/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--			9/5/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	10/3/2017	13.79	10/4/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	11/7/2017	13.61	11/8/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	12/4/2017	14.64	12/4/2017	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
	--	1/8/2018	14.04	1/8/2018	--	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP	NS-FP
MW-21	MW-21-072715			7/27/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-21-012116			1/21/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-21-D-012116			1/21/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-21-112916			11/29/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-21-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-032117			3/21/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-062817-FD			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-21-120717	12/4/2017	17.42	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-22	--			7/27/2015	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-22-012116			1/21/2016	µg/L	**19.8**	**3.4**	**47.2**	**37.4**	1 U	1 U	1 U	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			5/3/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-22-062917			6/29/2017	µg/L	**234**	10 U	**125**	30 U	10 U[b]	10 U	50 U[b]	--
	--			7/17/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			8/1/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/3/2017	9.94	10/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/7/2017	9.96	11/8/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	9.99	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/8/2018	10.01	1/8/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-23	MW-23-072715			7/27/2015	µg/L	5 U[b]	5 U	**7.5**	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-23D-072715			7/27/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-23-012016			1/20/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-23	MW-23-120216			12/2/2016	µg/L	**450**	5 U	**14.6**	**336**	5 U[b]	**46.4**	**5.9**	--
	MW-23-031317			3/13/2017	µg/L	**709**	5 U	**23.1**	**548**	5 U[b]	**127**	25 U[b]	--
	MW-23-032017			3/20/2017	µg/L	**642**	10 U	**12.7**	**579**	10 U[b]	**108**	50 U[b]	--
	MW-23-032017-FD			3/20/2017	µg/L	**620**	10 U	**12.0**	**548**	10 U[b]	**110**	50 U[b]	--
	MW-23-033117			3/31/2017	µg/L	**685**	10 U	**16.5**	**624**	10 U[b]	**130**	50 U[b]	--
	MW-23-040617			4/6/2017	µg/L	**432**	1 U	**6.6**	**254**	1 U	**76.5**	5 U	--
	MW-23-062817			6/28/2017	µg/L	**131**	10 U	10 U	**117**	10 U[b]	**19.1**	5 U	--
	MW-23-071717			7/17/2017	µg/L	**1.2**	1 U	1 U	3 U	1 U	**1** U	5 U	--
	MW-23-080117			8/1/2017	µg/L	**132**	1 U	**6.2**	**252**	1 U	**48.1**	5 U	--
	MW-23-090717			9/7/2017	µg/L	**1,110**	**9.25**	**43.1**	**999**	5 U[b]	**141**	25 U[b]	--
	MW-23-100417	10/3/2017	11.52	10/4/2017	µg/L	**703**	10 U	**17.5**	**515**	10 U[b]	**90.1**	50 U[b]	--
	MW-23-100417-DUP	10/3/2017	11.52	10/4/2017	µg/L	**543**	**2.65**	**11.5**	**424**	1 U	**69.2**	5 U	--
	MW-23-110817	11/7/2017	11.10	11/8/2017	µg/L	**788**	10 U	**21.5**	**580**	10 U[b]	**118**	50 U[b]	--
	MW-23-120617	12/4/2017	11.13	12/6/2017	µg/L	**693**	10 U	**17.0**	**408**	10 U[b]	**99.5**	50 U[b]	--
	MW-23-010918	1/8/2018	11.02	1/9/2018	µg/L	**127**	10 U	10 U	**137**	10 U[b]	**69.6**	50 U[b]	--
MW-23B	MW-23B-080515			8/5/2015	µg/L	5 U[b]	5 U	**7.0**	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-23B-012016			1/20/2016	µg/L	1 U	1 U	**3.9**	**7.1**	1 U	1 U	1 U	0.02 U
	MW-23B-120216			12/2/2016	µg/L	1 U	**1.4**	**3.5**	**11.0**	1 U	1 U	**1.3**	--
	MW-23B-031317			3/13/2017	µg/L	1 U	**1.11**	**2.63**	**8.86**	1 U	1 U	5 U	--
	MW-23B-032017			3/20/2017	µg/L	1 U	**1.55**	**2.98**	**11.7**	1 U	1 U	5 U	--
	MW-23B-033117			3/31/2017	µg/L	1 U	**1.24**	**2.41**	**8.86**	1 U	1 U	5 U	--
	MW-23B-040617			4/6/2017	µg/L	1 U	**1.21**	**2.41**	**9.23**	1 U	1 U	5 U	--
	MW-23B-062817			6/28/2017	µg/L	1 U	1 U	**1.73**	**6.20**	1 U	1 U	5 U	--
	MW-23B-090717			9/7/2017	µg/L	1 U	1 U	**1.65**	**5.40**	1 U	1 U	5 U	--
	MW-23B-120617	12/4/2017	11.45	12/6/2017	µg/L	1 U	**1.2**	**2.48**	**7.93**	1 U	1 U	5 U	--
MW-24	MW-24-080515			8/5/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-24-012616			1/26/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-24-120716			12/7/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-24-062817			6/28/2017	µg/L	**28.8**	**3.96**	**1.7**	**22.2**	1 U	1 U	5 U	--
	MW-24-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-24-120617	12/4/2017	4.51	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-24B	MW-24B-080515			8/5/2015	µg/L	5 U[b]	5 U	5 U	10 U	5 U[b]	5 U	5 U	0.02 U
	MW-24B-012616			1/26/2016	µg/L	1 U	1 U	**3.3**	**6.8**	1 U	1 U	1 U	0.019 U

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-24B	MW-24B-120716			12/7/2016	µg/L	1 U	1 U	**2.9**	**1.6**	1 U	1 U	1 U	--
	MW-24B-062817			6/28/2017	µg/L	**28.9**	**3.89**	**1.77**	**20.7**	1 U	1 U	5 U	--
	MW-24B-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-24B-120617	12/4/2017	5.69	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-25	MW-25-012716			1/27/2016	µg/L	**101**	1 U	1 U	**115**	1 U	1 U	**1.8**	0.02 U
	MW-25-012716			12/1/2016	µg/L	**675**	**30.2**	**15.3**	**619**	5 U[b]	**5.9**	**29.7**	--
	MW-25-031417			3/14/2017	µg/L	**627**	**28.6**	**10.1**	**668**	10 U[b]	10 U	50 U[b]	--
	MW-25-032017			3/20/2017	µg/L	**604**	**20.4**	20 U	**680**	20 U[b]	20 U	100 U[b]	--
	MW-25-033117			3/31/2017	µg/L	**673**	**30.1**	**12**	**736**	10 U[b]	10 U	50 U[b]	--
	MW-25-033117FD			3/31/2017	µg/L	**790**	**35.4**	**12.5**	**861**	10 U[b]	10 U	50 U[b]	--
	MW-25-040617			4/6/2017	µg/L	**558**	**24.3**	10 U	**682**	10 U[b]	10 U	50 U[b]	--
	MW-25-050317			5/3/2017	µg/L	**519**	**49.3**	**10.1**	**614**	1 U	1 U	**43.2**	--
	MW-25-062817			6/28/2017	µg/L	**431**	**34.8**	10 U	**520**	10 U[b]	10 U	50 U[b]	--
	MW-25-071717			7/17/2017	µg/L	**230**	**13.4**	10 U	**264**	10 U[b]	10 U	50 U[b]	--
	MW-25-080117			8/1/2017	µg/L	**234**	**14.4**	10 U	**277**	10 U[b]	10 U	50 U[b]	--
	MW-25-090817			9/8/2017	µg/L	**200**	**12.2**	**1.27**	**214**	1 U	1 U	**10.6**	--
	MW-25-100417	10/3/2017	8.52	10/4/2017	µg/L	**173**	**16.2**	**1.73**	**276**	1 U	**1.1**	**6.77**	--
	MW-25-110817	11/7/2017	8.35	11/8/2017	µg/L	**82.9**	**7.21**	1 U	**143**	1 U	1 U	**7.74**	--
	MW-25-120617	12/4/2017	7.10	12/6/2017	µg/L	**23.8**	**1.84**	1 U	**60.5**	1 U	1 U	5 U	--
	MW-25-010918	1/8/2018	8.8	1/9/2018	µg/L	**72**	**2.74**	1 U	**111**	1 U	1 U	5 U	--
MW-25B	MW-25B-012716			1/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-25B-120116			12/1/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-25B-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-090817-DUP			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-25B-120617	12/4/2017	5.30	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-26	MW-26-012016			1/20/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	MW-26-120116			12/1/2016	µg/L	1 U	1 U	**2.3**	1 U	1 U	1 U	1 U	--
	MW-26-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-26	MW-26-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-040617-FD			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-090717			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-100417	10/3/2017	7.71	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-110817	11/7/2017	6.56	11/8/2017	µg/L	1 U	1 U	**1.17**	3 U	1 U	1 U	5 U	--
	MW-26-120617	12/4/2017	6.83	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26-010918	1/8/2018	6.68	1/9/2018	µg/L	1 U	**1.79**	**6.2**	**13.8**	1 U	1 U	5 U	--
MW-26B	MW-26B-012016			1/20/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-26B-120116			12/1/2016	µg/L	1 U	1 U	1 U	**1.3**	1 U	1 U	1 U	--
	MW-26B-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-090717			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-090717-DUP			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-26B-120617	12/4/2017	9.17	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-27	MW-27-012716			1/27/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.019 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-27-062817			6/28/2017	µg/L	**2.69**	**4.06**	**3.88**	**35.9**	1 U	1 U	5 U	--
	MW-27-090817			9/8/2017	µg/L	**4.96**	**5.75**	**2.13**	**14.8**	1 U	1 U	5 U	--
	MW-27-120517	12/4/2017	27.46	12/5/2017	µg/L	**6.48**	**8.23**	**12.5**	**20.5**	1 U	1 U	5 U	--
MW-27B	MW-27B-051216			5/12/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-27B-120216			12/2/2016	µg/L	1 U	**5.3**	**9.1**	**45.7**	1 U	1 U	**8.9**	--
	MW-27B-062817			6/28/2017	µg/L	1 U	**4.04**	**4.04**	**32.7**	1 U	1 U	**6.09**	--
	MW-27B-090717			9/7/2017	µg/L	1 U	**3.73**	**6.35**	**30.3**	1 U	1 U	**7.54**	--
	MW-27B-120517	12/4/2017	30.70	12/5/2017	µg/L	1 U	**3.1**	**5.91**	**24.8**	1 U	1 U	**5.81**	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-27B	MW-27B-D-120517	12/4/2017	30.70	12/5/2017	µg/L	1 U	**3.96**	**7.24**	**31.6**	1 U	1 U	**7.09**	--
MW-28	MW-28-012716			1/27/2016	µg/L	**542**	**430**	**3,850**	**3,370**	1 U	**4.8**	**96.3**	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-28-031517			3/15/2017	µg/L	**1,120**	**68.9**	**3,350**	**1,370**	50 U[b]	50 U[b]	250 U	--
	--			3/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/31/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			4/6/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-28-050317			5/3/2017	µg/L	**65.9**	**14.5**	**263**	**1,010**	1 U	**2.94**	**9.33**	--
	MW-28-062817			6/28/2017	µg/L	**199**	**55**	**108**	**546**	1 U	1 U	**10.1**	--
	MW-28-071717			7/17/2017	µg/L	**219**	**64.2**	**85.8**	**422**	1 U	1 U	**14.7**	--
	MW-28-080217			8/2/2017	µg/L	**219**	**48.7**	**52.7**	**187**	1 U	**3.46**	**11.9**	--
	MW-28-090817			9/8/2017	µg/L	**130**	**16.2**	**175**	**388**	1 U	**4.77**	**13.6**	--
	--	10/3/2017	23.80	10/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/7/2017	23.78	11/7/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	23.94	12/7/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/8/2018	24.15	1/9/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-29	MW-29-012116			1/21/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	MW-29-112916			11/29/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-29-031317			3/13/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-090717			9/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-100417	10/3/2017	10.85	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-110817	11/7/2017	10.06	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-120617	12/4/2017	10.39	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-29-010918	1/8/2018	10.36	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-30	MW-30-012516			1/25/2016	µg/L	1 U	1 U	1 U	2 U	1 U	1 U	1 U	0.02 U
	--			11/28/2016	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-30	MW-30-050417			5/4/2017	µg/L	**104**	**3.98**	**341**	**161**	1 U	1 U	5 U	--
	MW-30-062917			6/29/2017	µg/L	**646**	25 U	**1,630**	**736**	25 U[b]	25 U	125 U[b]	--
	MW-30-071717			7/17/2017	µg/L	**922**	25 U	**2,050**	**1,320**	25 U[b]	25 U	125 U[b]	--
	MW-30-080217			8/2/2017	µg/L	**1,240**	**25.9**	**1,020**	**2,230**	25 U[b]	25 U	125 U[b]	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/3/2017	14.58	10/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/7/2017	14.60	11/8/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	14.47	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/8/2018	14.59	1/8/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-31	MW-31-051016			5/10/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-31-112916			11/29/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-31-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-D-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-100417	10/3/2017	22.70	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-110817	11/7/2017	20.81	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-120617	12/4/2017	20.05	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-31-010918	1/8/2018	22.55	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-31B	MW-31B-051116			5/11/2016	µg/L	1 U	1 U	**2.7**	1 U	1 U	1 U	1 U	0.02 U
MW-32	MW-32-051016			5/10/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-32-120616			12/6/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-32-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-32-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-32-120717	12/4/2017	10.02	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-33	MW-33-051016			5/10/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
MW-33T	MW-33T-051016			5/10/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-33T-120617	12/4/2017	27.12	12/6/2017	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
MW-34	MW-34-031517			3/15/2017	--	**978**	**33.0**	**143**	**218**	10 U[b]	**157**	50 U[b]	--
	MW-34-032017			3/20/2017	µg/L	**801**	10.0 U	**113**	**305**	10 U[b]	**149**	50 U[b]	--
	MW-34-033117			3/31/2017	µg/L	**728**	10.0 U	**81.4**	**224**	10 U[b]	**152**	50 U[b]	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-34	MW-34-040617			4/6/2017	µg/L	**860**	**1.7**	**58.6**	**181**	1 U	**123**	5 U	--
	MW-34-050317			5/3/2017	µg/L	**287**	**2.62**	**27.2**	**130**	1 U	**124**	5 U	--
	MW-34-062817			6/28/2017	µg/L	**167**	**4.59**	**9.3**	**39.2**	1 U	**68.3**	5 U	--
	MW-34-071717			7/17/2017	µg/L	**137**	**5.83**	**19.8**	**69.5**	1 U	**73.8**	5 U	--
	MW-34-080117			8/1/2017	µg/L	**517**	10 U	**31.7**	**110**	10 U[b]	**98.3**	50 U[b]	--
	MW-34-090817			9/8/2017	µg/L	**1,430**	**6.01**	**98.0**	**264**	1 U	**191**	**7.33**	--
	MW-34-100417	10/3/2017	2.76	10/4/2017	µg/L	**919**	10 U	**36.8**	**157**	10 U[b]	**151**	50 U[b]	--
	MW-34-100417-DUP	10/3/2017	2.76	10/4/2017	µg/L	**846**	**1.49**	**40.8**	**186**	1 U	**148**	5 U	--
	MW-34-110817	11/7/2017	2.48	11/8/2017	µg/L	**338**	10 U	**15.3**	**140**	10 U[b]	**266**	50 U[b]	--
	MW-34-120617	12/4/2017	2.52	12/6/2017	µg/L	**169**	10 U	**29.7**	**70**	10 U[b]	**218**	50 U[b]	--
	MW-34-010918	1/8/2018	2.48	1/9/2018	µg/L	**147**	10 U	**13.1**	**80**	10 U[b]	**246**	50 U[b]	--
MW-35	MW-35-051016			5/10/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-35-120116			12/1/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-35-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-100417	10/3/2017	10.34	10/4/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-110817	11/7/2017	8.94	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-120617	12/4/2017	10.41	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-010918	1/8/2018	10.57	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-35-D-010918	1/8/2018	10.57	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-36	MW-36-051116			5/11/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.02 U
	MW-36-112916			11/29/2016	µg/L	**1.3**	1 U	**6.5**	**1.1**	1 U	1 U	1 U	--
	MW-36-D-112916			11/29/2016	µg/L	1 U	1 U	**5.4**	1 U	1 U	1 U	1 U	--
	MW-36-062917			6/29/2017	µg/L	**2.11**	1 U	**2.28**	3 U	1 U	1 U	5 U	--
	MW-36-090817			9/8/2017	µg/L	**4.75**	1 U	**6.16**	**4.62**	1 U	1 U	5 U	--
	MW-36-120717	12/4/2017	20.14	12/7/2017	µg/L	**17.5**	1 U	**30.2**	**14.4**	1 U	1 U	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-36B	MW-36B-051116			5/11/2016	µg/L	1 U	1 U	**7.2**	1 U	1 U	1 U	1 U	0.02 U
	MW-36B-112916			11/29/2016	µg/L	1 U	1 U	**1.6**	1 U	1 U	1 U	1 U	--
	MW-36B-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-36B-062917-FD			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-36B-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-36B-120717	12/4/2017	20.90	12/7/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-37	MW-37-113016			11/30/2016	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	--
	MW-37-062817			6/28/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**1.44**	5 U	--
	MW-37-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**1.5**	5 U	--
	MW-37-120617	12/4/2017	3.47	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**2.93**	5 U	--
MW-38	MW-38-113016			11/30/2016	µg/L	1 U	1 U	1 U	1 U	1 U	**5.5**	1 U	--
	MW-38-031417			3/14/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**9.14**	5 U	--
	MW-38-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**7.55**	5 U	--
	MW-38-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**10.2**	5 U	--
	MW-38-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**8.06**	5 U	--
	MW-38-050317			5/3/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**9.08**	5 U	--
	MW-38-062817			6/28/2017	µg/L	**9.71**	**1.17**	1 U	**6.63**	1 U	1 U	5 U	--
	MW-38-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**8.59**	5 U	--
	MW-38-071717-FD			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**9.78**	5 U	--
	MW-38-080117			8/1/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**7.25**	5 U	--
	MW-38-090817			9/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**12.9**	5 U	--
	MW-38-100417	10/3/2017	2.23	10/4/2017	µg/L	**1.75**	1 U	1 U	3 U	1 U	**11.2**	5 U	--
	MW-38-110817	11/7/2017	1.88	11/8/2017	µg/L	**4.48**	1 U	1 U	**12.4**	1 U	**29.2**	5 U	--
	MW-38-120617	12/4/2017	2.01	12/6/2017	µg/L	**102**	1 U	1 U	**86.1**	1 U	**38**	5 U	--
	MW-38-010918	1/8/2018	1.95	1/9/2018	µg/L	**311**	1 U	**2.31**	**158**	1 U	**49.4**	5 U	--
MW-39	MW-39-120716			12/7/2016	µg/L	**6,320**	**682**	**1,290**	**3,650**	50 U[b]	**311**	**86**	--
	MW-39-031417			3/14/2017	µg/L	**6,370**	**431**	**2,200**	**3,700**	10 U[b]	**199**	**117**	--
	MW-39-032017			3/20/2017	µg/L	**7,340**	**704**	**2,990**	**4,050**	100 U[b]	**248**	500 U[b]	--
	MW-39-033117			3/31/2017	µg/L	**7,540**	**899**	**3,140**	**4,400**	50 U[b]	**272**	250 U[b]	--
	MW-39-040617			4/6/2017	µg/L	**6,180**	**754**	**3,280**	**3,860**	50 U[b]	**257**	250 U[b]	--
	MW-39-062817			6/28/2017	µg/L	**5,470**	**58**	**3,360**	**3,900**	20 U[b]	**239**	100 U[b]	--
	MW-39-071717			7/17/2017	µg/L	**4,690**	100 U	**3,760**	**4,580**	100 U[b]	**344**	500 U[b]	--
	MW-39-080117			8/1/2017	µg/L	**4,630**	100 U	**2,880**	**4,740**	100 U[b]	**348**	500 U[b]	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-39	MW-39-090817			9/8/2017	µg/L	**3,380**	**10.7**	**1,040**	**2,740**	1 U	**376**	**15.6**	--
	MW-39-100417	10/3/2017	3.75	10/4/2017	µg/L	**1,560**	50 U	**365**	**1,350**	50 U[b]	**305**	250 U[b]	--
	MW-39-110817	11/7/2017	4.89	11/8/2017	µg/L	**878**	50 U	**123**	**368**	50 U[b]	**442**	250 U[b]	--
	MW-39-120617	12/4/2017	5.72	12/6/2017	µg/L	**345**	50 U	**69**	**150**	50 U[b]	**355**	250 U[b]	--
	MW-39-D-120617	12/4/2017	5.72	12/6/2017	µg/L	**286**	1 U	**31**	**131**	1 U	**353**	5 U	--
	MW-39-010918	1/8/2018	4.86	1/9/2018	µg/L	**23.8**	5 U	5 U	15 U	5 U	**370**	25 U	--
MW-40	MW-40-120716			12/7/2016	µg/L	**6,730**	**588**	**7,460**	**3,390**	50 U[b]	**373**	**64.8**	--
	MW-40-031417			3/14/2017	µg/L	**11,600**	**1,280**	**16,100**	**7,260**	50 U[b]	**691**	250 U[b]	--
	MW-40-032017			3/20/2017	µg/L	**12,300**	**1,330**	**19,600**	**7,500**	200 U[b]	**654**	1,000 U[b]	--
	MW-40-033117			3/31/2017	µg/L	**13,300**	**1,500**	**19,500**	**8,070**	100 U[b]	**727**	500 U[b]	--
	MW-40-040617			4/6/2017	µg/L	**10,400**	**1,180**	**16,200**	**6,570**	200 U[b]	**650**	1,000 U[b]	--
	MW-40-062817			6/28/2017	µg/L	**9,250**	**1,030**	**19,200**	**6,540**	500 U[b]	**590**	2,500 U[b]	--
	MW-40-071717			7/17/2017	µg/L	**11,400**	**1,210**	**25,300**	**7,430**	500 U[b]	**727**	2,500 U[b]	--
	MW-40-080117			8/1/2017	µg/L	**12,000**	**1,120**	**23,200**	**8,070**	500 U[b]	**631**	2,500 U[b]	--
	MW-40-090817			9/8/2017	µg/L	**14,300**	**1,250**	**28,700**	**9,250**	20 U[b]	**716**	**219**	--
	MW-40-100417	10/3/2017	1.95	10/4/2017	µg/L	**13,800**	1,000 U[b]	**28,800**	**9,530**	1,000 U[b]	1,000 U[b]	5,000 U[b]	--
	MW-40-110817	11/7/2017	2.11	11/8/2017	µg/L	**13,500**	1,000 U[b]	**23,000**	**9,290**	1,000 U[b]	1,000 U[b]	5,000 U[b]	--
	MW-40-120617	12/4/2017	3.43	12/6/2017	µg/L	**14,300**	1,000 U[b]	**22,300**	**10,100**	1,000 U[b]	1,000 U[b]	5,000 U[b]	--
	MW-40-010918	1/8/2018	2.72	1/9/2018	µg/L	**12,400**	**773**	**22,300**	**10,200**	200 U[b]	**497**	1,000 U[b]	--
MW-41	MW-41-120716			12/7/2016	µg/L	**212**	2 U	2 U	**155**	2 U	**6.7**	**5.6**	--
	MW-41-031417			3/14/2017	µg/L	**469**	**1.78**	1 U	**275**	1 U	**4.34**	**18.1**	--
	MW-41-032017			3/20/2017	µg/L	**424**	**2.62**	1 U	**342**	1 U	1 U	**16.9**	--
	MW-41-033117			3/31/2017	µg/L	**449**	5 U	5 U	**343**	5 U[b]	5 U	25 U[b]	--
	MW-41-040617			4/6/2017	µg/L	**470**	**2.06**	1 U	**258**	1 U	**3.84**	**10.6**	--
	MW-41-062817			6/28/2017	µg/L	**292**	**8.83**	**2.09**	**271**	1 U	**3.36**	**13.3**	--
	MW-41-071717			7/17/2017	µg/L	**487**	**15.8**	**3.09**	**366**	1 U	**3.62**	**27.9**	--
	MW-41-080117			8/1/2017	µg/L	**371**	10 U	10 U	**260**	10 U[b]	10 U	50 U[b]	--
	MW-41-090817			9/8/2017	µg/L	**189**	**1.51**	1 U	**90**	1 U	**3.74**	5 U	--
	MW-41-100417	10/3/2017	4.37	10/4/2017	µg/L	**93.5**	1 U	1 U	**59.9**	1 U	**1.84**	5 U	--
	MW-41-110817	11/7/2017	4.39	11/8/2017	µg/L	**99.6**	1 U	1 U	**56.6**	1 U	**2.46**	**5.68**	--
	MW-41-120617	12/4/2017	5.55	12/6/2017	µg/L	**27.6**	1 U	1 U	**11.1**	1 U	**1.62**	5 U	--
	MW-41-010918	1/8/2018	4.4	1/9/2018	µg/L	**2.06**	1 U	1 U	3 U	1 U	**1.43**	5 U	--

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-42	MW-42-120716			12/7/2016	µg/L	**3.8**	1 U	1 U	**2.7**	1 U	1 U	1 U	--
	MW-42-031417			3/14/2017	µg/L	**19.3**	1 U	1 U	3 U	1 U	**1.12**	5 U	--
	MW-42-032017			3/20/2017	µg/L	**59.6**	1 U	1 U	**16.9**	1 U	**1.24**	5 U	--
	MW-42-033117			3/31/2017	µg/L	**135**	1 U	1 U	**73.8**	1 U	1 U	**5.19**	--
	MW-42-040617			4/6/2017	µg/L	**93.5**	1 U	1 U	**53.3**	1 U	**1.18**	5 U	--
	MW-42-062817			6/28/2017	µg/L	**15.1**	1 U	1 U	**11.7**	1 U	**1.25**	5 U	--
	MW-42-090817			9/8/2017	µg/L	**143**	1 U	1 U	**100**	1 U	**1.51**	**5.52**	--
	MW-42-120617	12/4/2017	5.26	12/6/2017	µg/L	**9.82**	1 U	1 U	**45**	1 U	**1.24**	5 U	--
MW-43	MW-43-110817	11/7/2017	4.45	11/8/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-43-120617	12/4/2017	4.50	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-43-010918	1/8/2018	4.35	1/9/2018	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-43B	MW-43B-120617	12/4/2017	4.08	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-44	--			3/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-44-062917			6/29/2017	µg/L	**1.06**	1 U	**7.12**	**3.11**	1 U	1 U	5 U	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	9.40	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
MW-44B	MW-44B-031317			3/13/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-44B-062817			6/28/2017	µg/L	1 U	1 U	**2.39**	3 U	1 U	1 U	5 U	--
	MW-44B-090717			9/7/2017	µg/L	1 U	1 U	**3.07**	3 U	1 U	1 U	5 U	--
	MW-44B-120517	12/4/2017	14.32	12/5/2017	µg/L	1 U	1 U	**2.27**	3 U	1 U	1 U	5 U	--
MW-45	--			3/13/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/20/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			3/31/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			4/6/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--			5/3/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-45-062917			6/29/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45-071717			7/17/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45-080217			8/2/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	10/3/2017	14.25	10/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	11/7/2017	14.24	11/8/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	12/4/2017	14.22	12/4/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	--	1/8/2018	14.25	1/8/2018	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW

Table 6. Analytical Results for Groundwater

Plantation Pipe Line Company

Lewis Drive Remediation Site, Belton, South Carolina

Site ID #18693 "Kinder Morgan Belton Pipeline Release"

Location	Sample ID	Gauging Date	Depth to Water	Sample Date	Analyte: Units	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	Naphthalene	EDB
MW-45B	MW-45B-031317			3/13/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45B-032017			3/20/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45B-033117			3/31/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45B-040617			4/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
	MW-45B-062817			6/28/2017	µg/L	1 U	1 U	**1.73**	3 U	1 U	1 U	5 U	--
	--			9/5/2017	--	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW	NS-IW
	MW-45B-120717	12/4/2017	15.93	12/7/2017	µg/L	1 U	1 U	**3.26**	3 U	1 U	1 U	5 U	--
MW-46	MW-46-120617	12/4/2017	9.48	12/6/2017	µg/L	**4.97**	1 U	1 U	**7.74**	1 U	**85.5**	5 U	--
MW-47	MW-47-120617	12/4/2017	17.75	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-48B	MW-48B-120617	12/4/2017	18.22	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	**2.92**	5 U	--
MW-49	MW-49-120617	12/4/2017	20.29	12/6/2017	µg/L	1 U	1 U	1 U	3 U	1 U	1 U	5 U	--
MW-50B	MW-50B-120617	12/4/2017	21.37	12/6/2017	µg/L	**1.37**	1 U	1 U	3 U	1 U	**35.5**	5 U	--
RBSL[a]:					**µg/L**	5.0	700	1,000	10,000	5.0	40	25	0.05

Notes:

[a] RBSL = Risk-based screening levels identified in South Carolina Underground Storage Tank Management Division *Programmatic Quality Assurance Program Plan* , *Revision 3.1* , Table D1 "RBSLs for Groundwater," February 2016.

[b] The analyte was analyzed for, but was not detected above the laboratory reporting/quantitation limit. However, the laboratory reporting/quantitation limit is above the screening criteria. The actual absence or presence of this analyte between the screening criteria and the laboratory reporting/quantitation limit cannot be determined.

*Unable to collect depth to water due to fluctuation from the sparging system operating.

Samples analyzed by EPA Methods SW 8260B and 8011.

Bold indicates the analyte was detected above the method detection limit.

Gray shading indicates the analyte exceeded RBSLs.

µg/L = microgram(s) per liter

1,2-DCA = 1,2-dichloroethane

EDB = 1,2-dibromoethane

ID = identification

NS-FP = sample not collected due to the presence of free product in the well

NS-HS = sample not collected due to health and safety concerns

NS-IW = sample not collected due to insufficient volume of water in well

NS-SL = sample not analyzed due to sample being lost in transit to laboratory

ANALYTICAL REPORT

January 15, 2018

CH2M Hill- Kinder Morgan- Atlanta, GA

Sample Delivery Group:	L962268
Samples Received:	01/10/2018
Project Number:	699858,LD. MR. SW
Description:	Lewis Drive Surface Water
Site:	LEWIS DR.
Report To:	Bethany Garvey 6600 Peachtree Dunwoody Road 400 Embassy Row - Suite 600 Atlanta, GA 30328

Entire Report Reviewed By:

Chris McCord
Technical Service Representative

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approval of the laboratory. Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures: 060302, 060303, and 060304.

SW11-010918 L962268-01 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:10 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 03:57	01/11/18 03:57	JHH

SW10-010918 L962268-02 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:20 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 04:13	01/11/18 04:13	JHH

FP01-010918 L962268-03 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:25 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 04:30	01/11/18 04:30	JHH

FP02-010918 L962268-04 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:30 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 04:47	01/11/18 04:47	JHH

SW09-010918 L962268-05 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:35 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 05:04	01/11/18 05:04	JHH

SW08-010918 L962268-06 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:50 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 05:20	01/11/18 05:20	JHH

SW13-010918 L962268-07 GW

Collected by: M. Warren | Collected date/time: 01/09/18 14:55 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 05:37	01/11/18 05:37	JHH

FP03-010918 L962268-08 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:10 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 05:53	01/11/18 05:53	JHH

SW04-010918 L962268-09 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:30 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 06:10	01/11/18 06:10	JHH

SW02-010918 L962268-10 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:35 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 06:27	01/11/18 06:27	JHH

SW01-010918 L962268-11 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:40 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 06:44	01/11/18 06:44	JHH

SW07-010918 L962268-12 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:45 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 07:00	01/11/18 07:00	JHH

SW12-010918 L962268-13 GW

Collected by: M. Warren | Collected date/time: 01/09/18 15:50 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 07:17	01/11/18 07:17	JHH

SW14-010918 L962268-14 GW

Collected by: M. Warren | Collected date/time: 01/09/18 16:15 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 07:34	01/11/18 07:34	JHH

TB01-010918 L962268-15 GW

Collected by: M. Warren | Collected date/time: 01/09/18 16:10 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 03:40	01/11/18 03:40	JHH

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times, unless qualified or notated within the report. Where applicable, all MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All radiochemical sample results for solids are reported on a dry weight basis with the exception of tritium, carbon-14 and radon, unless wet weight was requested by the client. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.

Chris McCord
Technical Service Representative

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 03:57	WG1061597
Toluene	ND		1.00	1	01/11/2018 03:57	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 03:57	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 03:57	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 03:57	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 03:57	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 03:57	WG1061597
(S) Toluene-d8	*109*		*80.0-120*		*01/11/2018 03:57*	WG1061597
(S) Dibromofluoromethane	*87.6*		*76.0-123*		*01/11/2018 03:57*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.5*		*80.0-120*		*01/11/2018 03:57*	WG1061597
(S) 4-Bromofluorobenzene	*103*		*80.0-120*		*01/11/2018 03:57*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 04:13	WG1061597
Toluene	ND		1.00	1	01/11/2018 04:13	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 04:13	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 04:13	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 04:13	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 04:13	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 04:13	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 04:13*	WG1061597
(S) Dibromofluoromethane	*89.4*		*76.0-123*		*01/11/2018 04:13*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.5*		*80.0-120*		*01/11/2018 04:13*	WG1061597
(S) 4-Bromofluorobenzene	*103*		*80.0-120*		*01/11/2018 04:13*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 04:30	WG1061597
Toluene	ND		1.00	1	01/11/2018 04:30	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 04:30	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 04:30	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 04:30	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 04:30	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 04:30	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 04:30*	WG1061597
(S) Dibromofluoromethane	*89.5*		*76.0-123*		*01/11/2018 04:30*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.6*		*80.0-120*		*01/11/2018 04:30*	WG1061597
(S) 4-Bromofluorobenzene	*105*		*80.0-120*		*01/11/2018 04:30*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 04:47	WG1061597
Toluene	ND		1.00	1	01/11/2018 04:47	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 04:47	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 04:47	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 04:47	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 04:47	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 04:47	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 04:47*	WG1061597
(S) Dibromofluoromethane	*88.5*		*76.0-123*		*01/11/2018 04:47*	WG1061597
(S) a,a,a-Trifluorotoluene	*97.7*		*80.0-120*		*01/11/2018 04:47*	WG1061597
(S) 4-Bromofluorobenzene	*105*		*80.0-120*		*01/11/2018 04:47*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 05:04	WG1061597
Toluene	ND		1.00	1	01/11/2018 05:04	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 05:04	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 05:04	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 05:04	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 05:04	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 05:04	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 05:04*	WG1061597
(S) Dibromofluoromethane	*90.6*		*76.0-123*		*01/11/2018 05:04*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.3*		*80.0-120*		*01/11/2018 05:04*	WG1061597
(S) 4-Bromofluorobenzene	*105*		*80.0-120*		*01/11/2018 05:04*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	1.16		1.00	1	01/11/2018 05:20	WG1061597
Toluene	ND		1.00	1	01/11/2018 05:20	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 05:20	WG1061597
o-Xylene	1.87		1.00	1	01/11/2018 05:20	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 05:20	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 05:20	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 05:20	WG1061597
(S) Toluene-d8	*109*		*80.0-120*		*01/11/2018 05:20*	WG1061597
(S) Dibromofluoromethane	*89.4*		*76.0-123*		*01/11/2018 05:20*	WG1061597
(S) a,a,a-Trifluorotoluene	*96.6*		*80.0-120*		*01/11/2018 05:20*	WG1061597
(S) 4-Bromofluorobenzene	*105*		*80.0-120*		*01/11/2018 05:20*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 05:37	WG1061597
Toluene	ND		1.00	1	01/11/2018 05:37	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 05:37	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 05:37	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 05:37	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 05:37	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 05:37	WG1061597
(S) Toluene-d8	*110*		*80.0-120*		*01/11/2018 05:37*	WG1061597
(S) Dibromofluoromethane	*90.5*		*76.0-123*		*01/11/2018 05:37*	WG1061597
(S) a,a,a-Trifluorotoluene	*97.8*		*80.0-120*		*01/11/2018 05:37*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 05:37*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 05:53	WG1061597
Toluene	ND		1.00	1	01/11/2018 05:53	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 05:53	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 05:53	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 05:53	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 05:53	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 05:53	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 05:53*	WG1061597
(S) Dibromofluoromethane	*89.9*		*76.0-123*		*01/11/2018 05:53*	WG1061597
(S) a,a,a-Trifluorotoluene	*99.1*		*80.0-120*		*01/11/2018 05:53*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 05:53*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 06:10	WG1061597
Toluene	4.09		1.00	1	01/11/2018 06:10	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 06:10	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 06:10	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 06:10	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 06:10	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 06:10	WG1061597
(S) Toluene-d8	*109*		*80.0-120*		*01/11/2018 06:10*	WG1061597
(S) Dibromofluoromethane	*89.5*		*76.0-123*		*01/11/2018 06:10*	WG1061597
(S) a,a,a-Trifluorotoluene	*97.4*		*80.0-120*		*01/11/2018 06:10*	WG1061597
(S) 4-Bromofluorobenzene	*105*		*80.0-120*		*01/11/2018 06:10*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	25.0		1.00	1	01/11/2018 06:27	WG1061597
Toluene	12.4		1.00	1	01/11/2018 06:27	WG1061597
Ethylbenzene	1.56		1.00	1	01/11/2018 06:27	WG1061597
o-Xylene	8.24		1.00	1	01/11/2018 06:27	WG1061597
m&p-Xylene	11.0		2.00	1	01/11/2018 06:27	WG1061597
Xylenes, Total	19.2		3.00	1	01/11/2018 06:27	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 06:27	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 06:27*	WG1061597
(S) Dibromofluoromethane	*89.3*		*76.0-123*		*01/11/2018 06:27*	WG1061597
(S) a,a,a-Trifluorotoluene	*97.6*		*80.0-120*		*01/11/2018 06:27*	WG1061597
(S) 4-Bromofluorobenzene	*107*		*80.0-120*		*01/11/2018 06:27*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 06:44	WG1061597
Toluene	ND		1.00	1	01/11/2018 06:44	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 06:44	WG1061597
o-Xylene	1.15		1.00	1	01/11/2018 06:44	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 06:44	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 06:44	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 06:44	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 06:44*	WG1061597
(S) Dibromofluoromethane	*90.7*		*76.0-123*		*01/11/2018 06:44*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.5*		*80.0-120*		*01/11/2018 06:44*	WG1061597
(S) 4-Bromofluorobenzene	*106*		*80.0-120*		*01/11/2018 06:44*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 07:00	WG1061597
Toluene	ND		1.00	1	01/11/2018 07:00	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 07:00	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 07:00	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 07:00	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 07:00	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 07:00	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 07:00*	WG1061597
(S) Dibromofluoromethane	*90.4*		*76.0-123*		*01/11/2018 07:00*	WG1061597
(S) a,a,a-Trifluorotoluene	*97.5*		*80.0-120*		*01/11/2018 07:00*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 07:00*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	12.3		1.00	1	01/11/2018 07:17	WG1061597
Toluene	5.65		1.00	1	01/11/2018 07:17	WG1061597
Ethylbenzene	2.16		1.00	1	01/11/2018 07:17	WG1061597
o-Xylene	11.1		1.00	1	01/11/2018 07:17	WG1061597
m&p-Xylene	14.6		2.00	1	01/11/2018 07:17	WG1061597
Xylenes, Total	25.7		3.00	1	01/11/2018 07:17	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 07:17	WG1061597
(S) Toluene-d8	*108*		*80.0-120*		*01/11/2018 07:17*	WG1061597
(S) Dibromofluoromethane	*89.1*		*76.0-123*		*01/11/2018 07:17*	WG1061597
(S) a,a,a-Trifluorotoluene	*99.4*		*80.0-120*		*01/11/2018 07:17*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 07:17*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 07:34	WG1061597
Toluene	ND		1.00	1	01/11/2018 07:34	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 07:34	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 07:34	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 07:34	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 07:34	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 07:34	WG1061597
(S) Toluene-d8	*106*		*80.0-120*		*01/11/2018 07:34*	WG1061597
(S) Dibromofluoromethane	*97.7*		*76.0-123*		*01/11/2018 07:34*	WG1061597
(S) a,a,a-Trifluorotoluene	*96.4*		*80.0-120*		*01/11/2018 07:34*	WG1061597
(S) 4-Bromofluorobenzene	*106*		*80.0-120*		*01/11/2018 07:34*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 03:40	WG1061597
Toluene	ND		1.00	1	01/11/2018 03:40	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 03:40	WG1061597
o-Xylene	ND		1.00	1	01/11/2018 03:40	WG1061597
m&p-Xylene	ND		2.00	1	01/11/2018 03:40	WG1061597
Xylenes, Total	ND		3.00	1	01/11/2018 03:40	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 03:40	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 03:40*	WG1061597
(S) Dibromofluoromethane	*88.6*		*76.0-123*		*01/11/2018 03:40*	WG1061597
(S) a,a,a-Trifluorotoluene	*98.6*		*80.0-120*		*01/11/2018 03:40*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 03:40*	WG1061597

Method Blank (MB)

(MB) R3278730-2 01/10/18 23:45

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Benzene	U		0.331	1.00
Ethylbenzene	U		0.384	1.00
Naphthalene	U		1.00	5.00
Toluene	U		0.412	1.00
Xylenes, Total	U		1.06	3.00
o-Xylene	U		0.341	1.00
m&p-Xylenes	U		0.719	2.00
(S) Toluene-d8	*106*			*80.0-120*
(S) Dibromofluoromethane	*91.5*			*76.0-123*
(S) a,a,a-Trifluorotoluene	*97.2*			*80.0-120*
(S) 4-Bromofluorobenzene	*103*			*80.0-120*

Laboratory Control Sample (LCS)

(LCS) R3278730-1 01/10/18 22:34

Analyte	Spike Amount ug/l	LCS Result ug/l	LCS Rec. %	Rec. Limits %	LCS Qualifier
Benzene	25.0	21.5	86.0	70.0-130	
Ethylbenzene	25.0	25.8	103	70.0-130	
Naphthalene	25.0	21.3	85.3	70.0-130	
Toluene	25.0	24.2	96.8	70.0-130	
Xylenes, Total	75.0	77.5	103	70.0-130	
o-Xylene	25.0	27.2	109	70.0-130	
m&p-Xylenes	50.0	50.3	101	70.0-130	
(S) Toluene-d8			*106*	*80.0-120*	
(S) Dibromofluoromethane			*89.2*	*76.0-123*	
(S) a,a,a-Trifluorotoluene			*101*	*80.0-120*	
(S) 4-Bromofluorobenzene			*103*	*80.0-120*	

Guide to Reading and Understanding Your Laboratory Report

The information below is designed to better explain the various terms used in your report of analytical results from the Laboratory. This is not intended as a comprehensive explanation, and if you have additional questions please contact your project representative.

Abbreviations and Definitions

MDL	Method Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
RDL	Reported Detection Limit.
Rec.	Recovery.
RPD	Relative Percent Difference.
SDG	Sample Delivery Group.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
U	Not detected at the Reporting Limit (or MDL where applicable).
Analyte	The name of the particular compound or analysis performed. Some Analyses and Methods will have multiple analytes reported.
Dilution	If the sample matrix contains an interfering material, or if concentrations of analytes in the sample are higher than the highest limit of concentration that the laboratory can accurately report, the sample may be diluted for analysis. If a value different than 1 is used in this field, the result reported has already been corrected for this factor.
Limits	These are the target % recovery ranges or % difference value that the laboratory has historically determined as normal for the method and analyte being reported. Successful QC Sample analysis will target all analytes recovered or duplicated within these ranges.
Qualifier	This column provides a letter and/or number designation that corresponds to additional information concerning the result reported. If a Qualifier is present, a definition per Qualifier is provided within the Glossary and Definitions page and potentially a discussion of possible implications of the Qualifier in the Case Narrative if applicable.
Result	The actual analytical final result (corrected for any sample specific characteristics) reported for your sample. If there was no measurable result returned for a specific analyte, the result in this column may state “ND” (Not Detected) or “BDL” (Below Detectable Levels). The information in the results column should always be accompanied by either an MDL (Method Detection Limit) or RDL (Reporting Detection Limit) that defines the lowest value that the laboratory could detect or report for this analyte.
Case Narrative (Cn)	A brief discussion about the included sample results, including a discussion of any non-conformances to protocol observed either at sample receipt by the laboratory from the field or during the analytical process. If present, there will be a section in the Case Narrative to discuss the meaning of any data qualifiers used in the report.
Quality Control Summary (Qc)	This section of the report includes the results of the laboratory quality control analyses required by procedure or analytical methods to assist in evaluating the validity of the results reported for your samples. These analyses are not being performed on your samples typically, but on laboratory generated material.
Sample Chain of Custody (Sc)	This is the document created in the field when your samples were initially collected. This is used to verify the time and date of collection, the person collecting the samples, and the analyses that the laboratory is requested to perform. This chain of custody also documents all persons (excluding commercial shippers) that have had control or possession of the samples from the time of collection until delivery to the laboratory for analysis.
Sample Results (Sr)	This section of your report will provide the results of all testing performed on your samples. These results are provided by sample ID and are separated by the analyses performed on each sample. The header line of each analysis section for each sample will provide the name and method number for the analysis reported.
Sample Summary (Ss)	This section of the Analytical Report defines the specific analyses performed for each sample ID, including the dates and times of preparation and/or analysis.

Qualifier	Description

The remainder of this page intentionally left blank, there are no qualifiers applied to this SDG.

ACCREDITATIONS & LOCATIONS

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be **YOUR LAB OF CHOICE.**
***** Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey–NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Connecticut	PH-0197	North Carolina [1]	DW21704
Florida	E87487	North Carolina [2]	41
Georgia	NELAP	North Dakota	R-140
Georgia [1]	923	Ohio–VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
Iowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky [1]	90010	South Dakota	n/a
Kentucky [2]	16	Tennessee [1 4]	2006
Louisiana	AI30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas [5]	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA – ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA – ISO 17025 [5]	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
EPA–Crypto	TN00003		

[1] Drinking Water [2] Underground Storage Tanks [3] Aquatic Toxicity [4] Chemical/Microbiological [5] Mold [n/a] Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. **ESC Lab Sciences performs all testing at our central laboratory.**



CH2M Hill- Kinder Morgan- Atlanta, GA

6600 Peachtree Dunwoody Road

Billing Information:
Accounts Payable
1000 Windward Concourse
Ste 450
Alpharetta, GA 30005

Report to: Bethany Garvey

Email To: bgarvey@ch2m.com; tom.wiley@ch2m.com; scott.powell@ch2m.com;

Project Description: Lewis Drive Surface Water

City/State Collected: BELTON, SC

Phone: 770-604-9182
Fax:

Client Project # 699858.LD.MR.SW

Lab Project # KINCH2MGA-LEWIS

Collected by (print): M. WARREN

Site/Facility ID # LEWIS DR.

P.O. #

Collected by (signature):

Immediately Packed on Ice N X Y ___

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day

Date Results Needed

Quote #

Pres Chk

Analysis / Container / Preservative

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	V8260BTEXNSC 40mlAmb-HCl	V8260BTEXNSC-TB 40mlAmb-HCl-Blk	BTEX	NAPTHALENE							Remarks	Sample # (lab only)
SW11-010918	GRAB	GW	NA	01/09/18	1410	3	X		X	X								-01
SW10-010918		GW			1420	3	X											-02
FD01-010918		GW			1425	3	X											-03
FD02-010918		GW			1430	3	X											-04
SW09-010918		GW			1435	3	X											-05
SW08-010918		GW			1450	3	X											-06
SW13-010918		GW			1455	3	X											-07
FD03-010918		GW			1510	3	X											-08
SW04-010918		GW			1530	3	X											-09
SW02-010918		GW			1535	3	X											-10

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other_____

Remarks:

pH _____ Temp _____

Flow _____ Other _____

Samples returned via: __ UPS X FedEx __ Courier

Tracking # 4142 5230 2310

Sample Receipt Checklist
COC Seal Present/Intact: NP Y N
COC Signed/Accurate: Y N
Bottles arrive intact: Y N
Correct bottles used: Y N
Sufficient volume sent: Y N
If Applicable
VOA Zero Headspace: Y N
Preservation Correct/Checked: Y N

Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Trip Blank Received: Yes / No, HCl / MeOH, TBR	If preservation required by Login: Date/Time
	01/09/18	1745		1	
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Temp: 4.1 °C Bottles Received: 56	
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1-10-18 Time: 845	Hold: Condition: NCF / OK

Chain of Custody Page 1 of 2

ESC LAB SCIENCES a subsidiary of

12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# 962268
H013

Acctnum: KINCH2MGA
Template: T131321
Prelogin: P634221
TSR: 526 - Chris McCord
PB: 1-3-18
Shipped Via: FedEX Ground

CH2M Hill- Kinder Morgan- Atlanta, GA

6600 Peachtree Dunwoody Road

Billing Information:
Accounts Payable
1000 Windward Concourse
Ste 450
Alpharetta, GA 30005

Report to: Bethany Garvey

Email To: bgarvey@ch2m.com; tom.wiley@ch2m.com; scott.powell@ch2m.com;

Project Description: Lewis Drive Surface Water

City/State Collected: BELTON SC

Phone: 770-604-9182
Fax:

Client Project # 699858, LD.MR.SW

Lab Project # KINCH2MGA-LEWIS

Collected by (print): M. WARREN

Site/Facility ID # LEWIS DR.

P.O. #

Collected by (signature):

Immediately Packed on Ice N Y

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day

Quote #

Date Results Needed

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	V8260BTEXNSC 40mlAmb-HCl	V8260BTEXNSC-TB 40mlAmb-HCl-Blk	BTEX	NAPTHALENE							Remarks	Sample # (lab only)
SW01-010918	GRAB	GW	NA	01/09/18	1540	3	X		Y	Y								-11
SW07-010918		GW			545	3	X		Y	Y								-12
SW12-010918		GW			1550	3	X		Y	Y								-13
SW14-010918		GW			1615	3	X		Y	Y								-14
—	—	GW	—	—	—	3	X											
—	—	GW	—	—	—	3	X											
—	—	GW	—	—	—	3	X											
TB01-010918	GRAB	GW	NA	01/09/18	1610	1		X	Y	Y								-15

Chain of Custody Page 2 of 2

ESC LABORATORY SCIENCES
a subsidiary of Pace Analytical

12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# 962268

Table #

Acctnum: KINCH2MGA
Template: T131321
Prelogin: P634221
TSR: 526 - Chris McCord
PB: 1-3-18G

Shipped Via: FedEX Ground

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other

Remarks:

pH ____ Temp ____
Flow ____ Other ____

Samples returned via:
__ UPS X FedEx __ Courier

Tracking # 4142 5230 2310

Sample Receipt Checklist
COC Seal Present/Intact: NP Y N
COC Signed/Accurate: Y N
Bottles arrive intact: Y N
Correct bottles used: Y N
Sufficient volume sent: Y N
If Applicable
VOA Zero Headspace: Y N
Preservation Correct/Checked: Y N

Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)
	01/09/18	1745	
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)

Trip Blank Received: Yes / No
HCl / MeOH
TBR

Temp: 1 °C Bottles Received: 58

Date: 1-10-18 Time: 845

If preservation required by Login: Date/Time

Hold:

Condition: NCF / OK

ANALYTICAL REPORT

January 16, 2018

CH2M Hill- Kinder Morgan- Atlanta, GA

Sample Delivery Group:	L962304
Samples Received:	01/10/2018
Project Number:	699858.LD.MR.GW
Description:	Lewis Drive Groundwater
Site:	LEWIS DRIVE
Report To:	Bethany Garvey 6600 Peachtree Dunwoody Road 400 Embassy Row - Suite 600 Atlanta, GA 30328

Entire Report Reviewed By:

Chris McCord
Technical Service Representative

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approval of the laboratory. Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures: 060302, 060303, and 060304.

MW-29-010918 L962304-01 GW

Collected by: M. Warren | Collected date/time: 01/09/18 09:00 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 07:50	01/11/18 07:50	JHH

MW-26-010918 L962304-02 GW

Collected by: M. Warren | Collected date/time: 01/09/18 09:15 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 08:07	01/11/18 08:07	JHH

MW-23-010918 L962304-03 GW

Collected by: M. Warren | Collected date/time: 01/09/18 09:25 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	10	01/11/18 08:24	01/11/18 08:24	JHH

MW-31-010918 L962304-04 GW

Collected by: M. Warren | Collected date/time: 01/09/18 09:45 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 08:40	01/11/18 08:40	JHH

MW-10-010918 L962304-05 GW

Collected by: M. Warren | Collected date/time: 01/09/18 10:00 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061597	1	01/11/18 08:57	01/11/18 08:57	JHH

MW-02-010918 L962304-06 GW

Collected by: M. Warren | Collected date/time: 01/09/18 10:10 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	10	01/11/18 12:34	01/11/18 12:34	LRL

MW-05-010918 L962304-07 GW

Collected by: M. Warren | Collected date/time: 01/09/18 10:20 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 12:56	01/11/18 12:56	LRL

MW-43-010918 L962304-08 GW

Collected by: M. Warren | Collected date/time: 01/09/18 11:05 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 13:17	01/11/18 13:17	LRL

MW-38-010918 L962304-09 GW

Collected by: M. Warren | Collected date/time: 01/09/18 11:25 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 13:38	01/11/18 13:38	LRL
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	5	01/12/18 01:42	01/12/18 01:42	JAH

MW-40-010918 L962304-10 GW

Collected by: M. Warren | Collected date/time: 01/09/18 12:00 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	200	01/12/18 02:03	01/12/18 02:03	JAH

MW-39-010918 L962304-11 GW

Collected by: M. Warren | Collected date/time: 01/09/18 11:50 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	5	01/12/18 02:23	01/12/18 02:23	JAH

MW-34-010918 L962304-12 GW

Collected by: M. Warren | Collected date/time: 01/09/18 11:40 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	10	01/11/18 14:42	01/11/18 14:42	LRL

MW-41-010918 L962304-13 GW

Collected by: M. Warren | Collected date/time: 01/09/18 13:20 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 15:04	01/11/18 15:04	LRL

MW-25-010918 L962304-14 GW

Collected by: M. Warren | Collected date/time: 01/09/18 13:25 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 15:25	01/11/18 15:25	LRL

MW-35-010918 L962304-15 GW

Collected by: M. Warren | Collected date/time: 01/09/18 13:35 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 15:46	01/11/18 15:46	LRL

MW-35-D-010918 L962304-16 GW

Collected by: M. Warren | Collected date/time: 01/09/18 13:40 | Received date/time: 01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 16:08	01/11/18 16:08	LRL

TB01-010918 L962304-17 GW

Collected by	Collected date/time	Received date/time
M. Warren	01/09/18 16:12	01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 11:52	01/11/18 11:52	LRL

FB01-010918 L962304-18 GW

Collected by	Collected date/time	Received date/time
M. Warren	01/09/18 16:15	01/10/18 08:45

Method	Batch	Dilution	Preparation date/time	Analysis date/time	Analyst
Volatile Organic Compounds (GC/MS) by Method 8260B	WG1061683	1	01/11/18 12:13	01/11/18 12:13	LRL

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times, unless qualified or notated within the report. Where applicable, all MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All radiochemical sample results for solids are reported on a dry weight basis with the exception of tritium, carbon-14 and radon, unless wet weight was requested by the client. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.

Chris McCord
Technical Service Representative

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 07:50	WG1061597
Toluene	ND		1.00	1	01/11/2018 07:50	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 07:50	WG1061597
Total Xylenes	ND		3.00	1	01/11/2018 07:50	WG1061597
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 07:50	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 07:50	WG1061597
1,2-Dichloroethane	ND		1.00	1	01/11/2018 07:50	WG1061597
(S) Toluene-d8	*108*		*80.0-120*		*01/11/2018 07:50*	WG1061597
(S) Dibromofluoromethane	*96.1*		*76.0-123*		*01/11/2018 07:50*	WG1061597
(S) 4-Bromofluorobenzene	*104*		*80.0-120*		*01/11/2018 07:50*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 08:07	WG1061597
Toluene	6.20		1.00	1	01/11/2018 08:07	WG1061597
Ethylbenzene	1.79		1.00	1	01/11/2018 08:07	WG1061597
Total Xylenes	13.8		3.00	1	01/11/2018 08:07	WG1061597
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 08:07	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 08:07	WG1061597
1,2-Dichloroethane	ND		1.00	1	01/11/2018 08:07	WG1061597
(S) Toluene-d8	*107*		*80.0-120*		*01/11/2018 08:07*	WG1061597
(S) Dibromofluoromethane	*88.1*		*76.0-123*		*01/11/2018 08:07*	WG1061597
(S) 4-Bromofluorobenzene	*107*		*80.0-120*		*01/11/2018 08:07*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	127		10.0	10	01/11/2018 08:24	WG1061597
Toluene	ND		10.0	10	01/11/2018 08:24	WG1061597
Ethylbenzene	ND		10.0	10	01/11/2018 08:24	WG1061597
Total Xylenes	137		30.0	10	01/11/2018 08:24	WG1061597
Methyl tert-butyl ether	69.6		10.0	10	01/11/2018 08:24	WG1061597
Naphthalene	ND		50.0	10	01/11/2018 08:24	WG1061597
1,2-Dichloroethane	ND		10.0	10	01/11/2018 08:24	WG1061597
(S) Toluene-d8	*108*		*80.0-120*		*01/11/2018 08:24*	WG1061597
(S) Dibromofluoromethane	*89.1*		*76.0-123*		*01/11/2018 08:24*	WG1061597
(S) 4-Bromofluorobenzene	*107*		*80.0-120*		*01/11/2018 08:24*	WG1061597

Sample Narrative:

L962304-03 WG1061597: Non-target compounds too high to run at a lower dilution.

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 08:40	WG1061597
Toluene	ND		1.00	1	01/11/2018 08:40	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 08:40	WG1061597
Total Xylenes	ND		3.00	1	01/11/2018 08:40	WG1061597
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 08:40	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 08:40	WG1061597
1,2-Dichloroethane	ND		1.00	1	01/11/2018 08:40	WG1061597
(S) Toluene-d8	*105*		*80.0-120*		*01/11/2018 08:40*	WG1061597
(S) Dibromofluoromethane	*90.7*		*76.0-123*		*01/11/2018 08:40*	WG1061597
(S) 4-Bromofluorobenzene	*107*		*80.0-120*		*01/11/2018 08:40*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 08:57	WG1061597
Toluene	ND		1.00	1	01/11/2018 08:57	WG1061597
Ethylbenzene	ND		1.00	1	01/11/2018 08:57	WG1061597
Total Xylenes	ND		3.00	1	01/11/2018 08:57	WG1061597
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 08:57	WG1061597
Naphthalene	ND		5.00	1	01/11/2018 08:57	WG1061597
1,2-Dichloroethane	ND		1.00	1	01/11/2018 08:57	WG1061597
(S) Toluene-d8	*108*		*80.0-120*		*01/11/2018 08:57*	WG1061597
(S) Dibromofluoromethane	*89.4*		*76.0-123*		*01/11/2018 08:57*	WG1061597
(S) 4-Bromofluorobenzene	*106*		*80.0-120*		*01/11/2018 08:57*	WG1061597

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	307		10.0	10	01/11/2018 12:34	WG1061683
Toluene	878		10.0	10	01/11/2018 12:34	WG1061683
Ethylbenzene	ND		10.0	10	01/11/2018 12:34	WG1061683
Total Xylenes	1300		30.0	10	01/11/2018 12:34	WG1061683
Methyl tert-butyl ether	61.8		10.0	10	01/11/2018 12:34	WG1061683
Naphthalene	63.7		50.0	10	01/11/2018 12:34	WG1061683
1,2-Dichloroethane	ND		10.0	10	01/11/2018 12:34	WG1061683
(S) Toluene-d8	*102*		*80.0-120*		*01/11/2018 12:34*	WG1061683
(S) Dibromofluoromethane	*88.0*		*76.0-123*		*01/11/2018 12:34*	WG1061683
(S) 4-Bromofluorobenzene	*108*		*80.0-120*		*01/11/2018 12:34*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 12:56	WG1061683
Toluene	ND		1.00	1	01/11/2018 12:56	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 12:56	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 12:56	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 12:56	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 12:56	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 12:56	WG1061683
(S) Toluene-d8	*105*		*80.0-120*		*01/11/2018 12:56*	WG1061683
(S) Dibromofluoromethane	*87.8*		*76.0-123*		*01/11/2018 12:56*	WG1061683
(S) 4-Bromofluorobenzene	*109*		*80.0-120*		*01/11/2018 12:56*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 13:17	WG1061683
Toluene	ND		1.00	1	01/11/2018 13:17	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 13:17	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 13:17	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 13:17	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 13:17	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 13:17	WG1061683
(S) Toluene-d8	*102*		*80.0-120*		*01/11/2018 13:17*	WG1061683
(S) Dibromofluoromethane	*88.5*		*76.0-123*		*01/11/2018 13:17*	WG1061683
(S) 4-Bromofluorobenzene	*109*		*80.0-120*		*01/11/2018 13:17*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	311		5.00	5	01/12/2018 01:42	WG1061683
Toluene	2.31		1.00	1	01/11/2018 13:38	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 13:38	WG1061683
Total Xylenes	158		3.00	1	01/11/2018 13:38	WG1061683
Methyl tert-butyl ether	49.4		1.00	1	01/11/2018 13:38	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 13:38	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 13:38	WG1061683
(S) Toluene-d8	*104*		*80.0-120*		*01/11/2018 13:38*	WG1061683
(S) Toluene-d8	*104*		*80.0-120*		*01/12/2018 01:42*	WG1061683
(S) Dibromofluoromethane	*101*		*76.0-123*		*01/12/2018 01:42*	WG1061683
(S) Dibromofluoromethane	*81.6*		*76.0-123*		*01/11/2018 13:38*	WG1061683
(S) 4-Bromofluorobenzene	*92.7*		*80.0-120*		*01/12/2018 01:42*	WG1061683
(S) 4-Bromofluorobenzene	*107*		*80.0-120*		*01/11/2018 13:38*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	12400		200	200	01/12/2018 02:03	WG1061683
Toluene	22300		200	200	01/12/2018 02:03	WG1061683
Ethylbenzene	773		200	200	01/12/2018 02:03	WG1061683
Total Xylenes	10200		600	200	01/12/2018 02:03	WG1061683
Methyl tert-butyl ether	497		200	200	01/12/2018 02:03	WG1061683
Naphthalene	ND		1000	200	01/12/2018 02:03	WG1061683
1,2-Dichloroethane	ND		200	200	01/12/2018 02:03	WG1061683
(S) Toluene-d8	*106*		*80.0-120*		*01/12/2018 02:03*	WG1061683
(S) Dibromofluoromethane	*97.8*		*76.0-123*		*01/12/2018 02:03*	WG1061683
(S) 4-Bromofluorobenzene	*95.1*		*80.0-120*		*01/12/2018 02:03*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	23.8		5.00	5	01/12/2018 02:23	WG1061683
Toluene	ND		5.00	5	01/12/2018 02:23	WG1061683
Ethylbenzene	ND		5.00	5	01/12/2018 02:23	WG1061683
Total Xylenes	ND		15.0	5	01/12/2018 02:23	WG1061683
Methyl tert-butyl ether	370		5.00	5	01/12/2018 02:23	WG1061683
Naphthalene	ND		25.0	5	01/12/2018 02:23	WG1061683
1,2-Dichloroethane	ND		5.00	5	01/12/2018 02:23	WG1061683
(S) Toluene-d8	*103*		*80.0-120*		*01/12/2018 02:23*	WG1061683
(S) Dibromofluoromethane	*101*		*76.0-123*		*01/12/2018 02:23*	WG1061683
(S) 4-Bromofluorobenzene	*95.1*		*80.0-120*		*01/12/2018 02:23*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	147		10.0	10	01/11/2018 14:42	WG1061683
Toluene	13.1		10.0	10	01/11/2018 14:42	WG1061683
Ethylbenzene	ND		10.0	10	01/11/2018 14:42	WG1061683
Total Xylenes	79.8		30.0	10	01/11/2018 14:42	WG1061683
Methyl tert-butyl ether	246		10.0	10	01/11/2018 14:42	WG1061683
Naphthalene	ND		50.0	10	01/11/2018 14:42	WG1061683
1,2-Dichloroethane	ND		10.0	10	01/11/2018 14:42	WG1061683
(S) Toluene-d8	*102*		*80.0-120*		*01/11/2018 14:42*	WG1061683
(S) Dibromofluoromethane	*90.7*		*76.0-123*		*01/11/2018 14:42*	WG1061683
(S) 4-Bromofluorobenzene	*110*		*80.0-120*		*01/11/2018 14:42*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	2.06		1.00	1	01/11/2018 15:04	WG1061683
Toluene	ND		1.00	1	01/11/2018 15:04	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 15:04	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 15:04	WG1061683
Methyl tert-butyl ether	1.43		1.00	1	01/11/2018 15:04	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 15:04	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 15:04	WG1061683
(S) Toluene-d8	*104*		*80.0-120*		*01/11/2018 15:04*	WG1061683
(S) Dibromofluoromethane	*90.0*		*76.0-123*		*01/11/2018 15:04*	WG1061683
(S) 4-Bromofluorobenzene	*110*		*80.0-120*		*01/11/2018 15:04*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	72.0		1.00	1	01/11/2018 15:25	WG1061683
Toluene	ND		1.00	1	01/11/2018 15:25	WG1061683
Ethylbenzene	2.74		1.00	1	01/11/2018 15:25	WG1061683
Total Xylenes	111		3.00	1	01/11/2018 15:25	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 15:25	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 15:25	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 15:25	WG1061683
(S) Toluene-d8	*104*		*80.0-120*		*01/11/2018 15:25*	WG1061683
(S) Dibromofluoromethane	*87.9*		*76.0-123*		*01/11/2018 15:25*	WG1061683
(S) 4-Bromofluorobenzene	*108*		*80.0-120*		*01/11/2018 15:25*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 15:46	WG1061683
Toluene	ND		1.00	1	01/11/2018 15:46	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 15:46	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 15:46	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 15:46	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 15:46	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 15:46	WG1061683
(S) Toluene-d8	*103*		*80.0-120*		*01/11/2018 15:46*	WG1061683
(S) Dibromofluoromethane	*90.9*		*76.0-123*		*01/11/2018 15:46*	WG1061683
(S) 4-Bromofluorobenzene	*110*		*80.0-120*		*01/11/2018 15:46*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 16:08	WG1061683
Toluene	ND		1.00	1	01/11/2018 16:08	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 16:08	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 16:08	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 16:08	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 16:08	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 16:08	WG1061683
(S) Toluene-d8	*103*		*80.0-120*		*01/11/2018 16:08*	WG1061683
(S) Dibromofluoromethane	*88.8*		*76.0-123*		*01/11/2018 16:08*	WG1061683
(S) 4-Bromofluorobenzene	*110*		*80.0-120*		*01/11/2018 16:08*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 11:52	WG1061683
Toluene	ND		1.00	1	01/11/2018 11:52	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 11:52	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 11:52	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 11:52	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 11:52	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 11:52	WG1061683
(S) Toluene-d8	*105*		*80.0-120*		*01/11/2018 11:52*	WG1061683
(S) Dibromofluoromethane	*89.0*		*76.0-123*		*01/11/2018 11:52*	WG1061683
(S) 4-Bromofluorobenzene	*110*		*80.0-120*		*01/11/2018 11:52*	WG1061683

Volatile Organic Compounds (GC/MS) by Method 8260B

Analyte	Result	Qualifier	RDL	Dilution	Analysis	Batch
	ug/l		ug/l		date / time	
Benzene	ND		1.00	1	01/11/2018 12:13	WG1061683
Toluene	ND		1.00	1	01/11/2018 12:13	WG1061683
Ethylbenzene	ND		1.00	1	01/11/2018 12:13	WG1061683
Total Xylenes	ND		3.00	1	01/11/2018 12:13	WG1061683
Methyl tert-butyl ether	ND		1.00	1	01/11/2018 12:13	WG1061683
Naphthalene	ND		5.00	1	01/11/2018 12:13	WG1061683
1,2-Dichloroethane	ND		1.00	1	01/11/2018 12:13	WG1061683
(S) Toluene-d8	*105*		*80.0-120*		*01/11/2018 12:13*	WG1061683
(S) Dibromofluoromethane	*89.0*		*76.0-123*		*01/11/2018 12:13*	WG1061683
(S) 4-Bromofluorobenzene	*108*		*80.0-120*		*01/11/2018 12:13*	WG1061683

Method Blank (MB)

(MB) R3278730-2 01/10/18 23:45

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Benzene	U		0.331	1.00
1,2-Dichloroethane	U		0.361	1.00
Ethylbenzene	U		0.384	1.00
Methyl tert-butyl ether	U		0.367	1.00
Naphthalene	U		1.00	5.00
Toluene	U		0.412	1.00
Xylenes, Total	U		1.06	3.00
(S) Toluene-d8	*106*			*80.0-120*
(S) Dibromofluoromethane	*91.5*			*76.0-123*
(S) 4-Bromofluorobenzene	*103*			*80.0-120*

Laboratory Control Sample (LCS)

(LCS) R3278730-1 01/10/18 22:34

Analyte	Spike Amount ug/l	LCS Result ug/l	LCS Rec. %	Rec. Limits %	LCS Qualifier
Benzene	25.0	21.5	86.0	70.0-130	
1,2-Dichloroethane	25.0	23.3	93.1	70.0-130	
Ethylbenzene	25.0	25.8	103	70.0-130	
Methyl tert-butyl ether	25.0	23.0	91.9	70.0-130	
Naphthalene	25.0	21.3	85.3	70.0-130	
Toluene	25.0	24.2	96.8	70.0-130	
Xylenes, Total	75.0	77.5	103	70.0-130	
(S) Toluene-d8			*106*	*80.0-120*	
(S) Dibromofluoromethane			*89.2*	*76.0-123*	
(S) 4-Bromofluorobenzene			*103*	*80.0-120*	

Method Blank (MB)

(MB) R3278852-2 01/11/18 11:15

Analyte	MB Result ug/l	MB Qualifier	MB MDL ug/l	MB RDL ug/l
Benzene	U		0.331	1.00
1,2-Dichloroethane	U		0.361	1.00
Ethylbenzene	U		0.384	1.00
Methyl tert-butyl ether	U		0.367	1.00
Naphthalene	U		1.00	5.00
Toluene	U		0.412	1.00
Xylenes, Total	U		1.06	3.00
(S) Toluene-d8	*105*			*80.0-120*
(S) Dibromofluoromethane	*87.4*			*76.0-123*
(S) 4-Bromofluorobenzene	*109*			*80.0-120*

Laboratory Control Sample (LCS)

(LCS) R3278852-1 01/11/18 10:12

Analyte	Spike Amount ug/l	LCS Result ug/l	LCS Rec. %	Rec. Limits %	LCS Qualifier
Benzene	25.0	23.3	93.4	70.0-130	
1,2-Dichloroethane	25.0	26.4	105	70.0-130	
Ethylbenzene	25.0	26.3	105	70.0-130	
Methyl tert-butyl ether	25.0	25.0	100	70.0-130	
Naphthalene	25.0	25.1	101	70.0-130	
Toluene	25.0	26.2	105	70.0-130	
Xylenes, Total	75.0	78.6	105	70.0-130	
(S) Toluene-d8			*99.1*	*80.0-120*	
(S) Dibromofluoromethane			*85.7*	*76.0-123*	
(S) 4-Bromofluorobenzene			*103*	*80.0-120*	

Guide to Reading and Understanding Your Laboratory Report

The information below is designed to better explain the various terms used in your report of analytical results from the Laboratory. This is not intended as a comprehensive explanation, and if you have additional questions please contact your project representative.

Abbreviations and Definitions

MDL	Method Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
RDL	Reported Detection Limit.
Rec.	Recovery.
RPD	Relative Percent Difference.
SDG	Sample Delivery Group.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
U	Not detected at the Reporting Limit (or MDL where applicable).
Analyte	The name of the particular compound or analysis performed. Some Analyses and Methods will have multiple analytes reported.
Dilution	If the sample matrix contains an interfering material, or if concentrations of analytes in the sample are higher than the highest limit of concentration that the laboratory can accurately report, the sample may be diluted for analysis. If a value different than 1 is used in this field, the result reported has already been corrected for this factor.
Limits	These are the target % recovery ranges or % difference value that the laboratory has historically determined as normal for the method and analyte being reported. Successful QC Sample analysis will target all analytes recovered or duplicated within these ranges.
Qualifier	This column provides a letter and/or number designation that corresponds to additional information concerning the result reported. If a Qualifier is present, a definition per Qualifier is provided within the Glossary and Definitions page and potentially a discussion of possible implications of the Qualifier in the Case Narrative if applicable.
Result	The actual analytical final result (corrected for any sample specific characteristics) reported for your sample. If there was no measurable result returned for a specific analyte, the result in this column may state “ND” (Not Detected) or “BDL” (Below Detectable Levels). The information in the results column should always be accompanied by either an MDL (Method Detection Limit) or RDL (Reporting Detection Limit) that defines the lowest value that the laboratory could detect or report for this analyte.
Case Narrative (Cn)	A brief discussion about the included sample results, including a discussion of any non-conformances to protocol observed either at sample receipt by the laboratory from the field or during the analytical process. If present, there will be a section in the Case Narrative to discuss the meaning of any data qualifiers used in the report.
Quality Control Summary (Qc)	This section of the report includes the results of the laboratory quality control analyses required by procedure or analytical methods to assist in evaluating the validity of the results reported for your samples. These analyses are not being performed on your samples typically, but on laboratory generated material.
Sample Chain of Custody (Sc)	This is the document created in the field when your samples were initially collected. This is used to verify the time and date of collection, the person collecting the samples, and the analyses that the laboratory is requested to perform. This chain of custody also documents all persons (excluding commercial shippers) that have had control or possession of the samples from the time of collection until delivery to the laboratory for analysis.
Sample Results (Sr)	This section of your report will provide the results of all testing performed on your samples. These results are provided by sample ID and are separated by the analyses performed on each sample. The header line of each analysis section for each sample will provide the name and method number for the analysis reported.
Sample Summary (Ss)	This section of the Analytical Report defines the specific analyses performed for each sample ID, including the dates and times of preparation and/or analysis.

Qualifier	Description

The remainder of this page intentionally left blank, there are no qualifiers applied to this SDG.

ACCREDITATIONS & LOCATIONS

ESC Lab Sciences is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our "one location" design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be **YOUR LAB OF CHOICE.**
***** Not all certifications held by the laboratory are applicable to the results reported in the attached report.

State Accreditations

Alabama	40660	Nevada	TN-03-2002-34
Alaska	UST-080	New Hampshire	2975
Arizona	AZ0612	New Jersey–NELAP	TN002
Arkansas	88-0469	New Mexico	TN00003
California	01157CA	New York	11742
Colorado	TN00003	North Carolina	Env375
Connecticut	PH-0197	North Carolina [1]	DW21704
Florida	E87487	North Carolina [2]	41
Georgia	NELAP	North Dakota	R-140
Georgia [1]	923	Ohio–VAP	CL0069
Idaho	TN00003	Oklahoma	9915
Illinois	200008	Oregon	TN200002
Indiana	C-TN-01	Pennsylvania	68-02979
Iowa	364	Rhode Island	221
Kansas	E-10277	South Carolina	84004
Kentucky [1]	90010	South Dakota	n/a
Kentucky [2]	16	Tennessee [1 4]	2006
Louisiana	AI30792	Texas	T 104704245-07-TX
Maine	TN0002	Texas [5]	LAB0152
Maryland	324	Utah	6157585858
Massachusetts	M-TN003	Vermont	VT2006
Michigan	9958	Virginia	109
Minnesota	047-999-395	Washington	C1915
Mississippi	TN00003	West Virginia	233
Missouri	340	Wisconsin	9980939910
Montana	CERT0086	Wyoming	A2LA
Nebraska	NE-OS-15-05		

Third Party & Federal Accreditations

A2LA – ISO 17025	1461.01	AIHA-LAP,LLC	100789
A2LA – ISO 17025 [5]	1461.02	DOD	1461.01
Canada	1461.01	USDA	S-67674
EPA–Crypto	TN00003		

[1] Drinking Water [2] Underground Storage Tanks [3] Aquatic Toxicity [4] Chemical/Microbiological [5] Mold [n/a] Accreditation not applicable

Our Locations

ESC Lab Sciences has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. **ESC Lab Sciences performs all testing at our central laboratory.**



CH2M Hill- Kinder Morgan- Atlanta, GA

6600 Peachtree Dunwoody Road

Billing Information:
Accounts Payable
1000 Windward Concourse
Ste 450
Alpharetta, GA 30005

Report to: Bethany Garvey

Email To: bgarvey@ch2m.com; tom.wiley@ch2m.com; scott.powell@ch2m.com;

Project Description: Lewis Drive Groundwater

City/State Collected: BELTON, SC

Phone: 770-604-9182
Fax:

Client Project # 699858.LD.MR.GW

Lab Project # KINCH2MGA-LEWIS12

Collected by (print): M. WARREN

Site/Facility ID # LEWIS DRIVE

P.O. #

Collected by (signature):

Immediately Packed on Ice N X Y ___

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day

Quote #

Date Results Needed

Pres Chk

Analysis / Container / Preservative

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	V8260BTEXMNSC 40mlAmb-HCl	V8260BTEXMNSC-TB 40mlAmb-HCl-Blk	BTEX	MTBE	NAPHTHALENE	1,2-DCA only					Remarks	Sample # (lab only)
MW-29-010918	GRAB	GW	NA	01/09/18	0900	3	X		X	X	X	X						-01
MW-26-010918		GW			0915	3	X		X	X	X	X						02
MW-23-010918		GW			0925	3	X		X	X	X	X						03
MW-31-010918		GW			0945	3	X		X	X	X	X						04
MW-10-010918		GW			1000	3	X		X	X	X	X						05
MW-02-010918		GW			1010	3	X		X	X	X	X						06
MW-05-010918		GW			1020	3	X		X	X	X	X						07
MW-43-010918		GW			1105	3	X		X	X	X	X						08
MW-38-010918		GW			1125	3	X		X	X	X	X						09
MW-40-010918		GW			1200	3	X		X	X	X	X						10

Chain of Custody Page 1 of 2

ESC LABORATORIES
a subsidiary of Accutest

12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# L962304

E033

Acctnum: KINCH2MGA
Template: T131319
Prelogin: P634219
TSR: 526 - Chris McCord
PB: 1-3-18 GM
Shipped Via: FedEX Ground

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other_____

Remarks:

pH _____ Temp _____
Flow _____ Other _____

Samples returned via: _ UPS _ FedEx __ Courier __ _____

Tracking # 4142 5230 2284

Sample Receipt Checklist
COC Seal Present/Intact: NP Y N
COC Signed/Accurate: Y N
Bottles arrive intact: Y N
Correct bottles used: Y N
Sufficient volume sent: Y N
If Applicable
VOA Zero Headspace: N
Preservation Correct/Checked: Y N

Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Trip Blank Received: Yes / No HCL / MeoH TBR
	01/09/18	1745		
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Temp: 2.7 °C Bottles Received: 52
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1/10/18 Time: 8:45

If preservation required by Login: Date/Time

Hold:

Condition: NCF / (OK)

Chain of Custody Page 2 of 2

CH2M Hill- Kinder Morgan- Atlanta, GA

6600 Peachtree Dunwoody Road

Billing Information:
Accounts Payable
1000 Windward Concourse
Ste 450
Alpharetta, GA 30005

Report to: Bethany Garvey

Email To: bgarvey@ch2m.com; tom.wiley@ch2m.com; scott.powell@ch2m.com;

Project Description: Lewis Drive Groundwater

City/State Collected: BELTON, SC

Phone: 770-604-9182
Fax:

Client Project # 699858.LD.MR.GW

Lab Project # KINCH2MGA-LEWIS12

Collected by (print): M. WARLEY

Site/Facility ID # LEWIS DRIVE

P.O. #

Collected by (signature):

Rush? (Lab MUST Be Notified)
___ Same Day ___ Five Day
___ Next Day ___ 5 Day (Rad Only)
___ Two Day ___ 10 Day (Rad Only)
___ Three Day

Quote #

Date Results Needed

Immediately Packed on Ice N X Y ___

Analysis / Container / Preservative

Sample ID	Comp/Grab	Matrix *	Depth	Date	Time	No. of Cntrs	V8260BTEXMNSC 40mlAmb-HCl	V8260BTEXMNSC-TB 40mlAmb-HCl-Blk	BTEX	MTBE	NAPHTHALENE	1,2-DCA ONLY	Remarks	Sample # (lab only)
MW-39-010918	GRAB	GW	NA	01/09/18	1150	3	X		X	X	X	X		-11
MW-34-010918		GW			1140	3	X		X	X	X	X		12
MW-41-010918		GW			1320	3	X		X	X	X	X		13
MW-25-010918		GW			1325	3	X		X	X	X	X		14
MW-35-010918		GW			1335	3	X		X	X	X	X		15
MW-35-D-010918		GW			1340	3	X		X	X	X	X		16
TB01-010918		GW			1612	3	X	X						17
FB01-010918		GW			1615	3	X	X	X	X	X	X		18
		GW				3	X							
		GW				3	X							

ESC LABORATORIES
a subsidiary of Pace Analytical
12065 Lebanon Rd
Mount Juliet, TN 37122
Phone: 615-758-5858
Phone: 800-767-5859
Fax: 615-758-5859

L# L962304

Table #

Acctnum: KINCH2MGA
Template: T131319
Prelogin: P634219
TSR: 526 - Chris McCord
PB: 1-3-18 GN

Shipped Via: FedEX Ground

* Matrix:
SS - Soil AIR - Air F - Filter
GW - Groundwater B - Bioassay
WW - WasteWater
DW - Drinking Water
OT - Other_____

Remarks:

pH _____ Temp _____

Flow _____ Other _____

Samples returned via:
__ UPS __ FedEx __ Courier __ _____

Tracking #

Sample Receipt Checklist
COC Seal Present/Intact: __NP X Y __N
COC Signed/Accurate: X Y __N
Bottles arrive intact: X Y __N
Correct bottles used: X Y __N
Sufficient volume sent: X Y __N
If Applicable
VOA Zero Headspace: __Y __N
Preservation Correct/Checked: __Y __N

Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Trip Blank Received: Yes / No HCL / MeoH TBR
	01/09/18	1745		
Relinquished by : (Signature)	Date:	Time:	Received by: (Signature)	Temp: 2.9 °C Bottles Received:
Relinquished by : (Signature)	Date:	Time:	Received for lab by: (Signature)	Date: 1/10/18 Time: 8:45

If preservation required by Login: Date/Time

Hold:

Condition: NCF / OK